

Introduction to AC Machines:

Classification of AC Rotating Machines

•Synchronous Machines:

•**Synchronous Generators:** A primary source of electrical energy.

•**Synchronous Motors:** Used as motors as well as power factor compensators (synchronous condensers).

•Asynchronous (Induction) Machines:

•**Induction Motors:** Most widely used electrical motors in both domestic and industrial applications.

•**Induction Generators:** Due to lack of a separate field excitation, these machines are rarely used as generators.

Energy Conversion

- Generators convert mechanical energy to electric energy.
- Motors convert electric energy to mechanical energy.
- The construction of motors and generators are similar.
- Every generator can operate as a motor and vice versa.
 - The energy or power balance is :
 - Generator: Mechanical power = electric power + losses
 - Motor: Electric Power = Mechanical Power + losses.

Physical Arrangement Of Windings In Stator Are-

- Pre-manufactured coils can be inserted into the stator slots one by one to form a three-phase distributed winding
- All the windings are in a single-speed three-phase motor design.

Physical Arrangement Of Windings In Cylindrical Rotor Are-

- The windings for rotor are less complex than stator.
- The windings of a rotor are less insulated.
- The size of the cylindrical rotor winding is small as it does not need to transmit huge current through it.

Slots For Windings:

The number of slots depends on how many phases of power are provided to the coil windings. A basic single-phase motor usually has **four slots** that contain two pairs of coil windings, each offset by 90 degrees; a basic three-phase motor has six slots with three pairs of coil windings, each pair offset by 120 degrees.


Winding Diagrams: (i) DC Winding diagrams (ii) AC Winding Diagrams

Terminologies Used In Winding Diagrams:

Conductor: An individual piece of wire placed in the slots in the machine in the magnetic field.

Turn: Two conductors connected in series and separated from each other by a pole pitch so that the emf induced will be additive.

Coil: When one or more turns are connected in series and placed in almost similar magnetic positions. Coils may be single turn or multi turn coils.



(a) Single turn Coil (b) 3 – turn coil (c) Multi turn coil
 Fig. 1 Different types of winding coils representations

Coil group: One or more coil single coils formed in a group forms the coil group.

Winding: Number of coils arranged in coil group is said to be a winding.

Pole Pitch: Distance between the poles in terms of slots is called pole pitch.





Fig. 2 Single and Multi turn coils

Full Pitch winding: If the coil pitch for a winding is equal to pole pitch the winding is called full pitch winding as shown in Fig .

Chorded winding: When the pitch of the winding is less than the full pitch or pole pitch then the winding is called short pitch winding or chorded winding.



(a) (b)
Fig. 3 Full pitched and short pitched coils

Single layer winding: Only one coil side placed in one slot.

Double layer winding: Two coil sides are placed in a single slot. Single and double layer windings are shown in Fig 4





Fig.4 Single and double layer windings



Classification of windings: Closed type and open type winding

Closed type windings: In this type of winding there is a closed path around the armature or stator. Starting from any point, the winding path can be followed through all the turns and starting point can be reached. Such windings are used in DC machines.

Open windings: There is no closed path in the windings. Such windings are used in AC machines.




Fig. 5 Photographs of the windings and coils

AC winding design:

The windings used in rotating electrical machines can be classified as

Concentrated Windings

- All the winding turns are wound together in series to form one multi-turn coil
- All the turns have the same magnetic axis
- Examples of concentrated winding are
 - field windings for salient-pole synchronous machines
 - D.C. machines
 - Primary and secondary windings of a transformer

Distributed Windings

- All the winding turns are arranged in several full-pitch or fractional-pitch coils
- These coils are then housed in the slots spread around the air-gap periphery to form phase or commutator winding
- Examples of distributed winding are
 - Stator and rotor of induction machines
 - The armatures of both synchronous and D.C. machines

Armature windings, in general, are classified under two main heads, namely,

Closed Windings

- There is a closed path in the sense that if one starts from any point on the winding and traverses it, one again reaches the starting point from where one had started
- Used only for D.C. machines and A.C. commutator machines

Open Windings

- Open windings terminate at suitable number of slip-rings or terminals
- Used only for A.C. machines, like synchronous machines, induction machines, etc

EMF Equation of a Synchronous Generator

The generator which runs at a synchronous speed is known as the synchronous generator. The synchronous generator converts the mechanical power into electrical energy for the grid. The Derivation of EMF Equation of a synchronous generator is given below.

Let,

P be the number of poles

ϕ is Flux per pole in Webers

N is the speed in revolution per minute (r.p.m)

f be the frequency in Hertz

Z_{ph} is the number of conductors connected in series per phase

T_{ph} is the number of turns connected in series per phase

K_c is the coil span factor

K_d is the distribution factor

Flux cut by each conductor during one revolution is given as $P\phi$ Weber.

Time taken to complete one revolution is given by $60/N$ sec

Average EMF induced per conductor will be given by the equation shown below

$$\frac{P\phi}{60/N} = \frac{P\phi N}{60} \text{ volts}$$

Average EMF induced per phase will be given by the equation shown below

$$\frac{P\phi N}{60} \times Z_{ph} = \frac{P\phi N}{60} \times 2T_{ph} \text{ and}$$

$$T_{ph} = \frac{Z_{ph}}{2}$$

$$\text{Average EMF} = 4 \times \phi \times T_{ph} \times \frac{PN}{120} = 4\phi f T_{ph}$$

The average EMF equation is derived with the following assumptions given below.

Coils have got the full pitch.

All the conductors are concentrated in one stator slot.

Root mean square (R.M.S) value of the EMF induced per phase is given by the equation shown below.

$$E_{ph} = \text{Average value} \times \text{form factor}$$

Therefore,

$$E_{ph} = 4\phi f T_{ph} \times 1.11 = 4.44 \phi f T_{ph} \text{ volts}$$

If the coil span factor K_c and the distribution factor K_d , are taken into consideration than the Actual EMF induced per phase is given as

$$E_{ph} = 4.44 K_c K_d \phi f T_{ph} \text{ volts (1)}$$

Equation (1) shown above is the EMF equation of the Synchronous Generator.

Winding Factors (Coil Pitch and Distributed Windings)

Pitch Factor:

A coil whose sides are separated by one pole pitch (i.e., coil span is 180° electrical) is called a full-pitch coil. With a full-pitch coil, the e.m.f.s induced in the two coil sides are in phase with each other and the resultant e.m.f. is the arithmetic sum of individual e.m.f.s. However the waveform of the resultant e.m.f. can be improved by making the coil pitch less than a pole pitch. Such a coil is called short-pitch coil. This practice is only possible with double-layer type of winding. The e.m.f. induced in a short-pitch coil is less than that of a full-pitch coil. The factor by which e.m.f. per coil is reduced is called pitch factor K_p . It is defined as:

$$K_p = \frac{\text{e.m.f. induced in short - pitch coil}}{\text{e.m.f. induced in full - pitch coil}}$$

Consider a coil AB which is short-pitch by an angle θ electrical degrees as shown in Fig. (11). The e.m.f.s generated in the coil sides A and B differ in phase by an angle θ and can




Fig. 11





Fig. 12

Since $E_A = E_B$, $E_R = 2E_A \cos \theta/2$

Pitch factor, $K_p = \frac{\text{e.m.f. in short - pitch coil}}{\text{e.m.f. in full - pitch coil}} = \frac{2E_A \cos \theta/2}{2E_A} = \cos \theta/2$

$\therefore K_p = \cos \theta/2$

↑ phasor sum
↓ arithmetic sum
 $E_A + E_A$

For a full-pitch winding, $K_p = 1$. However, for a short-pitch winding, $K_p < 1$.


Note that θ is always an integer multiple of the slot angle β .

Distribution Factor:

Even though we assumed concentrated winding in deriving EMF equation, in practice an attempt is made to distribute the winding in all the slots coming under a pole. Such a winding is called distributed winding.

In concentrated winding the EMF induced in all the coil sides will be same in magnitude and in phase with each other. In case of distributed winding the magnitude of EMF will be same but the EMF's induced in each coil side will not be in phase with each other as they are distributed in the slots under a pole. Hence the total EMF will not be same as that in concentrated winding but will be equal to the vector sum of the EMF's induced. Hence it will be less than that in the concentrated winding. Now the factor by which the EMF induced in a distributed winding gets reduced is called distribution factor and defined as the ratio of EMF induced in a distributed winding to EMF induced in a concentrated winding.

Distribution factor $K_d = \text{EMF induced in a distributed winding} / \text{EMF induced in a concentrated winding}$
 $= \text{vector sum of the EMF} / \text{arithmetic sum of the EMF}$



Let

$E = \text{EMF induced per coil side}$

$m = \text{number of slots per pole per phase,}$

$n = \text{number of slots per pole}$

$\beta = \text{slot angle} = 180/n$

The EMF induced in concentrated winding with m slots per pole per phase $= mE$ volts.

Fig below shows the method of calculating the vector sum of the voltages in a distributed winding having a mutual phase difference of β . When m is large curve ACEN will form the arc of a circle of radius r .

From the figure below $AC = 2r \sin \beta/2$

Hence arithmetic sum $= m \times 2r \sin \beta/2$

Now the vector sum of the EMF $s = 2r \sin m\beta/2$

Hence the distribution factor $K_d = \text{vector sum of the EMF} / \text{arithmetic sum of the EMF}$

$$= (2r \sin m\beta/2) / (m \times 2r \sin \beta/2)$$

$$K_d = (\sin m\beta/2) / (m \sin \beta/2)$$

In practical machines the windings will be generally short pitched and distributed over the periphery of the machine. Hence in deducing the EMF equation both pitch factor and distribution factor has to be considered. Hence the general EMF equation including pitch factor and distribution factor can be given as

$$\text{EMF induced per phase} = 4.44 f T_{ph} \times K_p K_d \text{ volts}$$

$$E_{ph} = 4.44 K_p K_d f T_{ph} \text{ volts}$$

$$\text{Hence the line Voltage } E_L = \sqrt{3} \times \text{phase voltage} = \sqrt{3} E_{ph}$$

MMF Space Wave of a Single Coil (Air-gap MMF distribution with fixed current through winding)

A cylindrical rotor machine with small air-gap as shown in Fig. 5.24(a) will be assumed here. The stator is imagined to be wound for two-poles with a single N-turn full-pitch coil carrying current i in the direction indicated. The figure shows some flux lines of the magnetic field set up. A north and corresponding south pole are induced on the stator periphery. The magnetic axis of the coil is from the stator north to the stator south. Each flux line radially crosses the air-gap twice, normal to the stator and rotor iron surfaces and is associated with constant mmf Ni . On the assumption that the reluctance of the iron path is negligible, half the mmf ($Ni/2$) is consumed to create flux from the rotor to stator in the air-gap and the other half is used up to establish flux from the stator to rotor in the air-gap. Mmf and flux radially outwards from the rotor to the stator (south pole on stator) will be assumed to be positive and that from the stator to rotor as negative.




Fig. 5.24 Mmf space wave of a single coil

The physical picture is more easily visualized by the developed diagram of Fig. 5.24(b) where the stator with the winding is laid down flat with the rotor on the top of it. It is seen that the mmf is a rectangular space wave wherein mmf of $+ Ni/2$ is consumed in setting flux from the rotor to stator and mmf of $- Ni/2$ is consumed in setting up flux from the stator to the rotor. It has been imagined here that the coil-sides occupy a narrow space on the stator and the mmf changes abruptly from $-Ni/2$ to $+ Ni/2$ at one slot and in reverse direction at the other slot. The mmf change at any slot is

$$Ni = \text{ampere-conductors/slot}$$

and its sign depends upon the current direction.

The mmf space wave of a single coil being **rectangular**, it can be split up into its fundamental and harmonics.

MMF Space Wave of One Phase of a Distributed Winding:

Consider now a basic 2-pole structure with a round rotor, with 5 slots/pole/phase (SPP) and a 2-layer winding as shown in Fig. 5.25. The corresponding developed diagram is shown in Fig. 5.26(a) along with the mmf diagram which now is a stepped wave obviously closer to a sine wave than the rectangular mmf wave of a single coil (Fig. 5.24(b)). Here since SPP is odd (5), half the ampere-conductors of the middle slot of the phase group a and a' contribute towards establishment of south pole and half towards north pole on the stator. At each slot the mmf wave has a step jump of $2N_c i_c$, ampere-conductors where N_c = coil turns (equal to conductors/layer) and i_c = conductor current.




Fig. 5.25 A 3-phase, 2-pole structure with two-layer winding




Fig. 5.26 Developed diagram and mmf wave of the machine of Fig. 5.25

Now F_{1p} , the peak of the fundamental of the mmf wave, has to be determined. Rather than directly finding the fundamental of the stepped wave, one can proceed by adding the fundamentals of the mmf s of individual slot-pairs (with a span of one pole-pitch). These fundamentals are progressively out of phase (space phase as different from time phase) with each other by the slot angle γ . This addition is easily accomplished by defining the breadth factor K_b , which will be the same as in the case of the generated emf of a coil group.

Harmonic Effect

- The flux distribution along the air gaps of alternators usually is non-sinusoidal so that the emf in the individual armature conductor likewise is non-sinusoidal
- The sources of harmonics in the output voltage waveform are the non-sinusoidal waveform of the field flux.
- Fourier showed that any periodic wave may be expressed as the sum of a d-c component (zero frequency) and sine (or cosine) waves having fundamental and multiple or higher frequencies, the higher frequencies being called harmonics.

Elimination or Suppressed of Harmonics

Field flux waveform can be made as much sinusoidal as possible by the following methods:

1. Small air gap at the pole centre and large air gap towards the pole ends
2. **Skewing:** skew the pole faces if possible
3. **Distribution:** distribution of the armature winding along the air-gap periphery
4. **Chording:** with coil-span less than pole pitch
5. **Fractional slot winding**
6. **Alternator connections:** star or delta connections of alternators suppress triplen harmonics from appearing across the lines

Note: For Problems and winding diagrams, please go through the class note book

Induction motors

AC 3/m is universally adopted for all applications such as lighting purposes, heating purposes, industrial purposes.

Motor manufactures have tried to manufacture motors for industrial purposes as AC motors.

Industrial purposes the need of AC motors increases. Thus the motor manufacture manufactures single AC & 3 phase AC motors.

An AC motor is connected to AC supply. a rotating magnetic field is set up in stator.

The speed of rotating magnetic field which revolves in the stator is called synchronous speed.

Such motors are called as synchronous motor.

AC motors are classified as

Synchronous motors

Speed of rotating field is synchronous

asynchronous motor

Speed of rotating field is below the synchronous speed or other than synchronous speed.

In case of dc motors, electrical power is conducted directly to the rotor part through brushes & commutation

Hence such motors are called a conduction motor.

In case of AC motor, Rotor does not receive electric power by conduction but rotor receives electric power by induction. Such motor receives electric power by induction are called Induction motors.

An induction motor can be treated as a rotating transformer because the stator is stationary one can acts as primary winding which ~~receives~~ takes the supply AC. the rotor is rotating one can acts as a secondary which receives electrical power ^{by induction} to convert the mechanical power at the rotor.

Advantages of I.M

- simple in construction, extremely rugged
- cost is low & more reliable
- It has high efficiency, brushes are absent for normal running conditions, hence frictional losses are reduced.
- It maintains good power factor i.e 0.85
- maintenance is minimum
- It is inherently a self starting motor i.e it does not require any separate motor to start up from rest position.

No need to synchronise with the supply frequency.

Disadvantages

→ It runs at constant speed, speed cannot be varied.

It is possible to control the speed, the efficiency of such motor losses & decreases

→ Its starting torque is low when compared to dc shunt motor.

Principle of Induction motor

Induction motor is an ac motor, the supply is given to the stator which is stationary one, current will set up a magnetic field in stator. This field revolves in stator at synchronous speed. This rotating magnetic field will induce a current in rotor by induction will set up a torque. The torque produced in rotor is rotating other than the synchronous ~~speed~~ speed.

Construction

It consists of stator & rotor.

(a) stator

It is a stationary one, which consists of number of stampings to receive the windings as slots.

→ stator carries a 3-phase winding & is given 3 phase ac supply.

→ The speed of the induction motor depends upon the number of poles.

$$P = 2n$$

where n is no. of stator slots per phase per pole

The rotor slots are not parallel with the rotor shaft but are arranged as skewed

The main advantages of provided skewed slots are

→ Reducing the magnetic hum

→ Reducing the locking tendency of rotor
i.e. Rotor teeth remaining under stator teeth due to magnetic attraction.

In small motors, complete rotor core is placed in a mould & all the bars & end rings forms as one piece. The metal used here are aluminium alloy.

Phase-wound Rotor

The rotor is provided with 3 phase supply consists of double layer, distributed winding.

→ Here rotor is wound as number of poles Δ is always wound 3 phase even, when stator is wound as 2 phase.

→ Here stator & rotor are 3 phase star connected manner.

→ The three phases are star connected internally & are brought out connected to the 3 insulated slip rings mounted on the rotor shaft.

→ Here slip rings are used to increase the starting torque of I_m by providing an external resistance connected to the each slip ring.

* rotor slots are not parallel to the rotor shaft they are provided slightly skewed.

Skewing of rotor helps

- (i) Reduces magnetic humming
- (ii) Reduces lock tendency of rotor, it avoids of rotor teeth under stator teeth

Advantages of Squirrel Cage rotor

- * Construction is rugged
- * Rotor bars completely welded so no burning of winding
- * Long life + little maintenance
- * High efficient

Disadvantages

- * Rotor bars are permanently welded no starting resistances are added to control speed
- * Starting torque is low.
- * Starting Currents is very high i.e 6 to 7 times rated Current.
- * operates on low power factor.

(2) Phase wound rotor or slip ring rotor

- * Here Rotor is wound for many poles.
- * Rotor windings wound similar to stator winding for number of poles.
- * Here rotor is wound for 3 phases. are connected to star manner.
- * Other 3 windings are brought out & are connected to 3 insulated slip rings, mounted on shaft. with brushes.
- * The windings through brushes are connected to 3 phase star connected grid.

Greater the number of poles, lesser the speed of I.M.

→ when stator is supplied with 3 phase supply a magnetic field is set up in stator, this field revolves in stator at synchronous speed having constant ~~magnitude~~ magnitude.

$$N_s = \frac{120 \times f}{P}$$

Rotor

Rotor

2 Types of rotor

- (i) squirrel-cage rotor (ii) phase-wound rotor.


90% of I.M uses squirrel-cage type rotor because simple & rugged construction.

→ Rotor is laminated core provided with parallel slots for carrying rotor conductors.

→ The rotor conductors are of copper bars or aluminium or alloy bars.

→ Each bar is placed in each slot forms a semi-closed circuit.

→ The rotor bars are electrically welded & is bolted with short circuit end rings



→ The rotor bars are ~~not~~ completely short circuited and not possible to add any external resistance for starting purposes.

The rotor slots are not parallel with the rotor shaft but are arranged as skewed

The main advantages of provided skewed slots are

→ Reducing the magnetic hum

→ Reducing the locking tendency of rotor

ie Rotor teeth remains under stator teeth due to magnetic attraction.

In small motors, complete rotor core is placed in a mould & all the bars & end rings forms as one piece. The metal used here are aluminium alloy.

Phase-wound Rotor

The rotor is provided with 3 phase supply consists of double layer, distributed winding.

→ Here rotor is wound as number of poles Δ is always wound 3 phase even, when stator is wound as 2 phase.

→ Here stator & rotor are 3 phase star connected manner.

Rotor

→ The three phases are star connected internally & are brought out connected to the 3 insulated slip rings mounted on the rotor shaft.

→ Here slip rings are used to increase the starting torque of IM by providing an external resistance connected to the each slip ring.




fig (a)

phase wound rotor provided with slip rings

During normal running conditions, the slip rings are short circuited automatically. i.e rotor is short circuited.


Production of Rotating field

When stator is provided with 2 phase supply or 3 phase supply, a rotating magnetic flux of constant magnitude is produced in stator.

Two supply

The principle of 2 phase, 2 pole stator consists of 2 identical windings each are spaced at 90° apart.

Let current flowing through each phase winding be sinusoidal. flux set up in each phase windings ϕ_1 & ϕ_2 .



Advantages

- * Starting is high torque & starting torque is high due to internal resistances with slip rings.
- * External resistances are to be added to rotor circuit
- * Requires little current to start
- * Speed can be easily controlled using external resistances.
- * Operates at high power factor.

Drawbacks

- * Construction is complicated
- * Chance of burning of rotor windings
- * frequent & requires maintenance
- * Performance is low

General Principle of induction motor

In dc motors electric power is conductively give to armature (rotor). Hence dc motor is a conduction motor.

In case of AC motors, rotor receive power by induction such motors receives electric power are called induction motors.

when stator is connected to 3 phase supply stator windings carries \sin/\cos currents produces

a rotating flux having constant magnitude revolving in stator at synchronous speed.

* This revolving flux induces an emf in stator conductors by mutual induction.

* This induced emf set up a torque which tends to rotate the rotor ~~at~~ other than the synchronous speed.

Production of rotating field

if stator is provided with 2 phase or 3 phase supply, a rotating flux of constant magnitude is produced in stator.


Two phase supply:

Let phase ① + phase ② are 2 phase supply each are spaced at 90° apart.

Let current flowing through each phase is sinusoidal produces a sinusoidal flux in each windings ϕ_1 + ϕ_2 .

Let ϕ_r be the resultant flux

$$\phi_r = \phi_1 + \phi_2$$



θ = phase angle
 ϕ_m = max flux

we know that $\sin \theta = \cos(90 - \theta)$

at $\theta = 0$, $\phi = \cos(90 - 0) = 0$

$\phi_1 = 0$, $\phi_2 = -\phi_m$

$$\phi_r = \sqrt{(\phi_1)^2 + (\phi_2)^2} = \sqrt{(-\phi_m)^2} = \phi_m$$

(b) when $\theta = 45^\circ$

$$\phi_1 = \phi_m \cos(90 - \theta) = \phi_m \cos(90 - 45)$$

$$\phi_m = \phi_1 \times \frac{1}{\sqrt{2}} \quad \text{or} \quad \phi_m = 0.707$$

$$\phi_2 = -\phi_m \cos(90 - \theta) = -\phi_m \cos(90 - 45)$$

$$\phi_2 = -\phi_m \times \frac{1}{\sqrt{2}} \quad \text{or} \quad -\phi_m \times 0.707$$

$$\phi_r = \phi_m \quad \phi_r = \sqrt{\phi_1^2 + \phi_2^2}$$

(c) when $\theta = 90^\circ$

$$\phi_1 = \phi_m \cos(90 - \theta) = \phi_m \cos(90 - 90)$$

$$\phi_1 = \phi_m$$

$$\phi_2 = -\phi_m \times 0 = 0$$

$$\phi_r = \sqrt{\phi_1^2 + \phi_2^2} = \sqrt{(\phi_m)^2 + 0} = \phi_m$$

(d) when $\theta = 135^\circ$

$$\phi_1 = \phi_m \cos(90 - \theta) = \phi_m \cos(90 - 135)$$

$$\phi_1 = \phi_m \times \frac{1}{\sqrt{2}}$$

$$\phi_2 = \phi_m \times \frac{1}{\sqrt{2}}$$

$$\phi_r = \phi_m$$

(e) when $\theta = 180^\circ$

$$\phi_1 = \phi_m \cos(90 - \theta) = \phi_m \cos(90 - 180)$$

$$\phi_1 = 0$$


$$\phi_2 = \phi_m$$

$$\phi_r = \phi_m$$

from, we conclude that resultant flux is constant & is equal to ϕ_m .

So $\phi_r \rightarrow$ resultant flux rotates at synchronous speed in stator $N_s = 120 f/p$.

For 3 phase supply



Let $\phi_1 = \phi_m \sin \omega t$

$\phi_2 = \phi_m \sin(\omega t - 120)$, $\phi_3 = \phi_m \sin(\omega t - 240)$

if $\theta = 0$

$\phi_1 = 0$, $\phi_2 = -\phi_m \sin(0 - 120) = -\phi_m \times \left(-\frac{\sqrt{3}}{2}\right)$

$\phi_2 = \phi_m \times \frac{\sqrt{3}}{2}$

$\phi_3 = \phi_m \sin(\omega t - 240) = -\phi_m \times \frac{\sqrt{3}}{2}$

$\phi_r = \sqrt{\phi_1^2 + \phi_2^2 + \phi_3^2} = \sqrt{0 + \left(-\frac{\sqrt{3}}{2}\right)^2 + \left(\frac{\sqrt{3}}{2}\right)^2}$
 $= \sqrt{\frac{3}{4} + \frac{3}{4} + 0} = \sqrt{\frac{6}{4}} = \frac{3}{2} \phi_m$

if $\theta = 60^\circ$

Rotor emf & Rotor reactance

$$E_r = s E_2$$

$$X_r =$$

Under Running Conditions

Let

$E_2 =$ standstill rotor emf/phase

$X_2 =$ rotor reactance/phase at standstill

$f_2 =$ rotor frequency at standstill

if rotor is at rest position (About to start)

$$s = 1$$

$f_2 =$ stator supply frequency 'f'

E_2 is maximum at standstill position

$$\left\{ \begin{array}{l} E_r = s E_2 = 1 \times E_2 \text{ (maximum)} \\ X_r = s X_2 = 1 \times X_2 \\ f_r = s f_2 = 1 \times f_2 = f \text{ (supply)} \end{array} \right\}$$

When rotor is running, it is due to relative speed b/c of ~~rotor~~ rotating stator flux & rotor conductor, ~~flux~~ is decreased, relative speed also decreased.

Hence for a slip 's' rotor emf will be 's' times the induced emf at standstill.

Under running Conditions

$$E_r = s E_2$$

$$f_r = s f_2$$

$$X_r = s X_2$$

Torque under running Conditions

$$T \propto E_2 I_2 \cos \phi_2 \quad \text{or}$$

$$T \propto \phi I_2 \cos \phi_2 \quad \text{if } V \text{ is constant } \phi = E_2$$

under running conditions the Torque is given as

$$T \propto E_r I_r \cos \phi_2$$


if supply voltage is constant then

$$\phi \propto E_r \quad E_r = \phi$$

$$T \propto \phi I_r \cos \phi_2$$

$E_r =$ Rotor emf / phase under running conditions

$I_r =$ Rotor emf / phase " " "



$$I_r = \frac{E_r}{Z_r} = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

$$\cos \phi_2 = \frac{R_2}{Z_r} = \frac{R_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

at standstill $E_2 \propto \phi$

$$T \propto \frac{s \phi E_2 R_2}{R_2^2 + (sX_2)^2} = \frac{k \phi \cdot s \cdot E_2 R_2}{R_2^2 + (sX_2)^2}$$

$$T = \frac{k_1 E_2 \cdot s \cdot E_2 R_2}{R_2^2 + (sX_2)^2} = \frac{k_1 \cdot s \cdot E_2^2 R_2}{R_2^2 + (sX_2)^2}$$

$$T = \frac{3}{2\pi N_s} \cdot \frac{s E_2^2 R_2}{R_2^2 + (sX_2)^2} = \frac{3}{2\pi N_s} \cdot \frac{s E_2^2 R_2}{Z_r^2}$$

At standstill rotor emf $E_2 \propto \phi$
 $s = 1$

$$T = \frac{3}{2\pi N_s} \cdot \frac{E_2^2 R_2}{Z_r^2}$$

$$Z_r^2 = R_2^2 + X_2^2$$

Q) A connected I.M has standstill impedance $(0.4 + j4) \Omega$ / phase & Rheostat impedance $(6 + j2) \Omega$ / phase.

Induced emf of motor is 80V b/c slip rings at standstill when connected to normal supply voltage. Find (i) Rotor Current at standstill with Rheostat (ii) when slip rings are short circuited & motor is running with a slip 3%.

sol

At standstill Conditions

$$\text{Induced emf / phase } E_2 = \frac{80}{\sqrt{3}} = 46.2 \text{ V}$$

$$\text{Stator impedance / phase } Z_2 = (0.4 + j4) + (6 + j2)$$

$$Z_2 = 6.4 + j6 = 8.77 \angle 43.16$$

$$\text{Rotor Current / phase } I_2 = \frac{E_2}{Z_2} = \frac{46.2}{8.77} = 5.27$$

$$\text{given } \phi = 43.16$$

$$\text{P.f} = \cos \phi = \cos(43.16) = 0.729$$

(ii) Slip rings are short circuited under running Conditions.

$$\text{Rotor induced emf / phase} = sE_2$$

$$E_r = sE_2 = 0.03 \times 46.2 = 1.386 \text{ V}$$

$$\text{Rotor impedance / phase } Z_r = R_2 + j(sX_2)$$

$$\text{Rotor Current / phase } I_r = \frac{E_r}{Z_r} = \frac{1.386}{0.4 + j0.12} = 0.4 + j0.12 \text{ A}$$

Condition Maximum Torque Condition under running

under running Condition, Torque

$$T \propto \frac{\phi E_2 * s * R_2}{R_2^2 + (X_2 s)^2} \quad \text{at standstill position } E_2 \propto \phi$$

$$T = \frac{K_1 * s * E_2^2 * R_2}{R_2^2 + (sX_2)^2}$$

Let $Y = \frac{1}{T}$

$$Y = \frac{R_2^2 + (SX_2)^2}{KSE_2^2 R_2}$$

$$= \frac{R_2^2}{KSE_2^2 R_2} + \frac{(SX_2)^2}{KSE_2^2 R_2} = \frac{R}{SE_2^2 + K}$$

Torque under running condition

$$T = \frac{K\phi E_2 S R_2}{R_2^2 + (SX_2)^2} \Rightarrow \text{Let } Y = \frac{1}{T}$$

$$Y = \frac{R_2^2 + (SX_2)^2}{K\phi E_2 S R_2} = \frac{R_2^2}{K\phi E_2 S R_2} + \frac{(SX_2)^2}{K\phi E_2 S R_2}$$

$$Y = \frac{R_2}{K\phi SE_2} + \frac{SX_2^2}{K\phi E_2 R_2}$$

differentiate with respect to (S)

$$\frac{dy}{ds} = \frac{+R_2}{K\phi E_2} \frac{d}{ds} \left(\frac{1}{S} \right) + \frac{X_2^2}{K\phi E_2 R_2} = 0$$

$$= \frac{-R_2}{K\phi E_2 S^2} + \frac{X_2^2}{K\phi E_2 R_2} = 0$$

$$\frac{X_2^2}{K\phi E_2 R_2} = \frac{R_2}{K\phi E_2 S^2}$$

$$X_2^2 = \frac{K\phi E_2 R_2^2}{K\phi E_2 S^2}$$

$$R_2^2 = S^2 X_2^2 = (SX_2)^2 \quad \text{or } R_2 = SX_2$$

Under running conditions, Torque is maximum if motor resistance / phase $R_2 =$ slip times the motor reactance / phase

$$R_2 = SX_2 \Rightarrow \boxed{S = \frac{R_2}{X_2}}$$

$$T_b \text{ \& } T_{max} =$$

$$T_{max} = \frac{k\phi s E_2 R_2}{R_2^2 + (sX_2)^2}$$

Torque under running condition

$$T = \frac{k\phi s E_2 R_2}{R_2^2 + (sX_2)^2} \rightarrow (1)$$

if $R_2 = sX_2$ in above equation we get maximum torque

$$T_{max} = \frac{k\phi s E_2 (sX_2)}{(sX_2)^2 + (sX_2)^2} = \frac{k\phi s^2 E_2 X_2}{2(sX_2)^2} \quad (2)$$

$$T_{max} = \frac{k\phi s E_2 R_2}{R_2^2 + R_2^2} = \frac{k\phi s E_2 R_2}{2R_2^2}$$

$$T_{max} = \frac{k\phi s E_2 R_2}{2R_2^2} = \frac{k\phi s E_2}{2R_2} \quad (3)$$

$$R_2 = sX_2$$

$$T_{max} = \frac{k\phi s E_2}{2sX_2} = \frac{k\phi E_2}{2X_2}$$

\Rightarrow if $s = \frac{R_2}{X_2}$ then maximum torque

$$T_{max} = \frac{k\phi s E_2 R_2}{R_2^2 + (sX_2)^2} = \frac{k_1 \phi \left(\frac{R_2}{X_2}\right) \times E_2 \times R_2}{R_2^2 + (sX_2)^2}$$

at standstill E_2 & ϕ

$$T_{max} = \frac{k_1 E_2^2 \times \frac{R_2^2}{X_2}}{R_2^2 + \left(\frac{R_2}{X_2}\right)^2 \cdot X_2^2} = \frac{k_1 E_2^2 \times \frac{R_2^2}{X_2}}{2R_2^2}$$

$$T_{max} = k_1 E_2^2 \times \frac{R_2^2}{2R_2^2 X_2} = k_1 E_2^2 \times \frac{1}{2X_2}$$

$$T_{max} = \frac{k_1 E_2^2}{2X_2}$$

$$k_1 = \frac{3}{2\pi N_s}$$

Effect of change in supply voltage on starting torque

$$T = k_1 \phi I_2 \cos \phi_2$$

we know that

$$T_{st} = \frac{k_1 E_2^2 R_2}{R_2^2 + X_2^2}$$



$E_2 \propto V$ then starting torque

$$T_{st} = \frac{k_2 (LV)^2 R_2}{R_2^2 + X_2^2}$$

Condition for maximum torque

Maximum torque occurs if rotor resistance $R_2 =$ rotor reactance X_2

$$R_2 = X_2$$

then

$$T_{st} = \frac{k_1 E_2^2 R_2}{R_2^2 + X_2^2}$$

$$k_1 = \frac{3}{2\pi N_s}$$

if given supply voltage is constant then flux ϕ & induced emf E_2 both are constant then T_{st} is given

$$V \propto \phi \propto E_2 = \text{constant}$$

$$T_{st} = \frac{k_3 R_2}{R_2^2 + X_2^2} = \boxed{\frac{k_3 R_2}{R_2^2 + X_2^2}}$$

Problem \rightarrow page NO (3)

3- ϕ Δ -connected I.M has stator to rotor turns ratio is 6:5. Rotor Reactance & Resistance 0.025 & 0.05 Ω /phase. what would be the value of external resistance R_E inserted in rotor circuit to obtain T_m at starting & what is the starting current of rotor.

1161

(3)

given stator to rotor turns ratio = 6.5

$$\frac{1}{K} = \frac{\text{Stator}}{\text{Rotor}} = \frac{1}{6.5}$$

$$X_2 = 0.25$$

$$R_2 = 0.05$$

$$K = \frac{\text{Rotor}}{\text{Stator}} = \frac{1}{6.5}$$

(λ to λ)

Rotor emf E_2 at standstill per phase for λ

$$E_2 = \frac{V_L}{\sqrt{3}} \times K = \frac{400}{\sqrt{3}} \times \frac{1}{6.5} = 35.5 \text{ V}$$

Tot is maximum if $R_2' = X_2$
 $R_2' = X_2 = 0.25 \Omega$

$$R_2 = X_2$$

$$R_2' = 0.25$$

$$R_E = R_2' - R_2$$

$$= 0.2 \Omega$$

External Resistance R_E or R_E' per phase required is given

$$R_E' = R_2' - R_2$$

$$R_2 = X_2$$

$$R_2' = R_2 = 0.25$$

$$R_E = R_2' - R_2$$

$$= 0.25 - 0.05 = 0.2 \Omega$$

Rotor impedance / phase $Z_2 = \sqrt{(R_2')^2 + X_2^2}$

$$= \sqrt{(0.25)^2 + (0.25)^2}$$

$$= 0.3535$$

Rotor Current / phase

$$I_2 = \frac{E_2}{Z_2} = \frac{35.5}{0.3535} = 100 \text{ A}$$

Problem

$$V_p = 3000V, f = 50Hz, P = 6 \text{ pole}$$

Δ connected I.M has, λ -connected slip ring rotor with transformation ratio is 3.6.

$R_2 = 0.1 \Omega / \text{phase}$, $X_2 = 3.61 mH$. Neglect stator impedance. Find starting current I_1 & starting torque T_{st} on rated voltage with slip rings short circuited.

given

Rotor emf/phase for Star Connected

$$E_2 = \frac{V_L * K}{\sqrt{3}} = 3000 * \frac{1}{3.6}$$

$$K = \frac{\text{rotor turns}}{\text{stator turns}} = \frac{1}{3.6}$$

$$3.6 = \frac{\text{stator}}{\text{rotor}} = \frac{1}{K}$$

also given rotor reactance X_2 is given in Henry's

$$X_2 = 2\pi f * L = 2\pi * 50 * 3.61 * 10^{-3}$$

$$X_2 = 1.13 \Omega$$

change in rotor Rotor Resistance

$$R_2' = \frac{R_2}{K^2} = \frac{0.1 *}{\left(\frac{1}{3.6}\right)^2} = 1.3 \Omega$$

$$X_2' = \frac{X_2}{K^2} = \frac{1.13}{\left(\frac{1}{3.6}\right)^2} = 14.7 \Omega$$

(2)

$\frac{3}{2\pi N_s}$

$$T_{st} = \frac{K_1 * (V_p)^2 * R_2'}{(R_2')^2 + (X_2')^2}$$

Starting Current

$$K_1 = \frac{3}{2\pi N_s}$$

$$I_{st} = I_1 = \frac{V}{\sqrt{(R_2')^2 + (X_2')^2}}$$

Given I.m is connected in $\lambda-\lambda$

$$V_p = \frac{V_L}{\sqrt{3}} = \frac{3000}{\sqrt{3}} = V = 1732.05$$

$$I_{st} = \frac{V_p}{\sqrt{(R_2')^2 + (X_2')^2}} = \frac{1732.05}{\sqrt{(1.3)^2 + (14.7)^2}}$$

$$I_{st} = 117.4V$$

$$N_s = \frac{120 * f}{P} = \frac{120 * 50}{6} = 1000 \text{ rpm}$$

$$N_s' = \frac{f}{\frac{P}{2}}$$

$$N_s' = \frac{1000}{\frac{20}{2}} = \frac{50}{\frac{6}{2}} = \frac{50}{3}$$

$$T_{st} = \frac{3}{2\pi (50/3)} * \frac{(1732.05)^2 * 1.3}{\sqrt{(1.3)^2 + (14.7)^2}}$$

$$= 513 \text{ Nm}$$

(a) $V_L = 1100V$, $f = 50Hz$ Δ -connected I.M has star connected slip ring rotor with phase transformation ratio is 3.8.

Rotor

Resistance $R_2 = 0.012 \Omega/\text{phase}$

$X_2 = 0.25 \Omega/\text{phase}$.

$\frac{S_{stator}}{S_{rotor}} = K \frac{I_{stator}}{I_{rotor}}$

$\frac{S_{rotor}}{S_{stator}} = \frac{I_{rotor}}{I_{stator}}$

Neglect stator impedance & magnetising currents. Determine.

- (i) Rotor Current (I_2) at start with slip rings shorted
- (ii) Rotor power factor at start with slip rings shorted
- (iii) Rotor Current at 4% slip with slip rings shorted
- (iv) Rotor Power factor at 4% " " "
- (v) External Rotor Resistance (R_E) per phase required to obtain starting current 100A in stator supply lines.

Sol

given

Δ -Connected I.M

in delta connected $V_p = V_L$ or $V_L = V_p$

\Rightarrow Rotor emf at standstill per phase

$E_2 = V_p * K$ or $V_L * K$

$K = \frac{\text{Rotor turns/phase}}{\text{stator turns/phase}} = \frac{1}{3.8}$

$E_2 = \frac{1100}{3.8} = 289.5V$

Δ to λ

(i) Rotor current per phase at start

$$I_2 = \frac{E_2}{Z_2}$$

$$\text{Rotor impedance } Z_2/\text{phase} = \sqrt{R_2^2 + X_2^2}$$

$$= 0.2503 \Omega$$

$$I_2 = \frac{289.5}{0.2503} = 1157 \text{ A}$$

(ii) Rotor power factor if slip rings are shorted.

$$\phi_2 \text{ or } P.f = \frac{R_2}{Z_2}$$

$$P.f = VI \cos \phi$$

$$\phi_2 \text{ or } P.f = \frac{0.012}{0.2503} = 0.048$$

(iii) Rotor current at 4% slip

$$I_2 = \frac{E_r}{Z_r}$$

if Rotor is condition is moving position then we consider the slip.

$$\text{Rotor emf/phase } E_r = s E_2$$

$$\text{Rotor reactance/phase } X_r = s X_2$$

$$\text{Rotor impedance/phase } Z_r = \sqrt{R_2^2 + (s X_2)^2}$$

$$\text{slip } s = 4\% = \frac{4}{100} = 0.04$$

$$\sqrt{R_2^2 + (X_r)^2}$$

$$E_r = 0.04 * 289.5 = 11.58 \text{ V}$$

$$X_r = 0.04 * 0.25 = 0.01$$

$$Z_r = \sqrt{(0.012)^2 + (0.04 * 0.25)^2} = 0.0156 \Omega$$

$$I_2 = \frac{11.58}{0.0156} = 742.8 \text{ A}$$

$$\frac{E_2}{E_1} = \frac{s}{S} = \frac{I_1}{I_2} = K$$

(IV) Rotor Power factor with 4% slip

$$\cos \phi_2 \text{ or P.f.} = \frac{R_2}{Z_2} = \frac{0.012}{0.0156} = 0.769$$

(V) $K = \frac{I_1}{I_2} \Rightarrow I_2 = \frac{I_1}{K}$ $\frac{I_2}{I_1} = K$

where I_1 Stator Current at starting
Current = 100 A

$$I_2 = \frac{100}{1/3.8} = 380 \text{ A at standstill}$$

$$I_2 = \frac{E_2}{Z_2} \Rightarrow Z_2 = \frac{E_2}{I_2} = \frac{289.5}{380}$$

$$Z_2 = 0.7618$$

$$Z_2^2 = (R_2')^2 + X_2^2 \quad \checkmark$$

$$(R_2') = \sqrt{Z_2^2 - X_2^2}$$

$$\sqrt{Z_2^2 - X_2^2} = R_2' = 0.7169$$

External Resistance R_E per phase required

$$R_E = R_2' - R_2 = 0.7169 - 0.012 = 0.707$$

Rotor torque & Breakdown Torque

Rotor torque at any slip can be expressed in terms of maximum torque

$$T = T_b \left[\frac{2}{(s_b/s) + (s/s_b)} \right]$$

s_b = breakdown or pull out slip

Q Calculate Torque exerted by an 8 pole, 50Hz 3 ϕ Im having 4% slip which develops max torque of 150 kg-m at a speed of 660 rpm. Resistance / phase of rotor is 0.5 Ω .

sol

given maximum Torque $T_{max} = 150$ kg-m.

Speed at maximum Torque = 660 rpm, $P = 8$

$$\rightarrow N_s = \frac{120 f}{P} = \frac{120 \times 50}{8} = 750 \text{ rpm}$$

$$\rightarrow s_b = \text{breakdown slip} = \frac{N_s - N}{N_s} = \frac{750 - 660}{750}$$

$$s_b = 0.12$$

also given original slip of Im is 4%

$$s = 0.04, R_2 = 0.5$$

Condition for maximum torque is

$$R_2 = s_b X_2$$

$$X_2 = \frac{0.5}{0.12} = 4.167$$

$$T_{max} = \frac{k \phi s E_2 R_2}{R_2^2 + (s X_2)^2}$$

if $R_2 = s_b X_2$

$$\rightarrow T_{max} = \frac{k \phi s E_2}{2 R_2} = \frac{k \phi s_b E_2}{2 R_2}$$

$$= 0.12 k \phi E_2 \rightarrow \text{①}$$

if slip 's' is 4%. Then

$$T = \frac{k \phi E_2 \cdot s \cdot R_2}{R_2^2 + (s X_2)^2}$$

$$T = \frac{k \phi E_2 \cdot s \cdot R_2}{R_2^2 + (s X_2)^2}$$

$$R_2^2 + (s X_2)^2$$


$$T = \frac{k\phi E_2 * 0.04 * 0.5}{(0.5)^2 + (0.04 * 4.167)^2} = \frac{0.02 k\phi E_2}{0.2778}$$

$$\frac{T}{T_{max}} = \frac{T}{150} = \frac{0.02 k\phi E_2}{0.2778} * \frac{1}{0.12 k\phi E_2}$$

$$\frac{T}{150} = \frac{0.02}{0.2778 * 0.12} \Rightarrow T = \frac{0.02 * 150}{0.2778 * 0.12}$$

$$T = 90 \text{ kg-m}$$

Relation between slip & Torque



from figure slip ranges from $s=0$ to $s=1$
 \rightarrow if $s=0$, $T=0$

$$T = \frac{k\phi s E_2 R_2}{R_2^2 + (s x_2)^2} = 0$$

Curve starts from (0).

\rightarrow At normal speeds, R_2 is negligible, $s x_2$ is small

\rightarrow As slip (s) increases continuously then

Torque becomes maximum. This torque is known as pullout torque or breakdown torque. or stalling torque

[As load on motor increases, Torque of motor also increases & becomes max:]

We know that maximum torque occurs if $R_2 = sX_2$

$$\therefore \text{slip } (s) = \frac{R_2}{X_2}$$

→ when torque reaches max:, as slip further increases, (as load on motor again increases), speed of motor decreases, torque of motor also decreases, finally motor slows down & eventually stops.

$$T = \frac{k\phi s E_2 * R_2}{R_2^2 + (sX_2)^2}$$

if k, ϕ, E_2 are constants, R_2 becomes negligible & X_2 becomes small

$$T = \frac{s}{(sX_2)^2} = \frac{1}{s}$$

$$T = \frac{1}{s}$$

Effect of change in supply voltage on Torque & speed

we know that Torque under Running Condition is given by

$$T = \frac{k\phi s E_2 R_2}{R_2^2 + (sX_2)^2}$$

At normal speeds R_2 is negligible, sX_2 is small

$$T = \frac{k\phi s E_2}{1}$$

If supply voltage (V) is constant, ϕ is constant

Then E_2 is also constant

$$E_2 \propto \phi \propto V$$

$$T \propto \phi s E_2$$

$$T \propto V * s * V \Rightarrow T \propto s V^2$$

Torque is proportional square of voltage.

→ If stator voltage decreases 10%, Torque decreases by 20%, speed also decreases.

Effect of changes in supply frequency on Torque & speed

Whenever a major disturbance occurs, first effected is supply frequency.

→ Change in frequency leads to change in motor speed. ($f \propto V$)

→ If supply frequency drops by 10%, motor speed decreases by 10%.

→ If motor is designed to operate 50Hz is connected to 60Hz supply frequency, Motor runs 20% faster than normal speed

→ for obtaining the normal speed we go for using the gears to control the speed.

→ If a 50Hz motor is well operated at 60Hz, its terminal voltage is raised by 120% of normal rating

→ A 60Hz motor will operate on 50Hz, its terminal voltage is reduced by 20% of normal voltage

full-load Torque & maximum Torque

Let the full load slip be s_f

T_f be the full load torque & T_{max} be maximum torque

$$T_f \propto \frac{\phi s_f E_2 R_2}{R_2^2 + (s_f X_2)^2}$$

if motor is at standstill position

$$E_2 \propto \phi$$

$$T_f = \frac{K s_f E_2^2 R_2}{R_2^2 + (s_f X_2)^2} \rightarrow (1) \quad \left[\begin{array}{l} T_{max} \propto \frac{\phi E_2}{2X_2} \\ T_{max} = \frac{K E_2^2}{2X_2} \end{array} \right.$$

$$T_{max} = \frac{K E_2^2}{2X_2} \quad \text{or} \quad \frac{K \phi E_2}{2X_2}$$

→ (2)

$$\frac{T_f}{T_{max}} = \frac{K s_f E_2^2 R_2}{R_2^2 + (s_f X_2)^2} = \frac{2 s_f R_2 X_2}{R_2^2 + (s_f X_2)^2} \cdot \frac{K E_2^2 / 2X_2}{K E_2^2 / 2X_2}$$

divide both Numerator & denominator by X_2^2 we get

$$\frac{T_f}{T_{max}} = \frac{2 s_f R_2 \frac{X_2}{X_2^2}}{\frac{R_2^2 + s_f^2 X_2^2}{X_2^2}} = \frac{2 s_f R_2 / X_2}{(R_2 / X_2)^2 + s_f^2} \rightarrow (3)$$

let $a = R_2 / X_2$ then equation (3)

$$\frac{T_f}{T_{max}} = \frac{2 s_f a}{a^2 + s_f^2}$$

$$\frac{T_f}{T_{max}} = \frac{2as_f}{a^2 + s_f^2}$$

if $a = s_{max}$ maximum slip then

$$\frac{T_f}{T_{max}} = \frac{2s_{max}s_f}{s_{max}^2 + s_f^2}$$

divide numerator & denominator by $s_{max}s_f$

$$\frac{T_f}{T_{max}} = \frac{2}{\frac{s_{max}}{s_f} + \frac{s_f}{s_{max}}} = \frac{2}{\frac{s_{max}}{s_f} + \frac{s_f}{s_{max}}}$$

→ starting torque & maximum torque

We know that starting torque

$$T_{st} \propto \frac{\phi E_2 R_2}{R_2^2 + X_2^2}$$

Constants if rotor flux, induced emf are constant
if supply voltage is constant

$$T_{st} \propto \frac{R_2}{R_2^2 + X_2^2} \rightarrow (1)$$

We know that maximum torque

$$T_{max} \propto \frac{\phi E_2}{2X_2}$$

if supply voltage constant,
 ϕ & E_2 are also constant

$$T_{max} \propto \frac{1}{2X_2} \rightarrow (2)$$

$$\frac{T_{st}}{T_{max}} = \frac{R_2}{\frac{R_2^2 + X_2^2}{\frac{1}{2X_2}}}$$

$$\frac{T_{st}}{T_{max}} = \frac{2R_2 X_2}{R_2^2 + X_2^2} = \frac{2R_2 X_2}{X_2^2 \left[\left(\frac{R_2}{X_2} \right)^2 + 1 \right]}$$

$$\frac{T_{st}}{T_{max}} = \frac{2R_2/X_2}{\left(R_2/X_2 \right)^2 + 1} = \frac{2a}{a^2 + 1}$$

Problem

A 746 kW 3 phase 50 Hz, 16 pole I.m has rotor impedance $(0.02 + j0.15)$ at stand still. T_f is obtained at 360 rpm. calculate
 (i) Ratio of T_{max} to T_f (ii) Speed of T_{max}
 (iii) Rotor resistance to be added to get maximum starting torque.

Sol

$$\text{(i)} \quad \frac{T_f}{T_{max}} = \frac{2a s_f}{a^2 + s_f^2}$$

given $f = 50 \text{ Hz}$ $P = 16$

$$Z_2 = R_2 + jX_2 = 0.02 + j0.15$$

T_f is obtained at speed $N = 360 \text{ rpm}$

$$N_s = \frac{120f}{P} = 375 \text{ rpm}$$

$$s_f = \frac{N_s - N}{N_s} = \frac{375 - 360}{375} = 0.04$$

$$a = \frac{R_2}{X_2} = \frac{0.02}{0.15} = 0.133$$

$$\frac{T_f}{T_{max}} = \frac{2 * 0.133 * 0.04}{(0.133)^2 + (0.04)^2} = 0.55$$

$$\frac{T_{max}}{T_f} = \frac{1}{0.55} = 1.818 \text{ N-m}$$

(ii) at maximum torque, slip is maximum

$$a = s_{max} = \frac{R_2}{X_2} = \frac{0.02}{0.15} = \frac{2}{15} = 0.133$$

$$N = N_s(1-s) = 375(1-0.133) = 325 \text{ rpm}$$

(iii) Maximum torque occurs

$$\text{if } R_2 = X_2$$

$$R_2 = 0.15$$

$$R_E = R_2' - R_2 = 0.15 - 0.02 = 0.13 \Omega$$

Problem 3 ϕ I.M having 6-pole Δ -connected stator winding runs on 240V, 50Hz supply. Rotor Resistance & reactance are 0.12Ω & $0.85 \Omega/\text{phase}$. The ratio stator to rotor turns is 1.8. full load slip 4%. Calculate developed torque at full load, T_m & speed at T_{max} .

Sol.

$$K = \frac{\text{rotor turns}}{\text{stator turns}} = \frac{1}{1.8}$$

Rotor induced emf/phase $E_2 = \frac{V_L}{\sqrt{3}} * K = \frac{240}{\sqrt{3}} * \frac{1}{1.8}$

$$E_2 = 77V$$

$$\text{slip } s = 4\% = 0.04$$

$$\text{also } P=6, f=50\text{Hz}, R_2=0.12, X_2=0.85$$

$$N_s = \frac{120 * f}{P} = \frac{120 * 50}{6} = 1000$$

$$N_s = \frac{1000}{60} = 16.666$$

$$N_s = \frac{120 * f}{P * 60} = \frac{1000}{2060} = \frac{50}{3}$$

$$N_s = \frac{50}{P/2} = \frac{50}{6/2} = \frac{50}{3}$$

$$N_s = \frac{120f}{P * 60} \frac{P}{P/2}$$

$$T_f = K_1 * \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2} = \frac{3}{2\pi(N_s/60)} * \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

Condition for maximum torque is $R_2 = s X_2$

synchronous alternator

Armature Reaction

It is defined as the effect of armature mmf on the mmf of main field flux.

This effect is 2 ways

① Cross magnetising effect ② de-magnetising effect

↳ Due to these pattern distribution of main field flux changes

Due to de-magnetising effect of armature reaction, main field flux becomes weakening or flux per pole decreases

The above 2 cases is for dc-generator.

In case of alternator these magnetising effect of armature reaction main field flux becomes strengthened or flux per pole increases

* If load is Resistive
effect of armature reaction is cross magnetising

* if load is inductive, effect of armature reaction is de-magnetising

* if load is Capacitive, effect of armature reaction is magnetising.

Purely Resistive load (P.f = unity)

When 3 phase alternator is loaded, stator carries 3 phase currents which gives armature magnetic field. which revolves in synchronous speed -

The magnetic field depends on

→ Position of poles

→ Load Current

→ Load P.f




fig 1 for unity load

Magnetic

→ from fig 1 Magnitude of armature MMF is constant with respect to time but it lags behind to the main field flux by 90° shown in fig 1

Phase angle b/w the 2 fluxes is 90° . So the armature reaction is purely cross magnetising. Due to this flux at the leading pole tips decreases & at trailing pole tips flux increases. Totally main field flux gets distorted.

purely inductive load (P.f=0, lagging)

$P.f = 0$, if $\cos\phi$ is zero if $\phi = 90^\circ$

$$\cos\phi = P.f = 0$$

$$\cos(90) = 0 = P.f$$




fig ③ flux waves for P.f=0 (lagging) load

In case of inductive load $P.f = 0$

if $\phi = 90^\circ$, $\therefore \cos(90) = 0$

$\cos\phi = P.f = 0$, if $\phi = 90$

from fig ② the position of main field flux is same but position of armature flux shifted by 90° . So armature flux is direct opposition to main field flux. Since current lag behind the voltage by 90° . So armature reaction is purely de-magnetizing due to this flux per pole decreases.

purely Capacitive Load $C.P.f = 0$, leading)

If load is purely Capacitive, $P.f = 0$,
if $\phi = -90^\circ$

$$\therefore P.f = \cos(-90) = 0$$

Here Current leads the voltage by -90° .
Hence position of main field flux remains same
but armature flux shifts by 90° .




fig ③ flux waves for leading p.f load

In this case from fig ③, both main field flux armature flux are in phase to each other. So armature reaction is purely magnetizing. The resultant main field flux per pole increases.

Voltage regulation of alternator

When an alternator is loaded, its terminal voltage decreases as load current ~~decreases~~ increases. The decrease in terminal voltage is due to

- ① Armature resistance & leakage reactance
- ② Armature reaction.

Voltage regulation definition

→ At constant speed & constant field excitation, terminal voltage of alternator changes from no load to full load is termed as voltage regulation.*

Let E_0 → no load terminal

V → Rated terminal voltage

or full load terminal voltage

} alternator

$$\% \text{ regulation} = \frac{E_0 - V}{V} * 100$$

→ Again regulation of alternator depends on load current & P.f of load.

→ Regulation is +ve for resistive & inductive loads

* Regulation is -ve for Capacitive loads.

→ In case of small size alternators, loading the machine upto rated current delivers.

Note down the full load terminal voltage & decrease load by keeping speed & excitation constant. Note down the no load voltage.

*** for testing large size alternators we go for adopting indirect methods.

1. EMF or synchronous impedance method

2. MMF or Ampere turn method

3. ZPF method or potier method

4. ASA method

1. Synchronous impedance method

Also known as e.m.f method. These test involves 3 tests

- (i) open circuit test (No load)
- (ii) short circuit test
- (iii) Measurement of armature Resistance.

(i) Open circuit test





Fig (i) o.c test

Also termed as no load test. By maintain the alternator speed constant & by varying field excitation, note down different values of induced emf.

I_f is continuously increasing, until the alternator developed rated voltage.


From ^{this} test we get the values of I_f & E_o . Plot the I_f vs E_o graph. This graph is o.c.c graph



By increasing I_f until generator develops rated voltage by maintaining speed constant.

(ii) Short circuit test


By keeping the field excitation at minimum position, allows to the alternator to run at rated speed on no load.



→ Alternator terminals are short circuited.

→ I_f is adjusted until the rated current flows through the short circuited terminals. Note down value of short circuit current (I_{sc}).

plot the graph I_f vs I_a characteristics



The above graphs o.c.c & s.c.c are drawn on Common plot.




fig 2 shows o.c.c & s.c characteristics represented on Common plot.

(iii) Measurement of R_a (armature resistance)

DC resistance of armature winding / phase is measured using Ammeter - Voltmeter or wheat stone bridge.

Here a small dc current is passed through any one of phase winding & note down the voltage drop across it.

$$\text{D.c resistance / phase} = \frac{\text{Voltage}}{\text{Current}}$$

Due to skin effect in a.c, effective or AC resistance is 1.5 times the d.c resistance

AC resistance = 1.5 times d.c resistance.




fig ③ shows measuring armature resistance.

→ In addition an alternator posses both ohmic & leakage reactance. When armature winding carries alternating current, a fluxes set up in windings. A small amount of flux links to the armature winding without crossing the air gap. This is known as leakage flux. Hence an alternator supplies armature resistance drop (IR) & armature leakage reactance drop (IX_L).

Thus for inductive loads, armature reaction is de-magnetising as a result induced emf reduces & is given by considering an additional fictitious reactance X_a .

emf drop is considered as IX_a . due to armature reaction. when

when an alternator is loaded, current flows through armature winding supplies internal voltage drops are IR_a , IX_L & IX_a

Due to skin effect in a.c, effective or AC resistance is 1.5 times the d.c resistance
 AC resistance = 1.5 times d.c resistance.




fig ③ shows measuring armature resistance.

→ In addition an alternator possesses both ohmic & leakage reactance. When armature winding carries alternating current, a fluxes set up in windings. A small amount of flux links to the armature winding without crossing the air gap. This is known as leakage flux. Hence an alternator supplies armature resistance drop (IR) & armature leakage reactance drop (IX_L).

Thus for inductive loads, armature reaction is de-magnetising as a result induced emf reduces & is given by considering an additional fictitious reactance X_a .

emf drop is considered as IX_a . due to armature reaction. when

when an alternator is loaded, current flows through armature winding supplies internal voltage drops are IR_a , IX_L & IX_a

Let E_0 = No load induced emf / phase

V = terminal voltage / phase

$$\therefore E_0 = V + IR_a + IX_L + IX_a$$

IR_a is in phase with I .

$IX_L + IX_a$ leads I by 90°

for resistive load phasor diagram





fig ① @ phasor diagram resistive load.

for inductive load phasor diagram fig ① ⑥



$$\cos \phi = \text{Load p.f}$$

$$X_s = X_L + X_a$$

for capacitive load phasor diagram refer ^{fig} 1b
by considering the dotted line Current leads.

$$\text{Let } X_s = X_L + X_a$$

$$IX_s = IX_L + IX_a$$

↳ termed as synchronous reactance (X_s)

from phasor diagram fig ①⑥


$$\begin{aligned} E_0 &= V + IX_s + IR_a \\ &= V + I(X_L + X_a) + IR_a \\ &= V + I(R_a + X_s) \end{aligned}$$

Reactance X is in complex or imaginary from ac write

$$E_0 = V + I(R_a + jX_s) = \boxed{V + IZ_s}$$

$$Z_s = R_a + jX_s$$

Z_s → termed as synchronous impedance.




$$OC^2 = ON^2 + CN^2$$

$$OC^2 = (OM + MN)^2 + (BN + BC)^2$$

$$E_0^2 = OC^2 = (V \cos \phi + IR_a)^2 + (V \sin \phi \pm IX_s)^2$$

$$E_0 = \sqrt{(V \cos \phi + IR_a)^2 + (V \sin \phi \pm IX_s)^2}$$



$\rightarrow I_f$
 PR = NO load induced emf/phase
 OR = field current

Synchronous impedance $Z_s = \frac{PR}{OR} = \frac{E_o}{I_{sc}} = \frac{O.C}{S.C}$

$$Z_s = \sqrt{R_a^2 + X_s^2}$$

R_a is known
 X_s is computed

$$\% \text{ Reg} = \frac{E_o - V}{V} * 100$$

Regulation at any desired load P.f can be determined.

Problems

if field excitation of 10A of alternator gives current 15A on short circuit & terminal voltage 900V on open circuit. Find the internal voltage drop with load current of 60A.

Sol. $I_f = 10A$, open circuit voltage $V_{oc} = 900V$
 short circuit current $I_{sc} = 15A$

internal voltage drop with 60A load current is

$$V = I Z_s$$

$$Z_s = \frac{V_{oc}}{I_{sc}} = \frac{900}{15} = 60 \Omega$$

$$V = I \times Z_s = 60 \times 60 = 3600 \text{ V}$$

Problem A 500V, 50KVA single phase alternator has an effective resistance of 0.2Ω . A field current 10A produces an armature current 200A on short circuit & an emf of 450V on open circuit. Calculate the full load regulation at 0.8 lag power factor.

Sol Rating of alternator = KVA = 50

Rated voltage = $V = 500 \text{ V}$,

effective resistance $R_a = 0.2 \Omega$, load p.f = 0.8 lag

$I_f = 10 \text{ A}$, $I_{sc} = 200 \text{ A}$, $E_o = \text{open circuit voltage} = 450 \text{ V}$

$$\% \text{ Reg} = \frac{E_o - V}{V} \times 100$$

$E_o = \text{open circuit \& no load voltage} = 450 \text{ V}$

$V = \text{terminal voltage} = 500 \text{ V}$

$$E_o = \sqrt{(V \cos \phi + I R_a)^2 + (V \sin \phi + I X_s)^2}$$

We know that synchronous impedance Z_s

$$Z_s = \frac{E_o}{I_{sc}} = \frac{\text{open circuit voltage}}{\text{short circuit current}} = 2.25 \Omega$$

$$Z_s = \sqrt{R_a^2 + X_s^2}$$

$$X_s = \sqrt{Z_s^2 - R_a^2} = 2.2411 \Omega$$

+ = lag
- = lead

$$\cos\phi = \text{p.f.} = 0.8 \text{ lag}$$

Rated Current $I = ?$

$$\text{KVA rating} = 50$$

$$\text{Rated voltage } V = 500 \text{ V}$$

$$\text{Rated Current } I = \frac{\text{VA} \times \text{Rating}}{\text{Rated Voltage}}$$

$$= \frac{50 \times 1000}{500} = 100 \text{ A}$$

$$E_0 = \sqrt{(500 \times 0.8 + 100 \times 0.2)^2 + (500 \times 0.6 + 100 \times 2.241)^2}$$
$$= 671.633 \text{ V}$$

$$\% \text{ full load regulation} = \frac{E_0 - V}{V} \times 100$$

$$= \frac{671.633 - 500}{500} \times 100 = 34.3266 \%$$

problem A 100 KVA rating, 3000V, 50Hz, 3 phase Star Connected alternator has effective armature resistance $R_a = 0.2 \Omega$. A field current 40A produces a short circuit current 200A & an O.C emf of 1040V (line value). Calculate full load percentage regulation at a power factor 0.8 lagging.

Sol Rating of alternator = 100 KVA = 100 * 1000 VA
Rated voltage (line value) = 3000V, $R_a = 0.2$, p.f. = 0.8 lag
field current $I_f = 40\text{A}$, O.C voltage $E_0 = 1040$ (line)
 $I_{sc} = 200\text{A}$.

alternator is a 3 phase star connected, so line voltages are converted into phase voltages.

$$\rightarrow \text{Rated voltage/phase} = \frac{\text{line voltage}}{\sqrt{3}} = \frac{3000}{\sqrt{3}} =$$

$$V_p = 1732.051 \text{ volts}$$

$$\rightarrow \text{open circuit voltage/phase} = \frac{V_{oc}}{\sqrt{3}} = \frac{1040}{\sqrt{3}}$$

$$V_{oc} = \frac{1040}{\sqrt{3}} = 600.44 \text{ V}$$

$$\rightarrow \text{open circuit voltage/phase} = \frac{V_{o.c}}{\sqrt{3}} = \frac{1040}{\sqrt{3}} = 600.44$$

→ synchronous impedance

$$Z_s = \frac{V_{o.c}}{I_{sc}} = \frac{600.44}{200} = 3.00 \Omega$$

$$\rightarrow Z_s = \sqrt{R_a^2 + X_s^2} \Rightarrow Z_s^2 = R_a^2 + X_s^2$$

$$X_s^2 = \sqrt{Z_s^2 - R_a^2}$$

$$X_s^2 = \sqrt{(3.00)^2 - (0.2)^2} = 2.9933 \Omega$$

$$\rightarrow \text{Rated Current } I = \frac{\text{VA Rating}}{\sqrt{3} * \text{Rated voltage}} = \frac{100 * 1000}{\sqrt{3} * 3000} = 19.245 \text{ A}$$

No load, induced emf

$$E_0 = \sqrt{(V \cos \phi + I R_a)^2 + (V \sin \phi + I X_s)^2}$$
$$= 1770.2352$$

$$\text{full load voltage regulation} = \frac{E_0 - V}{V} \times 100$$
$$= \frac{1770.23 - 1732.051}{1732.051} \times 100 = 2.205\%$$

M.M.F method or Ampere turn method

EMF method sometimes referred as pessimistic method. It gives high regulation than actual values.

→ MMF method sometimes referred as Optimistic method, also termed as ROBERT'S Ampere turn method. This method gives low regulation than actual values.

→ In emf method armature reaction effect is substituted by additional armature reactance.

→ In MMF method leakage reactance of armature is substituted by additional armature reaction effect.

Thus an MMF method requires an emf method data. MMF method involves

① No load test & ② short circuit test

↳ This is similar to o.c test which is obtained from EMF data. By drawing its open circuit characteristics.

In practical, alternator, R_a & X_L are usually small. During short circuit test, field excitation for full load current is the sum of excitation required to overcome leakage reactance drop & to overcome the

de-magnetizing effect.

During short circuit conditions P.f is almost zero. Leakage reactance drop $I X_L$ may be regarded as additional armature reaction.

Thus the field current required to develop rated voltage on no load & same field current required to ~~develop~~ circulate full load armature current during s.c test.

Let the field current develops rated voltage on no load is obtained from o.c.c as E_o & field current develops rated voltage on full load is V .

$$\% \text{ Reg} = \frac{E_o - V}{V} \times 100$$


① when load is purely inductive

Let $OA = I_{f1}$ be the field (Ampere turn) current develops rated voltage on no load.

$OB = I_{f2}$ be the field (Ampere turn) current needed to produce full load current on short circuit.

$$\text{Total field current } I_f = I_{f1} + I_{f2}$$


Armature reaction effect is purely de-magnetizing



$$OB = OA + AB$$

$$I_f = I_{f1} + I_{f2}$$

for an inductive load P.f is zero since I_a (ϕ) lags behind the voltage by 90°



$$\Rightarrow OB_1 = OA + AB_1$$

fig ① if P.f is lagging at an $(90 + \phi)$

Here field current I_{f1} (OA) is laid horizontal then field current I_{f2} (AB1) representing full load short circuit current is making at an angle $(90 + \phi)$

② when load is purely capacitive





fig ② if P.f is leading at an angle $(90 - \phi)$



$$OB_2 = OA - AB_2$$

field current (I_{f2}) required to circulate full load current is less than (I_{f1}) required to produce rated voltage

$$AB_2 < OA$$

Here armature reaction effect is purely magnetizing.

(iii) when load is purely resistive (P.f=1)





fig ③ P.f is unity for resistive load

If P.f is unity, armature reaction is purely magnetizing as a result emf gets distortional. Hence $OB_3 = OA + AB_3$

General Case

OA represents field current required to produce rated voltage V .

OC represents field current required to produce full load current on short circuit,



Vector $AB = OC$ drawn at angle $90 + \phi$ with respect to OA (if P.f is lagging).

OB is total field current, with 'O' as center and OB radius drawn an arc to x-axis at point 'P'

$$\% \text{ Reg} = \frac{E_0 - V}{V} \times 100$$

It should be noted that MMF gives regulation values less than actual values.

Problem no load excitation of alternator needed to give rated voltage is 80A. In a short circuit test, full load current flows through armature with field excitation is 50A. Calculate field excitation required to give full load current at 0.8 p.f lag Δ at rated terminal voltage.

Sol Let I_{f1} be field current of 80A generates rated voltage at no load.

$$I_{f1} = 80A$$


Let I_{f2} be the field current of 20A required to circulate full load current during short circuit $I_{f2} = 50A$ at p.f = 0.8 lag

$$\cos\phi = 0.8$$

$$\phi = \cos^{-1}(0.8) = 36.87^\circ$$

$$\sin\phi = 0.6$$

Total field current required to deliver full load current at rated voltage is $I_f = I_{f1} + I_{f2}$



$$\begin{aligned} OB^2 &= OC^2 + BC^2 \\ &= (OA^2 + AC^2) + BC^2 \end{aligned}$$

~~$$OB^2 = OA^2 + AC^2 = OA^2 + BC^2$$~~

$$= (I_{f1} + I_{f2} \sin \phi)^2 + (I_{f2} \cos \phi)^2$$

$$= (80 + 50 * 0.6)^2 + (50 * 0.8)^2 = 13700 \text{ A}$$

$$OB = I_f = \sqrt{13700} = 117.05$$

Problem

below are test results obtained on 6600V alternator

O.C voltage	3100	4900	6600	7500	8300
field current	16	25	37.5	50	70

A field current of 20A is required to circulate full load current during short circuiting the armature. calculate the MMF method, full load regulation at 0.8 p.f. lag. Neglect armature resistance & leakage reactance.


Sol

$I_{f2} = 20\text{A}$ required to circulate full load current, $\cos \phi = 0.8$.

$I_{f1} = ?$ which is obtained from O.C.C curve.

Rated voltage of alternator = 6600V

$I_{f1} = 37.5$ required to generate 6600V on no load





$$OB^2 = OC^2 + BC^2$$

$$= (OA + AC)^2 + BC^2$$

$$(I_{f1} + I_{f2} \sin \phi)^2 + (I_{f2} \cos \phi)^2$$

$$(37.5 + 20 * 0.6)^2 + (20 * 0.8)^2$$

$$I_f = \sqrt{2706.2} = 52A$$



at $I_f = 52A$ assume the no load voltage as 7600 approximately. ($E_0 = 7600$)

At $I_{f1} = 37.5A$, rated voltage is 6600

$$\% \text{ Reg} = \frac{E_0 - V}{V} * 100 = \frac{7600 - 6600}{6600} * 100 = 15.152\%$$

Unit - 1

Synchronous Reactance $\rightarrow (X_s = X_L + X_a)$

Emf setup due to armature reaction mmf is always in quadrature with load current I .

An emf induced in inductive coil & effect of armature reaction considered as equivalent to reactance drop IX_a . This reactance drop (IX_a) represents decrease in induced emf due to the effect of armature reaction.

where $X_a \rightarrow$ additional fictitious reactance added to the leakage reactance

The sum of leakage reactance X_L & a fictitious reactance (X_a) is synchronous reactance (X_s)

$$X_s = X_L + X_a$$

Effective Resistance ($R_e = R_a$)

The effective resistance of armature winding is termed as armature resistance. It is denoted as R_a/p

It is measured by applying ^{DC} voltage & measure the corresponding ^{DC} current flowing through armature winding.

Due to skin effect, effective resistance of AC is more than DC resistance.

$$R_{ac} > R_{dc}$$

Effective resistance under ac condition is varied from 1.25 to 1.75 ^{times} the dc resistance

$$R_{ac} = 1.25 \times R_{dc}$$

Unit -)

Synchronous impedance (Z_s)

If synchronous reactance is combined with armature effective resistance, the quantity is called as synchronous impedance (Z_s).

$$Z_s = R_a + jX_s$$

Alternator on Load

If field excitation of alternator is adjusted to give normal voltage on NO load then a load is connected to alternator. The terminal voltage of alternator changes with load. It is due to

(i) Voltage drop of armature effective resistance ($I R_a$)

(ii) Voltage drop of armature leakage reactance $I X_L$

(iii) Voltage drop of armature reaction.

Phasor diagrams (for loaded alternator)

Let $I R_a$ be the voltage drop of armature
 $I X_L$ be the voltage drop of leakage reactance
A Z_s be the synchronous impedance.

Phasor diagram for unity power factor

Unit - 1




fig (a) At unity power factor.

from fig (a) Here, current is in phase with voltage so phase angle b/w V & I is 0




fig (b) at lagging power factor for inductive loads

Current lags behind the voltage by 90° . so phase angle is $+90^\circ$. $P.f = 0$




fig (c) at leading power factor for capacitive loads.

EMF problem

Rating of alternator is 3.5 MVA

Connection type of alternator is star

rated voltage in line value $V = 4160$ at $f = 50\text{Hz}$

field current is 200A, required to circulate full load current on short circuit; calculate EMF method

(ii) ampere turn method having full load regulation at 0.8 p.f lag. Assume $R_a = 0$ during s.c

I_f in Amp	50	100	150	200	250	300	350	400	450
EMF in volts	1620	3150	4160	4750	5130	5370	5550	5650	5750

Sol

$$\text{Rating} = 3.5 \text{ MVA} = 3.5 \times 10^6$$

$I_f = 200\text{A}$, $V_{oc} = 4750$ in line,

rated voltage (V) = 4160 in line on full load

$$\text{p.f} = \cos \phi = 0.8, \phi = 36.52^\circ$$

$$\rightarrow V_{oc/p} = \frac{V_{oc}}{\sqrt{3}} = \frac{4750}{\sqrt{3}} = 2742.4 \text{ V}$$

rated voltage in line $V = 4160$

$$\rightarrow \text{rated voltage in phase} = \frac{V}{\sqrt{3}} = \frac{4160}{\sqrt{3}} = 2401 \text{ V}$$

$$\rightarrow Z_s = \frac{V_{oc \text{ in phase}}}{I_{sc}} = \frac{2742}{486} = 5.64 \Omega / \text{phase}$$

$$I_{sc} \text{ or Rated Current} = \frac{\text{Rating of alternator}}{\sqrt{3} \text{ Rated Voltage on F.L}}$$

$$= \frac{3.5 \times 10^6}{\sqrt{3} \times 4160} = 486 \text{ A}$$

Induced emf of alternator

$$E_o = \left[(V \cos \phi + I R_a)^2 + (V \sin \phi + I X_s)^2 \right]^{1/2}$$

$$Z_s^2 = R_a^2 + X_s^2$$

$$I_f R_a = 0$$

$$\sqrt{Z_s^2} = X_s$$

$$X_s = Z_s = 5.64 \Omega / p$$

$$\cos \phi = 0.8, \sin \phi = 0.6$$



$$E_o = \left[(2401 * 0.8 + 486 * 0)^2 + (2401 * 0.6 + 486 * 5.64)^2 \right]^{1/2}$$


$$= 4600$$

$$\% \text{ reg up} = \frac{E_o - V}{V} * 100 = \frac{4600 - 2401}{2401} * 100 = 91.58$$

data in

(ii) from table in problem $I_{f2} = 200 \text{ A}$ required to circulate full load current have rated voltage is 4750.

The normal voltage is 4160 at $I_{f1} = 150$



$$90 + \phi = 90 + 36.52 = 126.52$$

$$OB^2 = \left[OA^2 + AB^2 + 2(OA)(AB) \cos(180^\circ - 126.5) \right]^{1/2}$$

$$= \left[(I_{f1})^2 + (I_{f2})^2 + 2(I_{f1})(I_{f2}) \cos(53.5) \right]^{1/2}$$

$$OB = I_f = 313.35 \text{ A}$$

ZPF-method or Potier method

EMF & MMF method gives regulation values higher & lower than actual values.

ZPF method gives approximate values very near to actual values.

In synchronous impedance method, armature reaction effect is substituted by an additional fictitious reactance (X_a).

In MMF method, armature leakage reactance (X_L) is substituted by an additional reaction.

Due to above armature reactions effect enormous errors occur.

ZPF method is based on separating ($I X_L$) armature leakage reactance drop & effect of armature reaction.

This method uses first ~~two~~ 2 methods. Also it requires (i) no load curve (ii) full load ZPF curve. Reduction in voltage due to armature reactance is potier reactance.


** ZPF lagging curve is obtained as ***

→ allow the alternator to run at constant speed.

→ Connect the alternator terminals with pure inductive loads.

→ Increase field current (I_f) until the generator supplies full load ^{current} at ZPF at rated voltage.

→ first draw the O.C.C Curve obtained from emf method



→ plot the ZPF Curve (OM = field current required to deliver full load current at ZPF at rated voltage. BM = rated voltage at ZPF Curve)

→ A horizontal BD is drawn such that

$$BD = OA$$

where OA = I_f required to circulate full load current during S.C test

→ Draw Tangent OT from origin on O.C.C Curve. OT is air line

→ At point D, draw a line DC parallel to air line & this line intersect O.C.C Curve as point 'C'.

→ Join BC line from point 'C' on O.C.C to the point 'B' on ZPF Curve

→ Draw CP line perpendicular to line DB.

Triangle COB is termed as potier triangle

→ line CP is ~~the~~ voltage drop due to armature leakage reactance. $I_X L$.

(armature reaction)

→ PB gives I_f required to overcome the demagnetizing effect of armature at full load.

→ DP balancing the armature leakage reactance drop C_P .

We have $C_N = E$ rated voltage on F.L
by considering the drop $I X_L$

$$\cancel{C_N} \quad C_N = C_P + P_N$$

$$\text{But } P_N = B_M = C_P + B_M$$

$$C_N = C_P + B_M$$

$$E = I X_L + V$$

$$E = V + I X_L$$

To determine E_0 at no load induced emf

I_f required to generate voltage on NO load is $E_0 = I_f$ required to generate voltage on Full load E & I_f required to overcome armature reaction is V .

$$\cancel{I_f} = E$$

$$E_0 = E + V$$

ON → field current required to generate voltage E on O.C.C Curve during no load

→ At point (N)

NS = BP is laid at angle $90 + \phi$ with respect to ON then joined OS.

→ With O as center with radius as OS draw an arc to meet x-axis at point (K).

OK = resultant field current.

→ ~~Join KL~~ Draw a vertical line from point (K) it touches the o.c.c at point L.

$LK = E_0$





fig shows ZPF Curves

The phasor diagram of loaded alternator is shown



V = rated voltage on ZPF curve

I = full load current

P.f = $\cos \phi$

$$E_0 = E + IX_a$$

$$E = V + IR_a + IX_L$$

$$E^2 = (V + IX_L \sin \phi)^2 + (IX_L \cos \phi)^2$$


Problem

A 3 phase star connected alternator has 2.5 MVA rating gives 6.6 kV. The following data for o.c.c is

I_f (A)	16	20	25	32	45
Voltage terminal	4400	5500	6600	7700	8800

With armature short circuited, a full load current flowing, field current is 18A. when 3 machine is supplying full load current at ZPF at rated voltage, the field current is 45A.

Also a ZPF initial voltage 0 at $I_f = 18A$
 ZPF final voltage 3811V at $I_f = 45A$ during s.c test on full load test, Find (i) leakage reactance per phase (ii) full load armature reaction in terms of equivalent field current (iii) full load voltage regulation at 0.8 p.f lag, neglect R_a



CP drawn perpendicular to DB

DC drawn parallel to OT

$$CP = I X_L$$

given data alternator is 3 phase star connected

we have $V_p = V_L / \sqrt{3}$ Rating of alternator = 6.6 kV

$I_f =$	16	20	25	32	45
$V_p =$	$\frac{4400}{\sqrt{3}}$	$\frac{5500}{\sqrt{3}}$	$\frac{6600}{\sqrt{3}}$	$\frac{7700}{\sqrt{3}}$	$\frac{8800}{\sqrt{3}}$
	2540	3175	3811	4446	5081

2.5 MVA

Rated voltage of alternator $V = 6.6 \times 1000$

→ Rated Current $I = \frac{\text{Rating of alternator}}{\sqrt{3} \times V_{\text{rated}}}$

$$I = \frac{2.5 \times 10^6}{\sqrt{3} \times 6.6 \times 1000} = 218.69A$$

→ $CP = I \times X_L$

Let $CP = 462$ from measurement

$$(i) X_L = \frac{462}{218.69} = 2.113 \Omega$$

$CP = \text{rated voltage on o.c.c} - \text{rated voltage on ZPF curve}$

$$I X_L = E - V = 462V$$

(ii) BP \rightarrow field current required to overcome the armature reaction.

BP \rightarrow ON - NM = 15 A by measurement

(iii) To find E_0

we have $CP = IX_L = E - V$

$$IX_L = E - V$$

$$E = V + IX_L$$

given P.f = 0.8 lag


$$\cos \phi = 0.8, \quad \phi = 36.86^\circ, \quad \sin \phi = 0.6$$

CP = $IX_L = 462V$ from phasor diagram

Rated voltage on ZPF Curve = 3811

$$E = \sqrt{(V + IX_L \sin \phi)^2 + (IX_L \cos \phi)^2}$$

$$E = \sqrt{(V \cos \phi + IR_a)^2 + (V \sin \phi + IX_L)^2}$$



$$E^2 = (3811 + 462 * 0.6)^2 + (462 * 0.8)^2$$

$$E = 4104.873V$$

$I_f = 28A$ is required to generate

$$\begin{aligned} \text{Total field current} &= OS \text{ or } OK = (28 + 15) \\ &= 43A \end{aligned}$$

$$E_0 = 4965$$

$$\% \text{ Regulation} = \frac{E_0 - V}{V} * 100$$

$$= \frac{4965 - 3811}{3811} * 100 = 30.28\%$$


ASA-method → American standard Association

It is an improved one of MMF method.
This method is more suitable for salient & non-salient

In MMF total field current (I_f) required to generate voltage (E_o) on no load is obtained by adding field currents I_{f1} & I_{f2} .

I_{f1} → field current required to generate rated voltage on no load

I_{f2} → field current required to overcome armature reaction



$\phi = \text{lagging}$

$\cos \phi = \text{p.f.}$

The value of I_f is somewhat smaller than actual value of I_f required to generate E_o . This is due to the generated poles are unsaturated magnetically.

To get same amount of magnetic flux we need to increase the field excitation as a result poles becomes partially saturated.

This method calculates the additional field current required to saturate the generator poles.


Let $I =$ Rated & full load current

$V =$ Rated voltage

$R_a =$ armature resistance

$X_L =$ armature leakage reactance

phasor diagram




from phasor diagram $\phi =$ Load angle,

$$E_1 = V + IR_a + IX_L$$

IX_L drop is considered in ZPF method

→ Plot O.C.C Curve from no load & O.C test



$$OP = E_1$$

$$MN = I_{f2}$$

$$OM = I_{f1}$$

$$ON = I_f = OM + MN = I_{f1} + I_{f2}$$

$$NG = QR$$

$$OK = E_0$$

from origin 'O', draw a tangent passing through the surface of O.C.C Curve.

Let P be the point marked on Y-axis (Voltage) such $OP = E_1$.

Extend a line from point P to O.C.C Curve. Line intersect OT lines as 'Q' & intersects on O.C.C as 'R'.

→ length of RS indicates additional field current required to saturate poles of generator.

$$\% \text{ Reg} = \frac{E_0 - V}{V} * 100$$

Blondel's 2 reaction theory. (X_d & X_q)

Synchronous machine with non-salient pole (cylindrical rotor) has uniform air gap, hence reluctance of air gap is constant throughout.

But in salient pole & projecting poles has non-uniform air gap, hence reluctance of the air gap is not constant.


Non salient pole machine possess only one axis either direct & pole axis.

But a salient pole machine has 2 axis

- (i) field axis called direct axis (d-axis)
- (ii) axis passing through the centre of pole called quadrature & q-axis.

A salient pole with d-axis possess 2 mmf (i) field mmf & (ii) armature mmf.

Whereas q-axis possess only one mmf i.e. armature mmf on q-axis. Due to this reluctance is low along the pole & highly between the poles.



According to Blondel 2 reaction theory

① Armature Current is resolved into 2 components

I_d perpendicular to E_0

I_q along with E_0

(ii) for non salient pole alternator

$$X_d = X_q$$

for salient pole alternator

$$X_d > X_q$$

X_q ranges from 60-70% of X_d .




fig ① shows phasor diagram

$V \rightarrow$ Rated voltage

$I_a \rightarrow$ armature Current

I_d & I_q Components of I_a

$$\begin{aligned} \text{we have } I_d &= I_a \cos(90^\circ - \psi) \\ &= I_a \sin(\psi) \end{aligned}$$

$$I_q = I_a \cos \psi \quad (\psi = \delta + \theta)$$

→ Voltage drop $I_a R_a$ is parallel to I_a

→ Voltage drops $I_d X_d$ & $I_q X_q$ are perpendicular to current phasors I_d & I_q .

Voltage drops $I_a R_a$, $I_d X_d$, $I_q X_q$ are vectorially added. The resultant is E_0 .

from fig ①

$$E_0 = V + I_a R_a + I_d X_d + I_q X_q$$

In above equation, E_0 , V , I_a & R_a are known values. X_d & X_q values are getting from slip test.


Also Current Components I_d & I_q , angles ψ & δ are not known. These are calculated

from

$\triangle ODC$

$$\tan \psi = \frac{AD + AC}{OE + ED} = \frac{V \sin \phi + I_a X_q}{V \cos \phi + I_a R_a} \text{ generating action}$$

$$\text{for motoring action } \tan \psi = \frac{AD - AC}{AD - ED} = \frac{V \sin \phi - I_a X_q}{V \sin \phi - I_a R_a}$$



$\triangle ABC$


$$\frac{BC}{AC} = \cos \psi$$

$$AC = \frac{BC}{\cos \psi} = \frac{I_q X_q}{\cos \psi}$$

$$I_a X_q = \frac{I_q X_q}{\cos \psi}$$

Dotted line AC has drawn perpendicular to I_a
 Δ BC is drawn perpendicular to E_o .

$\angle ACB$ is ψ .



Now $I_d = I_a \sin \psi$

$I_q = I_a \cos \psi$

$$I_a = \frac{I_q}{\cos \psi} \Rightarrow \cos \psi = \frac{I_q}{I_a}$$

in ΔABC

$$\frac{BC}{AC} = \cos \psi \Rightarrow AC = \frac{BC}{\cos \psi}$$

$$\frac{I_q X_q}{\cos \psi} = I_a X_q$$

From ΔODC .

$$\tan \psi = \frac{AD + AC}{OE + ED} = \frac{V \sin \phi + I_a X_q}{V \cos \phi + I_a R_a}$$

$\delta = \psi - \phi$

for generating action

for motoring action ($\delta = \phi - \psi$)

$$\tan \psi = \frac{V \sin \phi - I_a X_q}{V \sin \phi - I_a R_a} = \frac{AD - AC}{AD - EO}$$

Excitation voltage is given as

$E_o = V \cos \delta + I_q R_a + I_d X_d \rightarrow$ for generator

for motoring

$$E_0 = V \cos \delta - I_q R_a - I_d X_q$$

If we neglect armature resistance

$$\psi = \phi + \delta \quad \text{generating}$$

$$\psi = \phi - \delta \quad \text{motoring}$$

$$\psi = \phi \pm \delta$$

$$I_d = I_a \sin \psi = I_a \sin(\phi \pm \delta)$$

$$I_q = I_a \cos \psi = I_a \cos(\phi \pm \delta)$$

$$V \sin \delta = I_q X_q = I_a X_q \cos(\psi)$$

$$V \sin \delta = I_a X_q \cos(\phi \pm \delta)$$

$$= I_a X_q [\cos \phi \cos \delta \pm \sin \phi \sin \delta]$$

$$V = I_a X_q [\cos \phi \cot \delta \pm \sin \phi]$$

$$V = I_a X_q \cos \phi \cot \delta \pm I_a X_q \sin \phi$$

$$I_a X_q \cos \phi \cot \delta = V \pm I_a X_q \sin \phi$$

$$\cot \delta = \frac{V \pm I_a X_q \sin \phi}{I_a X_q \cos \phi}$$

$$\tan \delta = \frac{I_a X_q \cos \phi}{V \pm I_a X_q \sin \phi}$$

If R_a is neglected in excitation voltage

$$E_0 = V \cos \delta \pm I_d X_d$$

Determination of X_d & X_q by slip test




fig (a) shows experimental set up for salient pole machine.

→ Bring the alternator to near the synchronous speed. The rotor speed is less or more than synchronous speed.

→ Keep the field winding is open circuited.

→ Apply a small voltage to the stator terminals using 3 phase variac.

→ stator windings carry 3 phase currents, a rotating magnetic field develops which is revolving in stator at synchronous speed.

→ Because of difference in rotor field speed & stator field speed (slip) an emf is induced in field winding of alternator.

→ As stator flux revolves, stator MMF aligns with field poles (direct axis), the reactance offered is X_d .

Stator MMF aligns with quadrature axis, the reactance offered is X_q .

→ This test is conducting of salient pole machine as a resultant length of airgap is not constant

as a result magnetic reluctance is low therefore reactance X_d & X_q are unequal.

→ Because of unequal X_d & X_q current drawn from the supply tends to oscillate between a maximum value & minimum value.

→ when current is at minimum value, the reactance offered is X_d but voltage is maximum

when current is at maximum value, the reactance offered is X_q but voltage is minimum.

→ Due to minimum & maximum values of reactance, the voltage drop of armature also varies.

$$X_d = \frac{\text{Maximum Voltage/phase}}{\text{Minimum Current}}$$

$$X_q = \frac{\text{Minimum Voltage/phase}}{\text{Maximum Current}}$$

Problem A 1000 KVA, 6600 V, star connected synchronous generator has an $R_a = 0.5 \Omega$, direct axis reactance $X_d = 8 \Omega$, & quadrature reactance X_q is 5Ω . It supplies rated voltage at 0.8 p.f lag. Calculate its no load induced emf.

Sol

Rating of alternator = 1000 * 1000 VA

Rated Voltage $V = 6600$

$$V/p = \frac{6600}{\sqrt{3}} = 3810.51 \text{ Volts}$$

$R_a = 0.5$, $X_d = 8 \Omega$, $X_q = 5 \Omega$, p.f = 0.8 lag

$$\rightarrow \text{full load current} = \frac{\text{Rated VA}}{\sqrt{3} * \text{Rated Voltage}}$$

$$I = \frac{1000 * 1000}{\sqrt{3} * 6600} = 87.48 \text{ A}$$

$$I_a = I = I_{sc} = 87.48 \text{ A}$$

$$\rightarrow \tan \psi = \frac{V \sin \phi + I_a X_q}{V \cos \phi + I_a R_a}$$

$$\tan \psi = \frac{3810.5 * 0.6 + (87.48 * 5)}{3810.5 * 0.8 + (87.48 * 0.5)} = 0.881$$

$$\psi = \tan^{-1}(0.881) = 41.375^\circ$$

$$\text{given } \phi = \cos^{-1}(0.8) = 36.869^\circ$$

$$\rightarrow \boxed{\psi = \Delta + \phi}$$

$$\Delta = \psi - \phi$$

$$\Delta = 41.375 - 36.869 = 4.506^\circ$$

we have

$$\rightarrow \boxed{I_d = I_a \sin \psi} = 87.48 * \sin(41.375) = 57.823 \text{ A}$$

$$\rightarrow \boxed{I_q = I_a \cos \psi} = 87.48 * \cos(41.375) = 65.645 \text{ A}$$

\rightarrow no load induced emf

$$\boxed{E_o = V \cos \Delta + I_q R_a + I_d X_d}$$

$$= 3810.5 * \cos(4.506) + (65.645 * 0.5) + (57.823 * 8)$$

$$E_o = 4294.14 \text{ V}$$

$$\% \text{ Regulation} = \frac{E_0 - V}{V} \times 100$$

$$= \frac{4294 \cdot 141 - 3810 \cdot 512}{3810 \cdot 512} \times 100 = 12 \cdot 692$$

ZPF Problem

Rating of alternator 30KVA Connected in star.
The following are O.C, & full load ZPF data
age, Rated voltage in line $V = 400$, 3 phase

Exciting Current (I_f)	6	8	12	18	24	28	
Open circuit emf in line	282	-	400	435	459	474	
ZPF in line volts	-	0	-	-	-	400	

Find armature reaction in Ampere turns & armature leakage reactance. Determine voltage regulation at full load 0.8 p.f., neglect R_a

Sol Rating = 30×1000 VA, Line voltage $V = 400$


$$\text{Rated voltage/p} = \frac{400}{\sqrt{3}} = 230 \cdot 94 \text{ V}$$

I_f in Amp	6	8	12	18	24	28	
O.C voltage in phase	$\frac{282}{\sqrt{3}}$	-	$\frac{400}{\sqrt{3}}$	$\frac{435}{\sqrt{3}}$	$\frac{459}{\sqrt{3}}$	$\frac{474}{\sqrt{3}}$	
	162.8		230.94	251.15	265	273.66	

At $I_f = 8$, ZPF voltage = 0

At $I_f = 28$, ZPF voltage = 400

draw ZPF Curves



Point A = (8A, 0V)

Point B = (28A, $400/\sqrt{3} = 230.94$ V)

BD = OA = 8A field Current

→ CD is drawn parallel to OT to cut on OCC at point C.

→ CP is drawn perpendicular DB.

$$CP = I X_L$$

$$\rightarrow I = \frac{30 \times 1000}{\sqrt{3} \times 400} = 43.3 \text{ A}$$

$$CP = 43.3 \times X_L$$

$$X_L = \frac{CP}{43.3}$$

CP = 32.5 (its a actual measured value)

$$X_L = \frac{32.5}{43.3} = 0.751 \Omega$$

BP = 7A by actual measurement

↳ I_f required to overcome armature reaction.


To find E_0

$$E = V + IX_L$$

$$p.f = \cos\phi = 0.8$$

$$\phi = \cos^{-1}(0.8) = 36.87^\circ$$

$$\sin\phi = 0.6$$



from phasor diagram

$$E = \left[(V + IX_L \sin\phi)^2 + (IX_L \cos\phi)^2 \right]^{1/2}$$

$$= \left[(230.94 + 43.3 * 0.751 * 0.6)^2 + (43.3 * 0.751 * 0.8)^2 \right]^{1/2}$$

$$= \sqrt{63396.2} = 251.787 \text{ V}$$

from O.C.C, field excitation required to generate voltage 251.787 on no load is 15.5A from measurement.

$$I_{f1} = 15.5 \text{ A}$$

Also $I_{f2} = 7 \text{ A}$ at N .

Total field current required to generate voltage

$$E_0 = \text{(ON)} \text{ (OA)}$$

$$I_f = I_{f1} + I_{f2}$$

$$= 15.5 + 7A = 22.5A$$

(OK)

$I_f = 20.5A$ by actual measurement OK

- $ON = 15.5A$, at point N, mark 126.87° angle.
- $NS = 7A = OA$ is drawn.
- Joined OS.
- With O as centre & radius as OS, draw an arc. Cut at x-axis at a point 'K'.
- Extend the vertical line from point 'K' to the curve O.C.C intersect at a point 'L'.
- Joined LK.

Corresponding to $I_f = 20.5A$ (OK line)

Corresponding voltage on O.C.C is $E_0 = 270$


$$\% \text{ Reg} = \frac{E_0 - V}{V} \times 100 = \frac{270 - 230.94}{230.94} \times 100 = 16.91\%$$

MMF method is used to compute voltage
regulation

- (i) Draw the O.C.C graph i.e. I_f Vs E_0 .
The data is obtained from O.C test.
- (ii) $OM = I_{f2}$ field current required to circulate full load current during short circuit test
- (iii) Let V be rated voltage per phase of alternator marked on O.C.C curve. Example is
 $V_p = 415/\sqrt{3} = 239.4$

Corresponding rated voltage per phase marks the field current as A

Q



OA = I_{fr} , field required to generate rated voltage per phase (V) on no load curve

→ (IV) Assume the load P.f is lagging

$$\theta = 90 + \theta$$

→ (V) At point 'A' with an angle $90 + \theta$ mark an angle.

Extended the line from point A to B. length of line AB = OM line.

→ (VI) Joined O & B, with length OB, with 'O' as Centre draw an arc to cut at a point x-axis is marked as

→ (VII) Extend the line from point (P) to O.C.C Curve as point P'

OP = I_f is the total field required to generate no load voltage E_0

Calculate percentage regulation

$$\% \text{ Reg} = \frac{E_0 - V}{V} * 100$$

$E_0 = I_f$ field current required to generate no load voltage on o.c.c curve [o.c test]

$V = I_{f1}$ field current required to generate rated voltage on o.c.c curve [o.c test]

Unit - III

Parallel Operation of Alternators

Synchronisation of alternators

As load demand is within limit of alternator o/p, no problems is raised. However when the load demand is in excess, a single alternator cannot meet the load, so the necessary arises more number of generators.

Several alternators are employed it shares a common load. when alternators are connected in parallel. First keep the alternators in parallel & they made to share a common load.

The process of bringing 2 or more alternators to share a common load when operating in parallel with bus bars is termed as synchronisation

parallel operation advantages

① Continuity of power supply


single alternator cannot be guaranteed to provide continue power supply during fault conditions. This would completely interrupt the supply.

② Efficiency of operation

2

Efficiency of alternator increases with

O/P.



Efficiency of alternator is maximum when supplying full or near full load.

Ex: A 10KVA alternator supplies 6KVA load its efficiency is very low.

using single alternator use 2 smaller units operating in parallel can share 3KVA & 3KVA equally.

- ③ smaller units running in parallel is more economically than single unit
- ④ Adding another unit to existing alternators in parallel provides future expansion.

Conditions required for parallel operations

① for single phase alternators

① terminal voltages of all generators must be similar

② frequencies of induced emf of all generators must be equal it is depending on the speed of prime movers.

③ Induced emf's E_1 & E_2 are in direct opposition to the local circuit but E_1 & E_2 are in phase with the external circuit.




fig ① shows due to their unequal frequencies flicker will takes place in L_1 & L_2




fig ② shows lamps flicker glow & dark during the phase differences in E_1 & E_2 .

Lamps glow brighter if E_1 & E_2 are in phase with bus bar voltage


Lamps will dark if E_1 & E_2 are in phase opposition to bus bar voltage.

Synchronising is done at middle of any one of either dark or brighter lamp period.

(b) For 3 phase alternator.

3

- (i) Terminal voltages of all generators must be equal.
- (ii) frequencies of generated emf's of all generators must be equal.
- (iii) phase sequence must be proper.
means similar phases must be joined



Methods of synchronising alternators

If a new alternator is added to the existing alternator in parallel, the following practical methods are adopted for synchronising


- (i) Dark lamp method
- (ii) Bright lamp method
- (iii) Synchroscope method.

(i) Dark lamp method

Assume that alternator 1 is already connected to bus bar & alternator 2 is to be ready to synchronised.

→ Initially alternator 2 synchronising switch kept open.

→ Bring the alternator 2 at rated speed & rated voltage. The generated emf of alternator 2 becomes equal to bus bar voltage, indicated by voltmeter



→ If phase sequence of alternator voltages is same as that of bus bar voltages.

→ All lamps brighter at a time & dark out at a time.

If phase sequence is not proper, lamps go bright one after another & dark one after another. During this case, interchange any 2 terminals of the alternator.

→ Flickering of lamps takes place during phase sequences are correctly matched to the bus bar voltages. Flickering in lamps indicates the differences in frequencies of alternator & bus bar voltage. Reduce the speed of flickering by adjusting the speed of alternator.

All lamps go dark, switch 's' closed.
Now 2nd alternator put in parallel with bus bar. They can share a common load.

This method of synchronising is termed as dark lamp method.

(ii) Bright lamp method

Here the set up is practically same as that of dark lamp method. Except L_2 & L_3 are ~~not~~ interchanged.


If phase sequences of alternator & bus bar voltages are similar, L_1 , L_2 & L_3 lamps in that L_1 goes dark, lamps L_2 & L_3 gets bright.

If frequencies are exactly same, lamp L_1 remain dark & lamps L_2 & L_3 remains bright. If L_2 & L_3 are bright & L_1 dark switch s is closed. This method is called bright lamp method.

(iii) Synchroscope method

A synchronising switch 's' should be closed during the dark lamp method or bright lamp method. This is done if phase voltages & frequencies are exactly equal to bus bar voltages.

Here we cannot justify all lamps are go bright or dark exactly. This is overcome by using synchroscope method.



Here a pointer is used to estimate the difference in the frequencies.

If incoming alternator is slow, pointer moves anticlockwise.

If incoming alternator is fast, pointer moves clockwise.

If frequencies are exactly, the pointer becomes stable at the center.

$$f = \frac{NP}{120} \quad N \text{ is speed of alternator}$$

The pointer remains in steady state in 12 '0' clock position /

power flow equations in alternators
power flow equation in non salient pole

Consider a 3 phase cylindrical rotor

Let V = terminal voltage

I = terminal or armature current } per phase

output power = VI

3 phase output power = $3VI$


Let P = real or true power

Q = Reactive Power

∴ Complex power of 3 phase alternator

$$S = P + jQ = 3VI^*$$

↓ Real ↘ Reactive



$$X_s = X_a + X_L$$

Δ = power angle or load angle

ϕ = p.f or phase angle

$$E_0 = V + IR_a + IX_a + IX_L$$

$$= V + IR_a + IX_s$$

$$= V + IR_a + jIX_s$$

$$Z_s = R_a + jX_s$$

$$E_0 = V + I(R_a + jX_s)$$

$$= V + IZ_s$$

→ let take (V) as reference phasor

$$V = VL \angle 0^\circ$$

$$I = \frac{E_0 \angle \Delta - VL \angle 0^\circ}{Z_s \angle \phi_s} \Rightarrow I = \frac{E_0 \angle \Delta}{Z_s \angle \phi_s} - \frac{VL \angle 0^\circ}{Z_s \angle \phi_s}$$

$$\phi_s = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$

$$I = \frac{E_0 \angle (\Delta - \phi_s) - VL \angle (0^\circ - \phi_s)}{Z_s}$$

Current Conjugate

$$I^* = \frac{E_0 L (\phi_s - \delta) - VL \phi_s}{Z_s}$$

$$\text{Power} = 3VI^* , \quad S = P + jQ$$

$$= \frac{3V}{Z_s} [E_0 L (\phi_s - \delta) - VL \phi_s]$$

$$I^* = \frac{3V}{Z_s} \left[E_0 \left\{ \cos(\phi_s - \delta) + j \sin(\phi_s - \delta) \right\} - V \left\{ \cos \phi_s + j \sin \phi_s \right\} \right]$$

Real power $P =$ Real part of S

$$P = \frac{3V}{Z_s} [E_0 \cos(\phi_s - \delta) - V \cos \phi_s]$$

$$P = \frac{3VE_0 \cos(\phi_s - \delta)}{Z_s} - \frac{3V^2 \cos \phi_s}{Z_s}$$

Reactive power $Q =$ imaginary part of S

$$Q = \frac{3V}{Z_s} [E_0 \sin(\phi_s - \delta) - V \sin \phi_s]$$

$$Q = \frac{3VE_0 \sin(\phi_s - \delta)}{Z_s} - \frac{3V^2 \sin \phi_s}{Z_s}$$

Substitute $X_s = Z_s$ since R_a is small
Practically its value $R_a = 0$. $\phi_s = 90^\circ$

$$\sin \phi_s = \sin(90) = 1$$

$$\text{Also } \cos(\phi_s - \delta) = \cos(90 - \delta) = \sin \delta$$

$$\cos \phi_s = \cos(90) = 0 \quad \text{we get}$$

$$P = \frac{3VE_0 \cos(90 - \delta)}{Z_s} - \frac{3V^2 \cos(90)}{Z_s}$$

$$P = \frac{3VE_0 \sin \delta}{Z_s} - 0 \Rightarrow P = \frac{3VE_0 \sin \delta}{X_s}$$

$$\text{similarly } \sin(\phi_s - \delta) = \sin(90 - \delta) = \cos \delta$$


$$\sin \phi_s = \sin 90 = 1$$

$$Q = \frac{3VE_0 \sin(90 - \delta)}{Z_s} - \frac{3V^2 \sin 90}{Z_s}$$

$$Q = \frac{3VE_0 \cos \delta}{Z_s} - \frac{3V^2}{Z_s} = \frac{3VE_0 \cos \delta}{X_s} - \frac{3V^2}{X_s}$$

\Rightarrow for P, if V, E_0 & X_s are constant we have

$P \propto \sin \delta$, where $\delta =$ load angle or power angle



with increase in load (δ), power also increases. P becomes maximum at $\delta = 90^\circ$ & P becomes zero at $\delta = 180^\circ$

$$\frac{dp}{d\delta} = 0$$

$$P = \frac{3VE_0}{X_s} \sin\delta$$

$$\therefore \frac{dp}{d\delta} = \frac{3VE_0}{X_s} \cos\delta$$

$$\frac{dp}{d\delta} = 0 \quad \text{if } \delta = 90$$

$$\cos\delta = \cos 90 = 0$$

consider Ra we have

$$P = \frac{3VE_0}{Z_s} \cos(\phi_s - \delta) - \frac{3V^2}{Z_s} \cos\phi_s$$

$$\frac{dp}{d\delta} = \frac{3VE_0}{Z_s} \sin(\delta - \phi_s) = 0$$

$$\sin(\delta - \phi_s) = 0$$

$$\delta = \phi_s$$

o/p power is maximum when $\delta = \phi_s$

To find the maximum o/p power


$$P = \frac{3VE_0}{Z_s} \cos(\phi_s - \delta) - \frac{3V^2}{Z_s} \cos\phi_s$$

if $\delta = \phi_s$ then P becomes

$$P = \frac{3VE_0}{Z_s} \cos(\phi_s - \phi_s) - \frac{3V^2}{Z_s} \cos\phi_s$$

$$= \frac{3V_0 E_0}{Z_s} (1) - \frac{3V^2}{Z_s} \cos\phi_s$$

$$\cos \phi_s = \frac{R_a}{Z_s}$$



$$P = \frac{3VE_0}{Z_s} - \frac{3V^2}{Z_s} \left(\frac{R_a}{Z_s} \right)$$

$$P = \frac{3VE_0}{Z_s} - \frac{3V^2 R_a}{Z_s^2} = P_{max}$$

$$\cos \phi_s = \frac{R_a}{Z_s}$$

$$\sin \phi_s = \frac{X_s}{Z_s}$$

Reactive power o/p is given as

we have Reactive power with R_a

$$Q = \frac{3VE_0}{Z_s} \sin(\phi_s - \Delta) - \frac{3V^2}{Z_s} \sin \phi_s \rightarrow \textcircled{1}$$

$$Q = -\frac{3V^2}{Z_s} \sin \phi_s \quad \text{Now} \quad \sin \phi_s = \frac{X_s}{Z_s}$$

$$Q = -\frac{3V^2}{Z_s} * \frac{X_s}{Z_s} = -\frac{3V^2 X_s}{Z_s^2}$$

$$\frac{dQ}{d\Delta} = 0$$

$$\frac{dQ}{d\Delta} = \frac{3VE_0}{Z_s} \cos(\phi_s - \Delta) \checkmark$$

$$\cos(\phi_s - \Delta) = 0$$

$$\cos 90 = 0$$

$$\phi_s - \Delta = \pm 90^\circ \quad \text{or} \quad \Delta = \phi_s \pm 90^\circ$$

$$Q_{max} = -\frac{3VE_0}{Z_s} - \frac{3V^2 X_s}{Z_s^2}$$

$$\theta_s = \phi_s + 90$$

$$\text{if } \Delta = \phi_s + 90$$


$$\sin(\phi_s - \phi_s - 90)$$

$$\therefore \sin(-90) = -1$$

(b) Power flow in salient pole alternator

for cylindrical or non-salient pole alternator
 real power $P = \frac{3VE_0 \sin \delta}{X_s}$

In case of salient pole motors X_d & X_q are unequal because of non uniform air gap.



consider a salient pole alternator connected to infinite bus bar.


let $V =$ Bus bar voltage

$V_t =$ terminal voltage of the alternator

$E_0 =$ No load induced emf

$X =$ reactance of line

let X_d & X_q are direct & quadrature reactances



phasor diagram

$$I = I_d + I_q$$

$$V_t = V + I_d X + I_q x, \quad E_0 = V_t + I_d X_d + I_q X_q$$

$I_d X_d$ & $I_q X_q$ are drawn leading I_d by 90°
 similarly $I_q X_d$ & $I_d X_q$ are drawn leading I_q by 90° .

$\delta =$ load angle or power angle


Let $X_d = x_d + x$, $X_q = x_q + x$

$I_d X_d$ & $I_d X_q$ voltage drop combined to give $I_d X_d$.

$I_q X_d$ & $I_q X_q$ are voltage drop combined to give $I_q X_q$

$$I_d = \frac{E_0 - V \cos \delta}{X_d} \rightarrow \textcircled{1}$$

$(E_0 = V \cos \delta + I_d X_d)$ $OC = OD + DC$



$OD = V \cos \delta$
$BC = AD = I_q X_q$

$OD = V \cos \delta$

$AD = BC = V \sin \delta = I_q X_q$

$$I_q = \frac{V \sin \delta}{X_q} \rightarrow \textcircled{2}$$

Here $V \cos \delta$ is in phase with I_q
 $V \sin \delta$ " " " with I_d

$$P = 3 \left[I_d V \sin \delta + I_q V \cos \delta \right] \rightarrow \textcircled{a}$$

$$\text{Now } I_d = \frac{E_0 - V \cos \delta}{X_d}, \quad I_q = \frac{V \sin \delta}{X_q}$$

substitute I_d & I_q in equation \textcircled{a} we get

$$P = 3V \left[\frac{E_0 - V \cos \delta}{X_d} \sin \delta \right] + 3V \left[\frac{V \sin \delta}{X_q} \cos \delta \right]$$

$$= \frac{3VE_0 \sin \delta}{X_d} - \frac{3V^2 \cos \delta \sin \delta}{X_d} + \frac{3V^2 \sin \delta \cos \delta}{X_q}$$

$$= \frac{3VE_0 \sin \delta}{X_d} - \frac{3V^2 \frac{\sin 2\delta}{2}}{X_d} + \frac{3V^2 \frac{\sin 2\delta}{2}}{X_q}$$

$$= \frac{3VE_0 \sin \delta}{X_d} + 3V^2 \frac{\sin 2\delta}{2} \left[\frac{1}{X_q} - \frac{1}{X_d} \right]$$

$$= \frac{3VE_0 \sin \delta}{X_d} + 3V^2 \frac{\sin 2\delta}{2} \left[\frac{X_d - X_q}{X_d X_q} \right]$$

$$P = \frac{3VE_0 \sin \delta}{X_d} + 3V^2 \frac{\sin 2\delta}{2} \left[\frac{X_d - X_q}{2 X_d X_q} \right]$$

first term $\frac{3VE_0 \sin \delta}{X_s}$ is same as that of salient pole. only X_s is replaced by X_d

$$\frac{3VE_0 \sin \delta}{X_d}$$

2nd term in above equation is termed as reluctance power.

We have Torque, $T = \frac{P * 60}{2\pi N}$ in Nm

Torque developed by salient pole motor is

$$T = \frac{3VE_0 * 60}{2\pi N_s X_d} \sin\delta + \frac{3V^2 (X_d - X_q) * 60}{2\pi N_s (2X_d X_q)} \sin 2\delta$$

in Nm-meters.

Problem

A 2500 kVA, 8 pole alternator runs at 750 rpm on 6.6 kV bus bars. If synchronous reactance is 20%, determine the synchronising power for 1° mechanical degree of displacement. Also calculate corresponding synchronising torque.

Sol Rating of alternator = 2500 * 1000 VA

Rated voltage 6.6 kV in line

Poles = 8, $N_s = 750$ rpm, $X_s = 20\%$.

→ Rated Voltage/phase = $\frac{V_L}{\sqrt{3}} = \frac{6600}{\sqrt{3}} = 3810.5$ V

→ full load current or rated current = $\frac{\text{rating of alternator}}{\sqrt{3} * \text{rated voltage}}$

$$I = \frac{2500 * 100}{\sqrt{3} * 6600} = 218.6933$$

→ Synchronous reactance drop = 20% = of $\frac{\text{Rated voltage}}{\text{phase}}$

$$IX_s = \frac{3810.5}{218.6933} * 0.2 = 762.1$$

→ Synchronous reactance drop / phase

$$X_s = \frac{IX_s}{\text{rated voltage/p}} = \frac{762.1}{\text{rated voltage/p}}$$

$$IX_s = 762.1$$

$$X_s = \frac{762.1}{I} = \frac{762.1}{218.693} = 3.484$$

↙ synchronous reactance drop / phase

$$\text{Total synchronising power} = \frac{3 \alpha E_0^2}{X_s}$$

α in electrical degrees

assume $E_0 = V$

$$= \frac{3 \alpha V^2}{X_s}$$

$\alpha = 1^\circ$ mechanical in degree

$$\boxed{\begin{aligned} 1^\circ \text{ electrical} &= 1^\circ \text{ mechanical} * \text{NO. of poles} \\ \theta_e &= \theta_m * (P/2) \quad \text{per pair} \end{aligned}}$$

$$\theta_m = \frac{\theta_e}{\frac{P}{2}} \Rightarrow 2 \frac{\theta_e}{P} = \theta_m$$

$$\left[\theta_e = \frac{\theta_m * P}{2} \right]$$

$$\alpha = \frac{1 * 8}{2} = 4^\circ \text{ electrical}$$

$$\alpha = 4 * \frac{\pi}{180^\circ} \text{ radians} = \frac{\pi}{45}$$

$$\text{Total synchronising power} = \frac{3 * \frac{\pi}{45} * 3810.5^2}{3.484} = 872.6 \text{ kW}$$

Synchronising power, Current & synchronising torque 10

Any one of generator tends to step out from synchronism a torque is termed as synchronising torque.


① Synchronising Current

Considered 2 alternators terminal voltages are equal on no load as E_1 & E_2 .

For parallel condition is achieved if magnitudes of $E_1 = E_2$ are equal.

For local armature circuit E_1 & E_2 are in phase opposition but for external circuit E_1 & E_2 are in phase.

If $E_1 = E_2$ there is no circulating current. Assume speed of 2nd alternator slightly reduces. Induced emf of 2nd alternator slightly changes by small angle



Any change in induced emfs of alternator creates a circulating current in the local armature circuit. This current is called as synchronising current.


$$I_{sy} = \frac{E_R}{Z_s}$$

E_R = difference or change in induced emf

Z_s = Combined synchronous impedances of alternator ① & ②

$$Z_s = Z_{s1} + Z_{s2}$$

$$Z_s = (R_{a1} + jX_{s1}) + (R_{a2} + jX_{s2})$$



I_{sy} synchronising w/B current lags behind the E_R by 90°

$$\tan \theta = \frac{X_s}{R_a}$$


$$X_s = X_{s1} + X_{s2}$$

$$R_a = R_{a1} + R_{a2}$$

In practical armature resistances R_{a1} & R_{a2} are small. Hence synchronising current is in nature of generator current for alternator 1 & motoring current for alternator 2.

This synchronising current I_{sy} gives a torque which speeds up the alternator 2 & retards the first alternator such that synchronism is again established. This torque is termed as synchronising torque.


Assume that speed of 1st alternator reduces shown in below figure, the resultant is induced emf E_1 falls back. Hence synchronising current is in the nature of generating current for alternator (1) & motoring current for alternator (2).



Hence synchronising current is in the nature of generating current for alternator (1) & motoring current for alternator (2).

Again synchronising current speeds up the alternator 1 & retards the 2nd generator until synchronism is achieved.

(II) Synchronising Power



assume a alternator 2 ~~is~~ emf slightly reduces due to reduced in speed. This creates induced emf's becomes unequal. This unequal emf's creates a circulating currents in local armature circuit. This current produces a torque which speeds up the alternator 2 & retards the first

retards the speed of first alternator.

$$I_{sy} = \frac{E_R}{Z_s}$$

$$E_R = 2E \cos\left(90 - \frac{\alpha}{2}\right)$$

$$E_R = 2E \sin\frac{\alpha}{2}$$

$$E_R = 2E\left(\frac{\alpha}{2}\right) = E\alpha$$

Now synchronizing power

$$I_{sy} = \frac{E\alpha}{Z_s}$$

Hence the first generator produces power is referred as synchronizing power. It is denoted as P_{sy} .

→ Consider 2 alternators.

Power supplied by each or first } $E_1 I_{sy} \cos\theta_1$
alternator

absorbed
Power supplied by 2nd alternator $E_2 I_{sy} \cos\theta_2$

Power supplied by first alternator =
Power absorbed by 2nd alternator + Copper losses

$$E_1 I_{sy} \cos\theta_1 = E_2 I_{sy} \cos\theta_2 + \text{Copper losses}$$

$$\text{if } \theta_1 = 0$$

$$\cos\theta_1 = 1$$

$$P_{sy} = E_1 I_{sy}$$

$$P_{sy} = E_1 \frac{E\alpha}{Z_s} \Rightarrow \text{put } E_1 = E$$

$$P_{sy} = \frac{E^2 d}{Z_s} = \frac{E^2 d}{X_s} \quad \text{if } R_a \text{ is neglected}$$

12

→ Total synchronising power = $3P_{sy}$

$$\# P_{sy} = \frac{3E^2 d}{X_s} \text{ watt}$$

$$\frac{E}{X_s} = I_{sc}$$

$$\text{Total synchronising Power } \# P_{sy} = 3 * E \left(\frac{E}{X_s} \right) d = 3EI_{sc}d$$

$$\# P_{sy} = 3EI_{sc}d$$

If the angle θ is not exactly 90° then more accurate form of expression is

$$\text{Total synchronising Power} = 3 * d * E * I_{sc} * \sin\theta$$

iii) Synchronising Torque

Synchronising Torque is produced due to synchronising current which takes place during alternators stepping out of synchronism.

Let T_{sy} denote synchronising torque

$$N_s = \frac{120f}{P}$$

$$P = \omega * T \Rightarrow P = \frac{2\pi N_s}{60} * T$$

$$\text{Power } P = \frac{2\pi N_s T}{60} \quad \text{if } T \text{ is in Nm-meters}$$

$$\text{we have } \# P_{sy} = \frac{2\pi N_s T_{sy}}{60}$$

$$T_{sy} = \frac{\# P_{sy} * 60}{2\pi N_s}$$

$$\text{We have } 3P_{sy} = \frac{3dE^2}{X_s}$$

$$T_{sy} = \frac{3dE^2 \cdot 60}{2\pi N_s X_s}$$

Problem A 10MVA, 50Hz, 3 phase alternator has an equivalent short circuit reactance of 20%. Calculate synchronising power per mechanical degree of phase displacement when running in parallel on 10,000V bus bars at 1500rpm.

Sol Rating of alternator = 10MVA = ~~10~~ 10,000 kW

bus-bar voltage = 10,000V in line, $\theta_m = 1^\circ$

Speed $N_s = 1500\text{rpm}$, $X_s = 20\% = 0.2$, $f = 50\text{Hz}$

$$\text{Rated voltage/phase} = \frac{\text{line voltage}}{\sqrt{3}} = \frac{10,000}{\sqrt{3}} = 5773.5\text{V}$$

$$\rightarrow \text{Full load or Rated Current} = \frac{\text{alternator rating}}{\sqrt{3} \times \text{Rated voltage in line}}$$

$$I = \frac{10 \times 10^6}{\sqrt{3} \times 10,000} = \frac{10,000,000}{17,320} = 577.35\text{A}$$

\rightarrow Reactance drop = 20% of phase voltage

$$IX_s = 577.35 \times 0.2 = 115.47\text{V}$$

synchronous reactance/phase

$$IX_s = 115.47 \Rightarrow X_s = \frac{115.47}{577.35} = 0.2$$

\rightarrow we know that $N_s = \frac{120f}{P} \Rightarrow P = \frac{120 \times f}{N_s}$

$$\text{No. of Poles } p = \frac{120 * 50}{1500} = 4$$

13

We have $\theta_e = \theta_m * \frac{\text{no. of poles}}{2}$

$$d = \theta_e = 1^\circ * \frac{4}{2} = 2^\circ \quad \text{in degree}$$

$$\theta_e = \frac{2 * \pi}{180} \text{ radians}$$

$$d = \theta_e = \theta_e^\circ * \frac{\pi}{180}$$

$$d = \theta_e = \frac{\pi}{90} \text{ radians}$$

E = rated voltage per phase = V

⇒ ~~Total~~ Synchronizing power

~~$$3P_{sy} = \frac{3 * d * E^2 * 60}{2\pi N_s X_s}$$~~

~~$$P_{sy} = \frac{d E^2}{X_s}$$~~

~~$$P_{sy} = \frac{\pi * (5773.5)^2}{90 * 0.2}$$~~

$$E = \text{rated voltage / phase} = 5773.5 \text{ V}$$

~~$$3P_{sy} = \frac{3 * \pi * (5773.5)^2 * 60}{90 * 2\pi * 1500 * 0.2}$$~~

$$P_{sy} = 5817.7 \text{ kW}$$

~~$$3P_{sy} = \frac{3 * \pi * (5773.5)^2 * 60}{90 * 2\pi * 1500 * 0.2} = 222.20 \text{ kW}$$~~

Problem

Rating of alternator = 5MVA = $5 * 10^6$ VA, poles = 4

3 phase alternator runs at 1500 rpm.

Rated voltage in line = 3.3 KV

% of synchronous reactance $X_s = 25\% = 0.25$

Power factor = 0.8 lag. Determine (i) Synchronizing power (ii) Torque

$$\text{Rated voltage/phase} = \frac{\text{Line Voltage} = 1905.255 \text{ V}}{\sqrt{3}}$$

$$\rightarrow \text{Full load Current } I = \frac{\text{Rating of alternator}}{\sqrt{3} * \text{Line Voltage}}$$

$$= \frac{5 * 10^6}{\sqrt{3} * 3.3 * 1000} = 874.77 \text{ A}$$

Synchronous reactance drop


~~$$(IX_s) = 0.25 * 874.77$$~~

$$IX_s = 0.25 * \text{Rated voltage / phase}$$

$$IX_s = 0.25 * 1905.255 = 476.313 \text{ V}$$

$$X_s = \frac{476.313}{874.77} = 0.5445 \Omega$$

→ To find E_0



$$\begin{aligned} E_0 &= V + IR_a + IX_a + IX_s \\ &= V + IR_a + IX_s \\ &= V + I(R_a + X_s) \end{aligned}$$

$$E_0 = V + IZ_s$$

$$I = 874.77$$

$$P.f \Rightarrow \cos \phi = 0.8$$

$$\phi = 31.788^\circ, \sin \phi = 0.526$$

$$\text{Voltage } V = V_p (\cos \theta + j \sin \theta)$$

$$V = (1905 \cdot 255) [0.85 + j0.526]$$

$$V = 1619.4 + j(1002 \cdot 16413)$$

14

$$\Rightarrow E_0 = V + I Z_s$$

$$= V + I (R_a + jX_s) \quad \text{Neglect } R_a$$

$$= V + I (X_s)$$

$$= 1619.4 + j(1002 \cdot 16) + j(476 \cdot 313)$$

$$= 1619.4 + 1478.4 (j)$$

$$E_0 = 2192.7 \angle \underline{42.4} \text{ Volts}$$

$$\text{Angle between } E_0 \text{ \& } V = \overset{\delta - \phi}{42.4 - 31.788}$$

$$\delta = 10.612$$

$$\text{load angle} = \cos \delta = \cos (10.612) = 0.9828$$

$$\alpha = 1^\circ \text{ mechanical}$$

$$\alpha = \left[\theta_e = \theta_m^\circ * \frac{\text{no. of poles}}{2} \right] = 1 * \frac{4}{2} = 2^\circ$$

$$\alpha = \theta_e^\circ * \frac{\pi}{180} \text{ radian}$$

$$\alpha = 2^\circ * \frac{\pi}{180} = \frac{\pi}{90} \text{ radians}$$

$$\alpha \text{ in degrees} = 2^\circ$$

$$\alpha \text{ in radians} = \frac{\pi}{90}$$

$$\cos(2) = 0.999, \quad \sin \alpha = (0.03489)$$

$$\text{Total Synchronizing Power} = \frac{3E_0 V \cos \delta \sin \alpha}{X_s}$$

$$= \frac{3 \times 2193.875 \times 1905.26 \times 0.9828 \times 0.0349}{0.544}$$

$$= 789.938 \approx 790 \text{ kW}$$

$$\text{Total synchronising torque} = \frac{\text{synchronising power} \times 60}{2\pi N_s}$$

$$= \frac{790 \times 60}{2\pi \times 1500} = 5.03 \text{ kNW-m}$$

Parallel operation of Alternators

Conditions necessary for parallel operation

- Terminal voltages of generators must be equal
 - The frequencies of generated emf's of all generators must be equal
 - Polarity of the voltages are must same
- x — x — x —

Consider 2 alternators, operating in parallel & sharing a common load. Assume that both generators have same speed-load characteristics.

Let

V = terminal voltage of each alternator


Z = load impedance

I = Current delivered by 2 alternators to load

Z_1, Z_2 → synchronous impedance of alternator ① & alternator ②

$I_1, I_2 \rightarrow$ Current supplied by alternator ① & alternator ②.

15



$E_1, E_2 \rightarrow$ induced emf's of alternator ① & alternator ②

* For Alternator (A1)

$$E_1 = V + I_1(R_1 + jX_1) = V + I_1 Z_1$$

* For Alternator (A2)

$$E_2 = V + I_2(R_2 + jX_2) = V + I_2 Z_2$$

$$\therefore E_1 - E_2 = I_1 Z_1 - I_2 Z_2 \rightarrow \text{①}$$

* Total Current $I = I_1 + I_2$

terminal voltage or Bus bar voltage

$$V = IZ \rightarrow \text{②}$$

\rightarrow Keep $V = IZ$ in E_1 & E_2 equation

$$E_1 = IZ + I_1 Z_1 = (I_1 + I_2)Z + I_1 Z_1$$

$$E_1 = I_1(Z + Z_1) + I_2 Z \rightarrow \text{③}$$

Similarly for

$$E_2 = IZ + I_2 Z_2 = (I_1 + I_2)Z + I_2 Z_2$$

$$E_2 = I_2(Z + Z_2) + I_1 Z \rightarrow \text{④}$$

from equation (2)

$$E_1 = I_1(Z + Z_1) + I_2 Z$$

$$I_2 Z = E_1 - I_1(Z + Z_1)$$

$$I_2 = \frac{E_1 - I_1(Z + Z_1)}{Z}$$

Substitute I_2 value in equation (1)

$$E_1 - E_2 = I_1 Z_1 - Z_2 \left[\frac{E_1 - I_1(Z + Z_1)}{Z} \right]$$

$$= I_1 Z_1 - \frac{Z_2 E_1}{Z} + \frac{Z_2 I_1 (Z + Z_1)}{Z}$$

$$E_1 - E_2 = I_1 \left[Z_1 + \frac{Z_2 (Z + Z_1)}{Z} \right] - \frac{Z_2 E_1}{Z}$$

$$E_1 - E_2 + \frac{Z_2 E_1}{Z} = I_1 \left[Z_1 + \frac{Z_2 (Z + Z_1)}{Z} \right]$$

$$\frac{Z(E_1 - E_2) + Z_2 E_1}{Z} = I_1 \left[\frac{Z Z_1 + Z_2 (Z + Z_1)}{Z} \right]$$

$$I_1 = \frac{Z(E_1 - E_2) + Z_2 E_1}{Z Z_1 + Z_2 (Z + Z_1)} = \frac{Z(E_1 - E_2) + Z_2 E_1}{Z Z_1 + Z Z_2 + Z_1 Z_2}$$

$$\boxed{I_1 = \frac{Z(E_1 - E_2) + Z_2 E_1}{Z(Z_1 + Z_2) + Z_1 Z_2}} \rightarrow (4)$$

Similarly for I_2 is obtained as

$$I_2 = \frac{Z(E_2 - E_1) + Z_1 E_2}{Z(Z_1 + Z_2) + Z_1 Z_2} \rightarrow (5)$$

$$\text{Total Current } I = I_1 + I_2$$

16

$$= \frac{(E_1 - E_2)Z + E_1 Z_2}{Z(Z_1 + Z_2) + Z_1 Z_2} + \frac{(E_2 - E_1)Z + E_2 Z_1}{Z(Z_1 + Z_2) + Z_1 Z_2}$$

$$= \frac{E_1/Z - E_2/Z + E_1 Z_2 + E_2 Z - E_1/Z + E_2 Z_1}{Z Z_1 + Z Z_2 + Z_1 Z_2}$$

$$I = \frac{E_1 Z_2 + E_2 Z_1}{Z(Z_1 + Z_2) + Z_1 Z_2}$$

$$\text{Bus bar Voltage } V = IZ$$

$$V = Z \left[\frac{E_1 Z_2 + E_2 Z_1}{Z(Z_1 + Z_2) + Z_1 Z_2} \right]$$

$$\text{Circulating Current } I_c = \frac{E_1 - E_2}{Z_1 + Z_2}$$

The above current circulating around the local armature circuit.

Problems 2 single phase alternators operating in parallel & supply power to load having impedance $Z = 6 + j2$. Open circuit induced emfs are $E_1 = 220 \angle 0^\circ$ & $E_2 = 220 \angle 10^\circ$ having corresponding impedances $Z_1 = (0.5 + j8)$ & $Z_2 = (0.3 + j10)$.

Find (i) Common terminal Voltage (V)

(ii) Current of PS of alternators

(iii) Power supplied by alternators

Sol - load impedance $Z = 6 + j2$
 $E_1 = 220 \angle 0^\circ$, $E_2 = 220 \angle 10^\circ$
 $Z_1 = 0.5 + j8$, $Z_2 = (0.3 + j10)$

$$Z_2 + Z_1 = Z$$

$$Z = 0.8 + j18 = 18.016 \angle 87.455^\circ$$

$$Z_1 Z_2 = 0.8$$

$$= (0.5 + j8.0)(0.3 + j10)$$

$$\Rightarrow Z_1 Z_2 = 80.192 \angle 174.705^\circ$$

$$Z = 6 + j2$$

$$= 6.3246 \angle 18.435^\circ$$

$$\Rightarrow E_1 = 220 \angle 0^\circ = 220 + 0j$$

$$\Rightarrow E_2 = 220 \angle 10^\circ = 216.658 + j38.202$$

$$\Rightarrow E_1 - E_2 = (220 + 0j) - (216.658 + j38.202)$$

$$E_1 - E_2 = 38.347 \angle -85^\circ$$

①

$$I_1 = \frac{Z(E_1 - E_2) + E_1 Z_2}{Z(Z_1 + Z_2) + Z_1 Z_2} = \frac{(38.347 \angle -85^\circ)(6.3246 \angle 18.43^\circ) + 220 \angle 0 (10.004 \angle 88.282^\circ)}{(6.3246 \angle 18.435^\circ)(18.018 \angle 87.455^\circ) + 80.196 \angle 174.706^\circ}$$

$$= \frac{242.542 \angle -66.565^\circ + 2201.1 \angle 88.282^\circ}{113.957 \angle 105.89^\circ + 80.196 \angle 174.706^\circ}$$

$$= \frac{2443.642 \angle 21.717^\circ}{194.153 \angle 280.596^\circ}$$

$$= \frac{1984.236 \angle 85.303^\circ}{161.315 \angle 133.506^\circ} = 12.300 \angle -48.196^\circ$$

$$I_1 = 8.199 - j9.1688$$

$$\Rightarrow I_2 = \frac{Z(E_2 - E_1) + E_2 Z_1}{Z(Z_1 + Z_2) + Z_1 Z_2}$$

$$I_2 = \frac{1996.624 \angle 98.46^\circ}{161.3133 \angle 133.5^\circ} = 12.3773 \angle -35.04^\circ$$

$$I_2 = 12.3773 \angle -35.04^\circ = 10.1339 - j7.1064$$

$$I = I_1 + I_2$$

$$= (8.199 - j9.1688) + (10.1339 - j7.1064)$$

$$= (18.333 - j16.2752) = 24.51 \angle -41.6^\circ$$

(iii) Power o/ps

Let P_1 & P_2 denote the power o/ps

$$P_1 = VI_1 \cos \phi_1$$

$$V = IZ$$

$$= 24.51 \angle -41.6^\circ * 6.3246 \angle 18.435^\circ$$

$$V = 155.01 \angle -23.165^\circ$$

$$= (155.01 \angle -23.165^\circ) * 12.300 \angle -48.196^\circ$$

$$= (1906.5) \cos (48.196 - 23.165)$$

$$= (1906.5) * (0.9) = 1727.44$$

$$P_2 = VI_2 \cos \phi_2$$

$$= (155 * 12.3773) \cos (-35.04 - 23.165)$$

$$= 1877.424$$

Effect of change in excitation.


Considered 2 alternators operating in parallel sharing a common load.

Assume induced emfs E_1 & E_2 , I_1 & I_2 are equal in magnitude & is in phase. As a result both generators operating at same power factor shares a common load. Reactive power supplied

Let ϕ be the angle by 2 generators are equal.

$$I_1 = I_2 = I$$

phasor diagram




V = common terminal voltage

$$I_1 = I_2 = I$$

Load current

$$I_1 + I_2 = 1 + 1 = 2I$$



$$\phi_1 = \phi_2 = \phi$$

$$KW_1 = KW_2$$


$$KVAR_1 = KVAR_2$$

$$\cos \phi = \text{P.f of each generator} = \text{Load P.f}$$

Since E_1 & E_2 are equal & is opposition to local armature circuit, there is no circulating current.

circulating currents is induced if induced emfs are unequal. in local armature circuit


$$I_c = \frac{E_1 - E_2}{Z_1 + Z_2}$$



I_c flows in same direction to I_1 but opposite to the direction I_2 . As a result I_1 increases & I_2 decreases. ϕ_1 decreases, ϕ_2 increases. The resultant is that kW o/p of G_2 remains same.

Thus total load remains same if field excitation of alternator is changed but reactive power o/p of generator changes but not true power o/p.

Even though the field excitation changes kW o/p remains unchanged but power factor of power delivered changes.



$\phi_1' > \phi_1$
 $\phi_2' < \phi_2$

G_1 supplies more reactive power at lower power factor &

G_2 supplies ^{less} reactive power at high P.f.

Effect of change in input power

Now we study the effect of change in i/p power to prime mover of any one of 2 alternators.

Let G_1, G_2 are 2 generators operating in parallel share a common load having induced emf's E_1 & E_2 are equal & is in phase.

Let the excitation & total load of 2 generators remaining unchanged & constant. If i/p to first generator (G_1) increases, speed of generator (G_1) cannot be increased.

But induced emf E_1 advances with respect of E_2 . shown in phasor diagram




fig (a) $E_1 = E_2$ is in phase





fig (b) $E_1 = E_2$

E_1 advances by α

Induced emf's becomes unequal as a result resultant emf E_R is produced gives rise to synchronising current I_{sy} .

Here I_{sy} lags behind E_R by 90° is in phase with E_1



I_{sy} lags E_R by 90°
 E_R is in phase E_1 .

→ Generator whose input power is more can share larger part of total load & other generator takes lesser part of load.

$G_1 \rightarrow$ i/p increases $\rightarrow G_1$ shares more load

$G_2 \rightarrow$ i/p constant $\rightarrow G_2$ " less load.




fig (C) KVA triangles

Even though the (I_{sy}) Synchronizing produces reactive power supplied by ~~loads~~ generators remains same.

in fig (C) Generator G_1 shares more load as KW_1 & G_2 shares less load $B'D$ as KW_2 .

Effect of change in excitation	Effect of change in i/p power
<p>Even though the excitation of one generator changes KW o/p of generator remains same but reactive power o/p generator changes also P.f changes</p> <p>$I_1 \uparrow, \phi_1 \downarrow, Q \uparrow, P = \text{const}$</p>	<p>Even though i/p power of one generator increases or changes, KW o/p of generators varies but reactive power o/p of generator remains same.</p> <p>Input G_1 increases, $P = \uparrow$, $Q = \text{constant}$.</p>

Problems

Two alternators working in parallel has loads

- (i) lights load 800 kW (ii) 500 kW at 0.9 p.f lag
(iii) 1000 kW at 0.8 p.f lag (iv) 600 kW at 0.9 p.f lead.

one alternator is supplying 1000 kW at 0.95 p.f lag. Calculate the o/p, p.f of the other generator (ii) find load p.f.

Sol for lighting loads p.f is almost unity

Total active power of 2 alternators is

$$800 + 500 + 1000 + 600 = 2900 \text{ kW}$$

→ first alternator active power = 1000 kW

Total active power of generators = 2900 kW


$$G_1 + G_2 = 2900 \text{ kW}$$

$$1000 + G_2 = 2900 \text{ kW}$$

o/p of 2nd alternator

$$G_2 = 2900 - 1000 = 1900 \text{ kW}$$

→ To calculate reactive component (KVAR) of load



$$\tan \phi = \frac{\text{KVAR}}{\text{KW}} = \frac{\text{OPP}}{\text{Adj}}$$

$$\text{KVAR} = \text{KW} * \tan \phi$$

For lag p.f KVA is +ve

lead p.f KVA is -ve

(i) for lights load of 800 kW

$$\text{p.f} = \cos \phi = 1$$

$$\text{if } \phi = 0$$

$$\text{KVAR} = 800 * \tan(0) = 0$$

(ii) 500 kW at 0.9 p.f lag

20

$$\boxed{KVAR = KW * \tan \phi}$$

$$\cos \phi = 0.9$$

$$KVAR = 500 * \tan(25.84)$$

$$\phi = \cos^{-1}(0.9) =$$

$$KVAR = 242.16 \text{ (+ve)}$$

$$\phi = 25.84$$

(iii) 1000 kW at 0.8 p.f lag

$$\boxed{KVAR = KW * \tan \phi}$$

$$\cos \phi = 0.8$$

$$= 1000 * \tan(36.86)$$

$$\phi = \cos^{-1}(0.8)$$

$$KVAR = 750 \text{ (+ve)}$$

$$\phi = 36.86$$

(iv) 600 kW at 0.9 p.f leading

$$\boxed{KVAR = KW * \tan \phi}$$

$$\cos \phi = -0.9$$

$$KVAR = 600 * (-0.48)$$

$$\phi = \cos^{-1}(-0.9)$$

$$= -290.59$$

$$\phi = 154.15$$

Reactive power supplied by all loads

$$\text{Total KVAR} = 0 + 242.161 + 750 - 290.59$$

$$= 701.568 \text{ KVAR}$$

$$\text{Total KW} = 2900 \text{ kW}$$

→ Total load power factor

$$\Rightarrow \boxed{\tan \phi_L = \frac{\text{Total KVAR}}{\text{Total KW}} = \frac{701.568}{2900} = 0.2419}$$

$$\phi_L = \tan^{-1}(0.2419) = 13.56^\circ$$

$$\cos \phi_L = \cos(13.56) = 0.9719$$

$$\phi_L = 0.9719$$

⇒ first alternator supplies 1000 kW at 0.95 P.f
lag

$$\text{KVAR} = \text{KW} * \tan \phi_L$$

$$= 1000 * \tan (18.19)$$

$$\text{KVAR} = 328.684$$

$$\cos \phi = 0.95$$

$$\phi = \cos^{-1}(0.95)$$

$$= 18.19$$

⇒ Reactive power supplied by 2nd alternator

$$\text{KVAR}_2 = ?$$

$$\text{Total Reactive Power KVAR} = 701.568$$

$$\boxed{\text{KVAR}_1 + \text{KVAR}_2 = 701.568}$$

$$328.64 + \text{KVAR}_2 = 701.568$$

$$\text{KVAR}_2 = 701.568 - 328.64$$

$$\boxed{\text{KVAR}_2 = 372.883}$$

→ P.f of the 2nd alternator

$$\boxed{\tan \phi_2 = \frac{\text{KVAR}_2}{\text{KW}_2} = \frac{372.883}{1900} = 0.196}$$

$$\phi_2 = \tan^{-1}(0.196) = 11.103$$

$$\Rightarrow \cos \phi_2 = \cos(11.103) = 0.98128$$

$$\text{KW}_2 \text{ of 2nd alternator} = 1900$$

$$\text{KVAR}_2 \text{ of 2nd alternator} = 372.883$$

$$\text{P.f of 2nd alternator} = 0.9812$$

$$\text{Load P.f } \phi_L = 0.9719$$

Problem 2 same ratings of ^{3 phase} alternator²
 Connected in parallel supplying a load 1500 kW
 at 11 kV, 0.8 P.f lag.

Each machine has $X_s = 60$ (Synchronous reactance)
 $R = 2.8$ (Resistance) / phase.

Power supplied by each machine is constant,
 excitation of 1st alternator is adjusted so
 that its armature current is 45 A. Calculate

- (i) Armature current of other alternator
 (ii) P.f. of each alternator.

Sol Load supplied = 1500 kW at 0.8 P.f lag
 Bus bar voltage = 11 kV = 11000 V (line value)

Synchronous reactance $X_s = 2.8 \Omega$ / phase

Resistance $R = 60 \Omega$ / phase

\Rightarrow Synchronous impedance of each alternator

$$Z_s = R + jX_s = 2.8 + j0.6 \text{ } \Omega \text{ / phase}$$

Armature current of first alternator

$$I_1 = 45 \text{ A}$$

\Rightarrow Total load current

$$I_L = \frac{\text{load supplied in kW}}{\sqrt{3} \times \text{bus bar volt} \times \text{P.f}}$$

$$= \frac{1500 \times 1000}{\sqrt{3} \times 11000 \times 0.8} = 98.4119 \text{ A}$$

$$I_L = \frac{\text{Load kW}}{\sqrt{3} \times V \times \text{P.f}}$$

$$\text{Current supplied by } \overset{\text{each}}{\text{alternators}} = \frac{\text{Total load current}}{2}$$

$$= \frac{98.412}{2} = 49.206 \text{ A}$$

given P.f = 0.8

$$\Rightarrow \text{Active Component } I_L = I_L \cos \phi$$

$$I_L = 98.412 * 0.8 = 78.7296$$

$$\Rightarrow \text{Reactive Component } I_L = I_L \sin \phi$$

$$= 98.412 * 0.6 = 59.0472 \text{ A}$$

$$\Rightarrow \text{Active Component Current supplied by each alternator}$$

$$= \frac{78.7296}{2} = 39.3648 \text{ A}$$

$$\Rightarrow \text{Reactive Component Current supplied by each alternator}$$

$$= \frac{59.0472}{2} = 29.5236 \text{ A}$$

change of excitation of 1st alternator

Current supplied by alternator ① i.e. its armature current $I_a = 45 \text{ A}$

Active Component of 1st alternator current

$$I_1 = 39.364$$

→ Reactive Component of 1st alternator

$$I_1 = \sqrt{(\text{Armature current})^2 - (\text{Active current})^2} = \sqrt{I_a^2 - I_1^2}$$
$$= \sqrt{(45)^2 - (39.368)^2}$$
$$= 21.804 \text{ A}$$

$$I_a = \sqrt{I_{AC}^2 + I_{RC}^2} \Rightarrow I_{RC}^2 = I_a^2 - I_{AC}^2$$

let I_2 be the current supplied by alternator (2)

$$I_2 = I_{pc} + I_{pe}$$

Reactive Component of I_2

$$= \text{acosue} \\ = (\text{Total Current of load}) - \text{Reactive Component } I_1$$

$$= 59.0472 - 21.0804 = \underline{\underline{37.24}}$$

$$\rightarrow \text{Active Component of } I_2 = 39.3648$$

Armature Current of 2nd alternator

$$= (\text{Reactive Component of } I_2)^2 =$$

$$(\text{Active Component of } I_2)^2 - (\text{armature current } 2^{\text{nd}} \text{ alternator})^2$$

$$\Rightarrow \text{Armature Current of } 2^{\text{nd}} \text{ alternator } (I_2) = \sqrt{(\text{Reactive } I_2)^2 + (\text{Active } I_2)^2}$$

$$= \sqrt{(37.24)^2 + (39.3648)^2}$$

$$= 54.191$$

To calculate Power factors

$\cos\phi_1$ & $\cos\phi_2$ are P.f's of alternators (1) & (2) having currents I_1 & I_2


$$\cos\phi = \frac{\text{Active Current Component}}{\text{Armature Current}}$$

$$\cos\phi_1 = \frac{39.3648}{45} = 0.8748$$

$$\cos\phi_2 = \frac{39.3648}{54.191} = 0.72641$$

$$I_{a2} = 54.191 \\ \cos\phi_1 = 0.8748 \\ \cos\phi_2 = 0.72641$$

Load sharing between two alternators



Considered 2 machines having same load-speed characteristics operating in parallel with common terminal voltage (V) & load impedance Z .

Let E_1 & E_2 are induced emfs of 2 machines
 Z_{s1} , Z_{s2} are synchronous impedances of 2 machines

Let V be common terminal voltage of 2 machines.

Terminal voltage V of machine ① is & machine ②

$$V = E_1 - I_1 Z_{s1} \rightarrow \text{①}$$

$$V = E_2 - I_2 Z_{s2} \rightarrow \text{②}$$

Also terminal voltage of load is

$$V = I Z$$

$$V = (I_1 + I_2) Z \rightarrow \text{③}$$

from equation ①

$$I_1 = \frac{E_1 - V}{Z_{s1}} \rightarrow \text{④}$$

from equation ②

$$I_2 = \frac{E_2 - V}{Z_{s2}} \rightarrow \text{⑤}$$

Adding (4) & (5)

$$I_1 + I_2 = \frac{E_1 - V}{Z_{S1}} + \frac{E_2 - V}{Z_{S2}}$$

$$= \frac{E_1}{Z_{S1}} - \frac{V}{Z_{S1}} + \frac{E_2}{Z_{S2}} - \frac{V}{Z_{S2}}$$

$$V \Rightarrow (I_1 + I_2) Z$$

$$I_1 + I_2 = \frac{V}{Z} \rightarrow (6)$$


$$\frac{V}{Z} = \frac{E_1 - V}{Z_{S1}} + \frac{E_2 - V}{Z_{S2}} \Rightarrow \frac{E_1}{Z_{S1}} + \frac{E_2}{Z_{S2}} - V \left[\frac{1}{Z_{S1}} + \frac{1}{Z_{S2}} \right]$$

$$\frac{V}{Z} + V \left[\frac{1}{Z_{S1}} + \frac{1}{Z_{S2}} \right] = \frac{E_1}{Z_{S1}} + \frac{E_2}{Z_{S2}}$$

$$V \left[\frac{1}{Z} + \frac{1}{Z_{S1}} + \frac{1}{Z_{S2}} \right] = \frac{E_1}{Z_{S1}} + \frac{E_2}{Z_{S2}}$$

$$V = \frac{\frac{E_1}{Z_{S1}} + \frac{E_2}{Z_{S2}}}{\frac{1}{Z} + \frac{1}{Z_{S1}} + \frac{1}{Z_{S2}}}$$

$$V = \frac{E_1 Y_1 + E_2 Y_2}{Y + Y_1 + Y_2}$$

Load voltage 

Problem determine the terminal voltage & kW of each machine if $E_1 = 100$, $E_2 = 1100$, $Z = 3 + j4$, $Z_1 = Z_2 = 0.2 + j1$.

sol Terminal voltage $V = \frac{E_1 Y_1 + E_2 Y_2}{Y + Y_1 + Y_2}$

$$Y_2 = Y_1 = \frac{1}{Z} = \frac{1}{3 + j4} = 0.1923 - 0.9615j$$

$$Y_0 = Y_0 = \frac{1}{Z_0 \cdot Z_0} = \frac{1}{9 + 4j} = 0.12 - 0.16j$$

$$\text{Terminal voltage } V = \frac{E_1 Y_1 + E_2 Y_2}{Y + Y_1 + Y_2}$$

$$V = \frac{40.83 - j201.915}{0.5046 - j2.083} = 96.11 \angle -2.311$$

$$I_1 = \frac{E_1 - V}{Z_1} = (E_1 - V) Y_1 = 5.457 \angle -34.64$$

$$I_2 = \frac{E_2 - V}{Z_2} = (E_2 - V) Y_2 = 14.525 \angle 15.45^\circ \times 0.9805$$

$$\angle -78.69$$

$$I_2 = 14.24 \angle -63.24 \text{ A}$$

$$\text{Kw o/p of machine (1)} = V I_1 = 96.11 \angle -2.311 \times 5.47 \angle -34.64$$

$$= 525.5 \text{ W}$$

$$\text{" " " machine (2)} = V I_2 = 1368 \text{ W}$$

Alternators on Infinite bus

The performance of alternator is not same when it operates separately on infinite bus.

An alternator is said to be on infinite bus if 2 or more generating units operated in parallel having same terminal voltage that is same as the common bus bar voltage.

A group of machines located at one place may be treated as a single large machine. Also the machines connected to same bus may be grouped into one large machine. If adding or disconnection of one machine which is in parallel would not affect the magnitude & phase of voltage & frequency.

Since an infinite bus is also a power s/m so that its voltage & frequency remains constant. 24

characteristics of infinite bus

→ terminal voltage remain constant because incoming machine is too small to increase or decrease

→ frequency remains constant

→ Z_s is very small since s/m has a large number of alternators in parallel.

→ In isolated operation, change of excitation leads to change the terminal of alternator, P.f depends on load only.

* If machines operating in parallel with an infinite bus its excitation is changed, P.f of machine changes but no change in terminal voltage.

* If excitation is increased, $e_{mf} >$ bus bar voltage, the machine acts as a generator & supplies power to bus bars.

* If excitation is decreased, $e_{mf} <$ the bus bar voltage, the prime mover is replaced by mechanical load & acts a synchronous motor

Problems

Two 500 KVA alternators operate in parallel to supply following loads

(i) 250 kW at 0.9 P.f lag (ii) 300 kW at 0.75 P.f lag (iii) 150 kW at 0.8 P.f lag. One machine supplies 100 kW at 0.8 P.f lag. Calculate P.f of each machine.

Sol KVA of each alternator = 250 KVA.


Total active power (P) supplied by all alternators
= 250 + 300 + 150 = 700 kW

→ first machine supplies 100 kW = P_1

active power supplied 2nd alternator
 $P_2 = ?$

$$\begin{aligned} \text{Total active power (P)} &= P_1 + P_2 \\ 700 &= 100 + P_2 \\ P_2 &= 600 \text{ kW} \end{aligned}$$

→ Reactive Power supplied by 1st machine



$$\cos \phi_1 = 0.8$$

$$\phi_1 = \cos^{-1}(0.8)$$

$$\phi_1 = 36.87^\circ$$

$$\tan \phi_1 = \tan(36.87) = 0.75$$

$$\sin \phi_1 = \frac{\text{KVAR}}{\text{KVA}} = \frac{BC}{AC}$$

$$\cos \phi_1 = \frac{\text{KW}}{\text{KVA}} = \frac{AB}{AC}$$

$$\frac{\sin \phi_1}{\cos \phi_1} = \frac{\text{KVAR} \times \text{KVA}}{\text{KVA} \times \text{KW}}$$

$$\tan \phi_1 = \frac{\text{KVAR}}{\text{KW}}$$

Reactive Power supplied by first machine

$$\text{KVAR} = \text{KW} \times \tan \phi_1$$

$$\text{KVAR} = 100 \times 0.75 = 75 \text{ KVAR}$$

→ Reactive power of total load

$$\boxed{\text{KVA} = \text{KW} \times \tan \theta}$$


$$= \text{KW}_1 \tan(\cos^{-1}(0.9)) + \text{KW}_2 \tan[\cos^{-1}(0.8)] \\ + \text{KW}_3 \tan(\cos^{-1}(0.75))$$

$$= 250 \tan(25.842) + 300 \tan[41.41] + \\ 150 \tan(36.87)$$

$$= 498.16 \text{ KVAR}$$

Total KVA of reactive power supplied 2 machines = Reactive power of machine ① + Reactive power 2nd machine

$$\text{Reactive power of 2nd machine} = 498.16 - 75 = 423.16 \text{ KVA}$$




power factor of 2nd machine

$$\tan \phi_2 = \frac{\text{KVAR}}{\text{KVA}} = \frac{423.16}{600} = 0.7053$$

$$\phi_2 = \tan^{-1}(0.7053) = 35.194$$

$$\text{P.f} = \cos \phi_2 = \cos(35.194) = 0.8172 \text{ lag}$$

- ② Governor's of each 2000 kW rating of alternators running in parallel are so adjusted that frequency of one alternator drops from 50 to 45 Hz & other drops from 50 Hz to 47 Hz from no load to full load. Calculate load on each machine when total load is 3000 kW



Sol Total load in s/m is 3000 kW

→ Each alternator have the Capacity to supply 2000 kW

$$\begin{aligned} \text{Decrease in difference in frequency of machine (A)} \\ &= \text{normal frequency} - \text{final frequency} \\ &= 50 - 45 = 5 \text{ Hz} \end{aligned}$$

$$\begin{aligned} \rightarrow \text{Decrease in difference in frequency of machine (B)} \\ &= \text{normal frequency} - \text{final frequency} \\ &= 50 - 47 = 3 \text{ Hz} \end{aligned}$$

PA = drop in frequency from 50 to 45 Hz

PR = " " " " from 50 to 47 Hz

MS = total load in the s/m

PO = Difference in frequency from no load to full load = 5 Hz \rightarrow 1st machine (A)

PO = Difference in frequency from no load to full load = 3 Hz \rightarrow 2nd machine (B)

\rightarrow Let (x) be rate of frequency drop in both alternator supplying total load is 3000 kW
PN = x

\rightarrow MN is load supplied by machine (A)

NS is " " " " machine (B)

Total load supplied by 2 alternators = OA + OB = 2000 + 2000 = 4000 kW

\rightarrow Consider the triangles PMN & PAO
from PMN triangle & PAO triangle

$$\frac{MN}{PN} = \frac{AO}{PO} \Rightarrow \frac{MN}{x} = \frac{2000}{5}$$

$$\boxed{MN = 400 * x}$$

\rightarrow Consider the triangles PNS & POR

$$\frac{NS}{PN} = \frac{OR}{PO} \Rightarrow \frac{NS}{x} = \frac{2000}{3}$$

$$N_3 = \frac{2000}{3} * x$$

27

$$MN + NS = MS$$

$$MS = 400 * x + \frac{2000}{3} * x$$

$$3000 = 400 * x + \frac{2000}{3} * x$$

$$x = 2.8125$$

→ load supplied by alternator ①

$$MN = 400 * x = 400 * 2.8125 = 1125 \text{ kW}$$

→ load supplied by alternator ②

$$NS = \frac{2000}{3} * x \Rightarrow \frac{2000}{3} * 2.8125 = 1875 \text{ kW}$$

Actual frequencies of alternators supplies
3000 kW is

$$50 - x = 50 - 2.8125 = 47.1875 \text{ Hz}$$

② Two 2000 KVA ~~W~~ identical alternators operated in parallel. The governor of prime mover of 1st machine such that frequency drops from 50 Hz on no load to 48 Hz on full load. 2nd machine speed drops from 50 Hz to 47.5 Hz.

① Calculate load shared by each machine of load 3000 kW.

(ii) What is the maximum load of unity P.f that can be delivered without overloading each machine

sol
Rating of each alternator = 2000 KVA

First Machine frequency drops on no load to full load 50 Hz - 48 Hz

2nd machine frequency drops from 50 Hz to 47.5 Hz


$$\left. \begin{aligned} BD &= 2000 \\ DC &= 2000 \end{aligned} \right\} \text{ kW}$$

$$PR = \text{load Line} = 3000 \text{ kW}$$

$$AB = x$$

$$AD = 2 \text{ Hz}$$

$$AO = 2.5 \text{ Hz}$$



Total load in the s/m is 3000 kW

Each alternator have the Capacity to supply = 2000 kW load

Assume the P.f supplied by alternators have unity P.f for the given load.

⇒ Decrease in frequency of machine (1) = nominal frequency - final frequency = $50 - 48 = 2 \text{ Hz}$

Similarly for machine (2) = $50 - 47.5 = 2.5 \text{ Hz}$

⇒ AB = drop in frequency of machine (1) = $50 - 48 = 2 \text{ Hz}$

AC = drop in frequency of machine (2) = $50 - 47.5 = 2.5 \text{ Hz}$

⇒ AD = difference in frequency from no load to full load = 2 Hz

AO = Difference in frequency from no load to full load = 2.5 Hz

Let x be the rate of frequency drop
from no load to full load 28

① To find the load division

Considered triangles PAQ & ABD

$$\frac{PQ}{AQ} = \frac{BD}{AD}$$

$$\Rightarrow \frac{PQ}{x} = \frac{2000}{AD} \Rightarrow \frac{PQ}{x} = \frac{2000}{2} \Rightarrow 1000x \rightarrow \text{①}$$

$$PQ = 1000x \rightarrow \text{①}$$

Consider triangles AQR & AOC

$$\frac{QR}{AR} = \frac{OC}{AO} \Rightarrow \frac{QR}{x} = \frac{2000}{2.5Hz}$$

$$QR = \frac{2000}{2.5} * x = 800x \rightarrow \text{②}$$

\Rightarrow Total load in the s/m = 3000 kW

$$PQ + QR = 3000 \text{ kW}$$

$$1000x + 800x = 3000$$

$$x = \frac{3000}{1800} = 1.666 \text{ Hz}$$

\rightarrow load supplied by machine ①

$$PQ = 1000x = 1000 * 1.666 = 1666 \text{ kW}$$

load supplied by machine ②

$$QR = 800x = 800 * 1.666 = 1333 \text{ kW}$$

\rightarrow Actual frequency of both alternators supplies

$$3000 \text{ kW load} = 50 - x = 50 - 1.666 = 48.334$$

① To find maximum load at unity P.f

At point 'D' extend the line on AC and mark the point as 'T'.

load supplied by alternator = 2000 kW = DT

Consider the triangles ADT & AOC

$$\frac{DT}{AD} = \frac{OC}{AO}$$

$$\frac{DT}{2} = \frac{2000}{2.5}$$

$$DT = 1600 \text{ kW}$$

Total load supplied

$$= BD + DT \Rightarrow 2000 + 1600 = 3600 \text{ kW}$$

Unit - IV

Synchronous MOTORS

Theory of operation

Introduction

If an alternator is supplied with an ac power, it capable of rotating as a motor & doing mechanical work.

If the mechanical power is supplied removed, with dc field remains energized & an ac supply is connected across the armature terminals, torque will developed & the alternator will at synchronous speed. Any change in mechanical load will not cause a speed changed (constant speed).

In case of dc motor field winding & armature winding requires a dc supply. But in case of synchronous motor field winding requires a dc supply & whereas armature winding is connected to 3 phase ac supply.

Dc excitation may be provided either from dc s/m plant by using batteries or using dc generators.

For high speed motors Direct Connected exciters are used with exciter armature mounted on the motor shaft.

For low speed machines belted exciters are employed

The main essential parts of 3 phase synchronous motor are (i) laminated stator core with 3 phase armature winding.

33

- (ii) rotating field with damper windings & slip rings
- (iii) brushes & holders
- (iv) two end shields consists of bearings to support the rotor shaft.

characteristic features of synchronous motor

- It is not a self starting motor
- It runs only at one speed that is synchronous speed at whatever load.
- It can be operated for both lagging & leading p.f's.


Construction

It mainly consists of 2 parts

- (1) Stator & (2) Rotor

- also termed as armature, which is in cylindrical structure.
- It is made up of cast steel or Iron or rolled steel.
- Stator consists of slots which are arranged in the inner periphery.
- Each slots carries 3 phase armature windings. which are connected in star manner.
- The ends of windings are brought out & is connected to the power supply.

Rotor



- Rotor is cylindrical in structure which is made up of cast steel.
- The main poles are fixed to the rotor core.
- The poles are projected out from the surface of the rotor.
- Each pole carries a field coils, wound around the poles. All field coils are joined in series.
- The ends of field coils are joined to 2 insulated copper slip rings, mounted on the shaft of the motor.
- Carbon brushes presses the slip rings, excitation current is supplied to the motor through carbon brushes via slip rings.
- excitation is generally obtained from a dc source.

principle of operation


34

synchronous motor is inherently not a self starting motor because it does not develop a unidirectional torque.


when 3 phase supply is given to stator, a rotating magnetic field is set up in the stator revolving around the stator at synchronous speed.

$$N_s = \frac{120f}{P} \quad P = \text{no. of stator poles}$$

let us assume that there is one pair of poles assume the stator poles is rotating in clockwise shown in figure



Repulsion
(Anticlockwise rotor)



Attraction
clockwise rotor

N & S → rotor poles

N_s & S_s → stator poles

Rotor is stationary field N & S poles remaining stationary.

Stator poles (N_s & S_s) revolves in the space at synchronous speed. If N_s & N & S_s & S there is a force of repulsion takes place as a result rotor tends to rotate in anticlockwise direction, torque also in anticlockwise direction.

→ After a half period stator interchanges a position of poles then the position of poles S_s & N & N_s & S there is a force of attraction takes place as a result rotor tends in clockwise direction. This gives a torque in clockwise.


→ Because of anticlockwise & clockwise directions torques, the motor cannot respond easily to oppose torque. The net result is motor is stationary.

To start the motor we require 2 types of supply. one balanced 3 phase ^{AC} supply given to stator & a d.c excitation is supplied to field winding. Now both stator poles & rotor poles are rotating in same direction at same speed they rotate poles get engaged with stator poles. Even if prime mover is removed the rotor continues to run at synchronous speed.


Equivalent circuit

35

- let V = stator applied voltage
 - E_b = back emf developed
 - R_a = armature resistance
 - X_s = synchronous reactance
 - Z_s = " impedance
- } per phase



equivalent circuit




phasor diagram

The phasor diagram of synchronous motor is similar to alternator. Here armature reaction can be substituted by X_a which is added to leakage reactance gives synchronous reactance X_s . shown in equivalent circuit

The phasor diagram of synchronous motor differs to synchronous alternator.

$$\phi = E_b \angle I_a$$

$$\alpha = E_b \angle V$$



when α is +ve

Voltage equation of stator circuit

$$V = -E + I Z_s \rightarrow (1)$$

In this case excitation voltage acts as a source voltage & is equal to the sum of terminal voltage & synchronous impedance drop. above is for synchronous generator.

In case of synchronous motor V is source voltage applied to stator & E is an counter emf. Voltage equation of synchronous motor is shown in equation (1).

In 2nd case phasor diagram of synchronous motor differs from synchronous generator involves angle δ called power or torque angle.


Power flow equations in synchronous motor

We know that voltage equation of syn motor

$$V = E_b + I_a Z_s$$

$$I_a = \frac{V - E_b}{Z_s}$$

$$Z_s = R_a + jX_s$$



Angle θ by which I_a lags behind E_R

$$\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$

Let the motor i/p = $V I_a \cos \phi$

V = applied voltage / phase

Total i/p for star connected $P = \sqrt{3} V_L I_L \cos \phi$

↳ ①

Mechanical power developed by rotor

$$P_m = E_b I_a \cos(\alpha - \phi) \text{ per phase} \rightarrow \text{②}$$

of out i/p power some amount of power ($I_a^2 R_a$) is wasted in armature

Total i/p power = armature + Mechanical power (P_m)
for star connected (P) Cu loss




$$P = P_m + I_a^2 R_a$$

Mechanical i/p power developed by rotor $P_m = P - I_a^2 R_a$


$$P_m = \sqrt{3} V_L I_L \cos\phi - 3 I_a^2 R_a$$

i/p power to stator


$$P = V I_a \cos\phi$$



power developed by synchronous motor 37



for small machines neglect the armature resistance hence equivalent circuit is given as



$\phi = \text{angle b/w } V \text{ \& } I_a$
 $\alpha = \text{ " b/w } V \text{ \& } E_b$

$\frac{OC}{OA} = \cos \alpha$

$AB = E_b \sin \alpha = I_a X_s \cos \phi$

motor i/p power per phase $P_{in} = V I_a \cos \phi$

$= I_a (V \cos \phi)$

from ΔOAD

~~$\cos \phi = \frac{AD}{OA}$~~ $\Rightarrow \frac{AD}{V} = \cos \phi \Rightarrow AD = V \cos \phi$

$\frac{OD}{OA} = \cos \phi \Rightarrow \frac{OD}{V} = \cos \phi \Rightarrow OD = V \cos \phi$

$= I_a (OD)$

from ΔOCD

$\frac{OD}{OC} = \cos(\phi - \alpha) \Rightarrow \frac{OD}{E_b} = \cos(\phi - \alpha)$


$OD = E_b \cos(\phi - \alpha)$

motor i/p power to stator / phase = $I_a E_b \cos(\phi - \alpha)$

from ΔABC

$$\cos(\phi - \alpha) = \frac{AB}{AC}$$

$$\frac{AB}{I_a X_s} = \cos(\phi - \alpha) \Rightarrow AB = I_a X_s \cos(\phi - \alpha)$$



from ΔOAB

$$\frac{AB}{OA} = \sin \alpha$$

$$\frac{AB}{V} = \sin \alpha \Rightarrow AB = V \sin \alpha$$

$$\frac{V \sin \alpha}{I_a X_s} = \cos(\phi - \alpha)$$

motor i/p power to stator = $E_b I_a \cos(\phi - \alpha)$

$$P_{in} = \frac{E_b \cdot V \cdot I_a \sin \alpha}{I_a X_s} \quad \text{if } \phi = 90^\circ$$

$$P_{in} = \frac{E_b V \sin \alpha}{X_s}$$

Total i/p 3 phase power to stator

$$P_{in} = \frac{3VE_b}{X_s} \sin \alpha = P_m$$

38

Synchronous motor with different excitations

if $E_b = V$ synchronous motor is in normal excitation


$E_b < V$ is under excitation

$E_b > V$ is over excitation

$$\theta = (\alpha + \alpha')$$

$$\alpha = \theta - \phi$$

$E_b = V$
 $E_b < V$ for lagging p.f is shown in fig ①




$$E_b^2 = V^2 + E_R^2 - 2VE_R \cos(\theta - \phi)$$

fig ①

↳ for normal excitation ($E_b = V$) & for under excitation ($E_b < V$)

$$\begin{matrix} V \& I_a \text{ angle is } \phi \\ E_R \& I_a \text{ " is } \theta \end{matrix}$$

If $E_b > V$ then motor is said to be over excitation & it draws leading current shown in fig ②



$$\theta = \phi + \alpha$$

$$\alpha = \theta - \phi$$

fig ② over excitation I_a leads voltage
 $E_b > V$ for ~~lagging~~ leading p.f

$$E_b^2 = V^2 + E_R^2 - 2VE_R \cos(\theta + \phi)$$

$E_b > V$ for unity p.f shown in fig (3)




fig (3) $E_b > V$
at unity p.f

$$E_b^2 = E_R^2 + V^2 - 2VE_R \cos \theta$$

Problem A 440V, 3 phase star connected synchronous motor has stator resistance / phase 0.1Ω & X_s / phase 4Ω . When loaded it takes 20A from supply mains. Determine back emf developed by armature. If p.f at which motor is operating (i) 0.8 lag (ii) 0.8 leading (iii) unity

sol $V_L = 440V, I_a = 20A$


$$V_p = \frac{V_L}{\sqrt{3}} = \frac{440}{\sqrt{3}} = 254V$$

$$Z_s = R_a + jX_s = 0.1 + 4j = 4 \angle 88.568^\circ$$

$$\theta = 88.568^\circ$$


$$\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right) = 88.568^\circ$$

$$I_a = \frac{E_R}{Z_s} \Rightarrow E_R = I_a Z_s = 20 \times 4 = 80V$$



When P.f is lag at 0.8

39



$$E_b = V \quad \text{①}$$

$$E_b < V$$

Angle b/w E_R & V is $\theta - \phi$

$$\theta - \phi$$

$$\theta = 88.568$$

$$\cos \phi = 0.8$$

$$\phi = \cos^{-1}(0.8) = 36.87$$

Angle b/w E_R & V is $\theta - \phi = 51.69^\circ$

$$E_b = \sqrt{V^2 + E_R^2 - 2VE_R \cos(\theta - \phi)}$$

$$= \sqrt{(254)^2 + (80)^2 - 2(254 \times 80) \cos(51.69)}$$

$$= \sqrt{45,727.067} = 213.84$$

① $E_b > V$ $\cos \phi = 0.8$ leading

Angle b/w E_R & $V = \theta + \phi = 88.568 + 36.87$


$$\phi = \cos^{-1}(0.8) = 36.87 \Rightarrow 125.438^\circ$$

$$E_b^2 = E_R^2 + V^2 - 2VE_R \cos(\theta + \phi)$$

$$= (80)^2 + (254)^2 - 2(80)(254) \cos(125.438)$$

$$E_b = \sqrt{94,480} = 307.38 \text{ V}$$

$$307.38 (E_b) > \underline{V} (254)$$




② $E_b > V$, P.f = 1,

Angle b/w E_R & V is only θ

$$\cos \phi = 1 \Rightarrow \cos^{-1}(1) \Rightarrow \phi = 0$$

$E_b > V$ P.F. = unity



$\phi =$ angle b/w I_a & V is 0, $\theta =$ angle E_R & V

$$E_b^2 = E_R^2 + V^2 - 2E_R V \cos \theta$$

$$= (80)^2 + (254)^2 - 2 \times 80 \times 254 \cos 88.68^\circ$$


$$E_b = \sqrt{691900} = 264.387$$

Phasor diagram of a salient pole synchronous motor

Voltage equation of salient synchronous motor

$$V = E_f + I_a R_a + j I_d X_d + j I_q X_q$$

(a) lagging power factor $\cos \phi$



Phasor diagram for lagging

$\phi = V \angle I_a$
$\psi = E_f \angle I_a$
$\delta = E_f \angle V$

$OA = E_f$, $AG = I_a R_a$, $GH = I_q X_q$, $HF = I_d X_d$
 $OF = V$, $AC = I_q R_a$, $CD = HF = I_d X_d$

$$OD = OA + AC + CD$$

from $\triangle ODF$

$$\cos \delta = \frac{OD}{OF} \Rightarrow \cos \delta = \frac{OD}{V} \Rightarrow \boxed{OD = V \cos \delta}$$

$$V \cos \delta = E_f + I_q R_a + I_d X_d$$

$$GH = CG + CH$$

$$I_q X_q = I_d R_a + V \sin \delta \rightarrow (2)$$

$$\frac{CH}{OF} = \sin \delta$$

$$\phi = \psi + \delta$$

46

$$\psi = \phi - \delta$$

$$I_d = I_a \sin \psi = I_a \sin(\phi - \delta) \rightarrow (3)$$

$$I_q = I_a \cos \psi = I_a \cos(\phi - \delta) \rightarrow (4)$$

$$I_a X_q \cos(\phi - \delta) = I_a R_a \sin(\phi - \delta) + V \sin \delta$$

$$I_a X_q [\cos \phi \cos \delta + \sin \phi \sin \delta] = I_a R_a [\sin \phi \cos \delta - \cos \phi \sin \delta] + V \sin \delta$$

$$I_a X_q \cos \phi \cos \delta + I_a X_q \sin \delta \sin \phi =$$

$$I_a R_a \sin \phi \cos \delta - I_a R_a \cos \phi \sin \delta + V \sin \delta$$

$$\sin \delta (V - I_a R_a \cos \phi + I_a X_q)$$

$$V \sin \delta - I_a R_a \cos \phi \sin \delta - I_a X_q \sin \delta \sin \phi$$

$$I_a X_q \cos \phi \cos \delta - I_a R_a \sin \phi \cos \delta$$


$$\Rightarrow \sin \delta (V - I_a R_a \cos \phi - I_a X_q \sin \phi)$$

$$= \cos \delta [I_a X_q \cos \phi - I_a R_a \sin \phi]$$

$$\frac{\sin \delta}{\cos \delta} = \frac{I_a X_q \cos \phi - I_a R_a \sin \phi}{V - I_a R_a \cos \phi - I_a X_q \sin \phi}$$

$$\tan \delta = \frac{I_a X_q \cos \phi - I_a R_a \sin \phi}{V - I_a R_a \cos \phi - I_a X_q \sin \phi}$$

cb) leading power factor



$OA = E_f$, $AC = I_a R_a$ $CD = I_q X_q$ $DF = I_d X_d$, $OF = V$,

$\delta =$ angle b/w V & E_f

$\phi =$ angle b/w V & I_a

$\psi =$ angle b/w E_f & I_a

from Δ ABC

$$\frac{BC}{AC} = \frac{OPP}{HYP} = \sin \psi$$

$$\Rightarrow BC = AC \sin \psi = I_a R_a$$

\Rightarrow NOW

$$OA = OH + AH = OH + (HB - AB)$$

$$E_f = V \cos \delta + I_d X_d + (-I_q R_a)$$

$$= V \cos \delta + I_d X_d - I_q R_a \rightarrow \textcircled{1}$$

$$\Rightarrow HF = BD \Rightarrow BC + CD$$

$$V \sin \delta = I_d R_a + I_q R_a \rightarrow \textcircled{2}$$

$$\psi = \phi + \delta$$

$$I_d = I_a \sin \psi = I_a \sin(\phi + \delta) \rightarrow \textcircled{3}$$

$$I_q = I_a \cos \psi = I_a \cos(\phi + \delta) \rightarrow \textcircled{4}$$

from HAB

$$HB = AH + AB$$

$$\boxed{AH = HB - AB}$$

\Rightarrow from Δ OFH

$$\cos \delta = \frac{\text{adj}}{\text{HYP}} = \frac{OH}{OF}$$

$$\cos \delta = \frac{OH}{V}$$

$$\boxed{OH = V \cos \delta}$$

from line BCD

$$BD = BC + CD$$

\Rightarrow from Δ OFH

$$\sin \delta = \frac{HF}{OF}$$

$$HF = V \sin \delta$$

Substitute equation 3, 4 in equation ②

$$V \sin \delta = I_a R_a \sin(\phi + \delta) + I_a X_q \cos(\phi + \delta) \quad 47$$

$$= I_a R_a [\sin \phi \cos \delta + \cos \phi \sin \delta] + I_a X_q \begin{bmatrix} \cos \phi \cos \delta - \\ \sin \phi \sin \delta \end{bmatrix}$$

$$V \sin \delta = I_a R_a \sin \phi \cos \delta + I_a R_a \cos \phi \sin \delta + I_a X_q \cos \phi \cos \delta - I_a X_q \sin \phi \sin \delta$$

$$V \sin \delta + I_a X_q \sin \phi \sin \delta - I_a R_a \cos \phi \sin \delta = I_a R_a \sin \phi \cos \delta + I_a X_q \cos \phi \cos \delta$$

$$\sin \delta \left[V + I_a X_q \sin \phi - I_a R_a \cos \phi \right] = \cos \delta \left[I_a R_a \sin \phi + I_a X_q \cos \phi \right]$$

$$\frac{\sin \delta}{\cos \delta} = \tan \delta = \frac{I_a R_a \sin \phi + I_a X_q \cos \phi}{V + I_a X_q \sin \phi - I_a R_a \cos \phi}$$


③ unity power factor

$$\cos \phi = 1 \text{ if } \phi = 0$$

$\sin \phi = 0$ in lagging p.f

$$\tan \delta = \frac{I_a X_q}{V - I_a R_a}$$

$$\psi = \phi + \delta$$




Effect of change in load at constant excitation 48

When the motor is on no load, motor field slightly falls back in phase with stator field. If the motor is lightly loaded by keeping field excitation constant, motor falls back more in phase with stator field by a larger phase angle. Due to this more armature drawn by motor to develop torque in order to meet increasing load.

Effect of load in synchronous motor is explained in 3 ways of excitation

(i) normal excitation ($E_b = V$) (ii) under excitation $E_b < V$ (iii) Over excitation $E_b > V$.

(i) Normal excitation ($E_b = V$)



By keeping field excitation constant, allow the motor to run with small load, torque angle say d_1 is small, similarly phase angle ϕ_1 b/w V & I_{a1} be small so P.f is high ($\cos \phi_1$)

Now the load on motor slightly increases torque angle increases from d_1 to d_2 , to meet the extra load motor draws more armature current say I_{a2} .


Angle between I_a & V say ϕ_2 increases from ϕ_1 to ϕ_2 , corresponding P.f decreases $\cos\phi_1$ to $\cos\phi_2$. Resultant voltage E_{R2} increases E_{R1} .

Load \uparrow , torque \uparrow , $I_a \uparrow$, $E_R \uparrow$, phase angle $\phi_1 \uparrow$, P.f \downarrow

(2) under excitation ($E_b < V$)

Allow the motor to run with small load by maintaining constant excitation, torque angle say α_1 is small but I_{a1} lags behind the voltage with larger phase angle ϕ_1 . So larger the phase angle means lower the P.f say $\cos\phi_1$.

\rightarrow Now the load on motor slightly increases, torque angle α_2 increases from α_1 to α_2 . To meet the extra load motor develops more torque by drawing more amount of armature current say I_{a2} increases from I_{a1} to I_{a2} . But the phase angle decreases ϕ_1 to ϕ_2 . Resultant voltage increases from E_{R1} to E_{R2} . Due to decrease in angle from ϕ_1 to ϕ_2 power factor increases from $\cos\phi_1$ to $\cos\phi_2$.



Load \uparrow , torque \uparrow , $I_a \uparrow$, $E_R \uparrow$
 angle \uparrow ,
 But P.f \uparrow , phase angle $\phi \downarrow$


$E_b < V$ under excitation (lagging)

over excitation ($E_b > V$)

49
Allow the motor to run with small load by keeping excitation constant. Load angle α_1 is small but current drawn by motor say I_{a1} leads the supply voltage at an angle say ϕ_1 . At light loads phase angle ϕ_1 between I_{a1} & V is larger. So power factor $\cos\phi_1$ is small.

Again add & increase some load on motor, torque angle increases from α_1 to α_2 by drawing more armature current from supply. Here armature current increases from I_{a1} to I_{a2} to meet the extra load. But phase angle decreases from ϕ_1 to ϕ_2 . Resultant P.f increases from $\cos\phi_1$ to $\cos\phi_2$.


So for under & over voltage excitation its power factor increases upto unity.



$E_b > V$ over excitation

Load \uparrow , torque \uparrow , angle \uparrow , $I_a \uparrow$, $E_R \uparrow$
but phase angle $\phi \downarrow$, P.f \uparrow

Effect of variation on armature current & power factor



Consider the synchronous motor in which the mechanical load is constant

fig (a) $E_b = V$ only for 100% excitation. The armature ~~lags~~ current I lags behind V by a small angle ϕ . So angle θ with E_R is fixed by stator

$$\tan \theta = \frac{X_s}{R_a}$$

fig (b) $E_b < V$ excitation is less than 100%.

Here E_R is advanced clockwise by I .

Magnitude of current I increases but its phase angle ϕ increases as a result p.f decreases hence active component $I \cos \phi$ remains same but wattless component decreases.

from fig (c)

50



when $E_b > V$ indicates the overexcited motor. Here E_R is pulled into anticlockwise to I . Now motor is drawing a leading current. The result I may be in phase with V & $\phi = 0$ P.f becomes unity. So current drawn by motor would be minimum.

(1) Magnitude of I_a varies with excitation. The current has large value for both low & high excitation. Variation of armature current with field excitation is known as

(V) Curves

(2) when ~~under~~ ^{under} excited motor runs with lagging P.f & ~~under~~ ^{over} excited motor runs with ~~lagging~~ ^{leading} P.f.

Variation of P.f with excitation is termed as inverted (V) Curves.



An over excited motor can be run with leading power factor. This is useful for phase advancing purposes in industrial loads driven by induction motors.

Both transformers & induction motor draws lagging current from supply. If it is operated at light loads, it draws more reactive power & makes the P.f low.

Different torques a synchronous motor

① Starting torque: It is developed when full voltage is applied stator winding. Also known as break away torque.

② Running torque Motor develops the torque during running conditions. It is determined by horse power & speed of driven machine. Horse power of motor indicate maximum torque.

③ pull in torque

The amount of torque at which the motor will pull into step is called pull in torque.

When speed of synchronous motor is 2 to 5% below the synchronous speed it is acting as induction motor. After excitation is on, rotor pulls into synchronously with rotating stator field.

(d) pull out Torque

51

Maximum torque develops without pulling into step or synchronism is called pull out torque.


Motor develops maximum τ when its rotor is retarded by an angle of 90° .

Any load increased, the motor pulled out from synchronism & stop.

V & inverted V Curves

if load on motor constant, load angle α torque angle remains same. change in excitation result change in back emf

Let the field excitation on motor is gradually increased by maintaining the load on motor constant.



E_R, V moves left side to E_b if I_f increases

Let V be the rated voltage / phase

E_b = back emf

α = load or torque angle

ϕ = phase angle b/w V & I_a

I_a = armature current drawn by motor

θ is angle b/w E_R & V , $\theta = \tan^{-1} \left(\frac{X_s}{R_a} \right)$

E_R = Resultant voltage

Active Current Component = $I_a \cos \phi$

$$P.f = \cos \phi$$

$$\text{Active Power} = V I_a \cos \phi$$

if load on motor is kept constant

$I_a \cos \phi$ is constant

if $I_a \cos \phi$ is constant, V is constant

→ Let I_f on motor gradually increase.

E_b developed by motor ~~decreases~~ increases.

Resultant Voltage E_R moves to left side.

Here I_a lags behind the E_R by angle θ .

→ If E_R moves towards left, I_a moves also towards left as a result angle ϕ progressively decreases.

→ For certain field excitation, I_a is in phase with V then angle ϕ becomes zero.


The P.f at which the motor operates as unity. The field excitation at which the motor operates as unity is termed as normal excitation. ($E_b = V$)

Any field excitation is less than normal excitation is termed as under excitation ($E_b < V$)

Any field excitation is more than normal excitation is termed as over excitation ($E_b > V$)

→ when motor is operated under excitation motor draws lagging current.

→ when motor is operated in over excitation it draws a leading current.



from phasor diagrams

If load on motor kept constant, field excitation increases, I_a , E_b , E_R moves left side to E_b .

If increases, E_b increases corresponding E_R & I_a also increases also p.f. increases from lagging to unity to leading.

Curves drawn between corresponding field current I_f & armature current I_a is known as V-curves fig ①

similarly Curves drawn b/w I_f & p.f. is known as inverted V curves, shown in fig ②




fig ① V-curves

fig ②

- ① → no load
- ② → full load (50%)
- ③ → full load (100%)
- ④ → unity p.f

V curves can be drawn at different loads from no load to full load.

Synchronous Condenser


An over excited synchronous motor is termed as synchronous condenser. During this case motor draws leading current from supply & operates at leading power factor.

A synchronous motor running no load is also a (over excited motor) synchronous condenser. This has a capability to generate or absorb reactive power in lines.

In any power s/m most of the loads are reactive power loads like transformers, induction motors, current limiting reactors etc. These devices draw lagging current from supply and makes the power factor ~~high~~ is low.

If reactive component of power is quite large, same amount of power is supplied to the lines, to make the power factor high. such leading power devices is a synchronous condenser. These can draw a leading current from the supply.

If the field winding of synchronous motor is overexcited by a d.c source then it supplies reactive power in opposite direction to the lagging devices load. This is used below 500KVAR is not at all economical.



$$I = I_L + I_m$$




Fig synchronous motor & its phasor diagram

Problem A synchronous motor taking 50kW from mains connected in parallel with factory load 250kW having 0.8 p.f lagging. The combined load has 0.9 p.f lagging. Find leading kVA supplied by motor & p.f at which it is operating.

Sol
 Power consumed by synchronous motor = 50kW
 " " " " factory load = 250kW

Before installation of synchronous motor p.f is 0.8 lagging $\cos\phi_1 = 0.8$

After installing synchronous motor p.f is 0.9
 $\cos\phi_2 = 0.9$

→ lagging Reactive (KVA) power drawn by factory load is at 0.8 p.f lagg

$$\tan\theta = \frac{\text{KVAR}}{\text{KW}}$$

$$\cos\phi_1 = 0.8$$

$$\text{KVAR} = \tan\theta_1 * \text{KW}$$

$$\phi = \cos^{-1}(0.8)$$

$$= \tan(36.87) * 250 \quad \phi = 36.87$$

$$\text{KVAR} = 187.5$$

of factory load.

⇒ Total Combined load in kW is

$$= (\text{factory load} + \text{synchronous motor load}) \text{ in kW}$$

$$= 250 + 50 = 300 \text{ kW}$$

p.f of Combined load = 0.9 lag

→ lagging Reactive (KVA) power of Combined load at 0.9 p.f is

$$\cos\phi_2 = 0.9 \Rightarrow \phi_2 = 25.842^\circ$$

$$\text{KVAR of combined load} = \text{KW} * \tan \theta_2$$

$$= 300 * \tan(25.842)$$

54

$$\text{KVAR of Combined load} = 145.3 \text{ KVA}$$

Here P.f is increased from 0.8 to 0.9 by the synchronous motor

⇒ leading Reactive (KVA) of synchronous

$$\text{motor} = \boxed{\text{KVAR of factory} - \text{KVAR of combined load}}$$

$$= 187.5 - 145.3 = 42.2 \text{ KVAR (leading)}$$

cb) To find the P.f of synchronous motor

$$\tan \theta_m = \frac{\text{leading KVAR of sim}}{\text{Power consumed of sim}}$$

$$= \frac{42.2}{50} = 0.844$$

$$\phi_m = \tan^{-1}(0.844) = 40.164$$

$$\text{P.f} = \cos \phi_m = \cos(40.164) = 0.7642$$


KVA taken by synchronous motor is

$$\text{KVA} = \sqrt{(\text{KW})^2 + (\text{KVAR})^2}$$

$$= \sqrt{(50)^2 + (42.2)^2}$$

$$= 65.428$$

KVA of synchronous motor



Problem A factory load 4000 kW is connected to 11 kV at 0.8 P.f lagging. An additional load of synchronous motor ^{1500 HP} is connected in parallel factory load lbs P.f is 0.95 lagging. The efficiency of motor is 80%.

- (1) Determine the KVA Capacity of motor
- (2) P.f of the motor to operate

Sol power consumed by factory load = 4000 kW

P.f of factory load $\cos \phi_1 = 0.8$ lag

Capacity of synchronous motor is o/p of

motor = 1500 HP

$$1 \text{ HP} = 735.5 \text{ W}$$

$$\text{o/p of motor} = 1500 * 735.5 \text{ W}$$

$$= 1103.250 \text{ kW}$$

also given efficiency of motor = 80%.

we know that

$$\eta = \frac{\text{o/p}}{\text{i/p}} \Rightarrow \boxed{\text{i/p} = \eta * \text{o/p}}$$

$$\boxed{\text{i/p} = \frac{\text{o/p}}{\eta}} = \frac{1103.250}{0.8} = 1379.062 \text{ kW}$$

$$\Rightarrow \text{Total Combined load in kW} = \left(\begin{array}{l} \text{motor} \\ \text{load} \end{array} + \begin{array}{l} \text{factory} \\ \text{load} \end{array} \right)$$

$$= 1379.062 + 4000 = 5379.062 \text{ kW}$$

P.f of Combined load is 0.95 lagging

$$\cos \phi_2 = 0.95$$

\Rightarrow lagging Reactive (KVA) power of factory load

$$\text{KVAR} = \text{KW} * \tan \theta_1$$

$$\cos \phi_1 = 0.8 \Rightarrow \phi = 36.87$$

$$\begin{aligned} \text{KVAR of factory load} &= 4000 * \tan(36.87) \\ &= 3000 \text{ KVA} \end{aligned}$$

\Rightarrow lagging reactive power of ~~combined load~~ ^{combined load}

$$\begin{aligned} \text{KVAR of synchronous motor} &= \frac{5379.062}{\cos \theta_2} * \tan \theta_2 \\ &= \frac{5379.062}{0.95} * \tan(18.195) \end{aligned}$$

$$\cos \theta_2 = 0.95$$

$$\theta_2 \Rightarrow 18.195$$

$$= 1768.026 \text{ KVA}$$

$$\text{KVAR of Combined load} = 1768.026 \text{ KVA}$$

After installing the synchronous motor its P.f raises from 0.8 to 0.95 lag

① \Rightarrow leading reactive (KVA) power drawn by synchronous motor = KVAR of factory load - KVAR of combined load

$$\begin{aligned} \text{leading KVAR syn motor} &= 3000 - 1768.026 = 1231.974 \end{aligned}$$

(ii) To find the P.f of synchronous motor

$$\tan \theta_m = \frac{\text{KVAR of s.m leading}}{\text{KW of s.m}}$$

$$= \frac{1768.026}{1379.062} = 1.2820$$

$$\theta_m = \tan^{-1}(1.2820)$$

$$\text{P.f} = \cos \theta_m = \cos[\tan^{-1}(1.2820)]$$

Hunting in synchronous machine

We know that as the load on motor increases, rotor falls back in phase. Coupling angle δ also increases but motor continues to run at synchronous speed. It is because of magnetic interlocking b/w stator & the rotor poles.

If load on motor reduces, the rotor falls advance in phase, δ (load or torque or power or coupling angle) decreases during this condition motor develops only electromagnetic torque.

During no load condition rotor poles coincides with the stator poles. This creates a magnetic locking b/w stator & rotor which tends to rotate the rotor at synchronous speed.

During load condition, if we increase the load in steps, magnetic interlocking b/w stator & rotor decreases to overcome this rotor draws more current to develop torque. Here electric magnetic torque is equal to & opposite to load torque.

If a part of load is suddenly thrown off, rotor need not develop much torque as a result, rotor falls advances in phase with coupling angle. The speed of the rotor is not decreased but its speed increases above the synchronous speed. To avoid these rotor is provided with damper winding. It is due to large inertia of rotor, the rotor tends to oscillate in new equilibrium position.

new equilibrium position.

56

The phenomenon of rotor tends to oscillate in new equilibrium position due to inertia is termed as hunting.

causes of hunting in synchronous motor.

- ① sudden change in load
- ② sudden change in field current
- ③ fault in supply s/m.
- ④ Load torque contains harmonics

Effects of hunting

- ① Make the machines to loose synchronism
- ② Causes a variations in supply
- ③ creates a mechanical resonance in rotor
- ④ increases mechanical stress in rotor shaft
- ⑤ Increases mechanical losses as well as increasing the machine temperature

minimizing or Reduction of hunting

Hunting in synchronous machines can be reduced using

- ① Dampers windings (2) use of flywheels

2nd method uses a flywheel provided with the prime mover. This increases the inertia of prime mover & helps in maintaining speed constant

using Dampers windings

Dampers windings is a low resistance copper bars embedded in the slots of salient pole machine. The windings is short circuited. When hunting takes place, an emf is induced

in the damper winding. Due to relative motion b/w damper winding conductors & rotating stator magnetic field a torque is produced. This torque opposes direction of rotor. Thus the oscillations in rotor reduces gradually.

In absence of emf is induced in rotor damper winding. Damper windings can also help the synchronous motor as started as a induction motor.

Methods of starting of synchronous motor

Synchronous motor is not a self starting motor. Different starting methods are adopted to start the synchronous motor. These are

- ① using Damper windings
- ② using pony motor
- ③ using a d.c motor.

using Damper windings

Damper windings are used for high ratings of synchronous machines. These windings placed in the slots of rotor poles. All these windings are short circuited to carry currents to develop a torque.

When 3 phase A.C supply is given to stator, a rotating magnetic field is set up in stator. This rotating flux cuts the stationary damper winding conductors. An emf is induced in the damper winding. This emf induces a current in the damper windings produces a torque. This torque tends to rotate rotor at near the synchronous speed.

Now DC excitation is applied to the field winding of rotor develops a rotor poles. The rotor also tends to rotate in the same direction of stator field at synchronous speed. Due to ~~stator~~ rotor poles coincides with stator fields poles, a magnetic locking will take place & continuously to run at synchronous speed.

thus a synchronous motor at the starting acts as induction motor & runs as synchronous motor during d.c excitation.

② using pony motor

Pony motor is a small a.c. motor driven at synchronous speed.

This is connected to the rotor of synchronous motor through a belt.

When 3 phase supply given to stator, a rotating magnetic field is set up which cuts the field ~~PHASES~~ ^{winding} of rotor. Here rotor is driven by a small ac motor at synchronous speed, the rotor develops rotor poles that creates a magnetic locking with the stator poles which can continuously run the rotor at synchronous speed.

The supply to the pony motor is disconnected it can continuously run at the synchronous speed.

(3) using a DC motor

In this method, first run the synchronous motor as alternator which can be driven by DC motor mounted on the shaft.

Here alternator is properly synchronised with the bus bar supply. If the external supply for the DC motor is removed, the alternator continues to run at synchronous speed which takes power from bus bar.

Here the synchronous motor started as slip ring induction motor since starting torque is high & damper winding does not form a short circuit. These slip rings are connected to external rheostat ^{along} with damper windings.

Single phase and Special Machines

Unit - 5

Machines - III

Single phase motors

These are also called as induction motors or AC motors. There are of 3 phase induction motors and single phase induction motor.

3 phase induction is inherently self starting motor whereas single phase is inherently NOT self starting. Single phase does not develop a unidirectional starting torque. To start the motor it is to be converted into 2 phase motor at starting.

If an AC supply is given to single phase AC motor, the torque cannot put rotor into motion. However a slight push is given to rotor, the rotor begins to run in that direction. So single phase doesn't develop the starting torque, that's why it is inherently ^{not} self starting.

Construction

Its construction is similar to 3 phase induction motor.

① Its stator is provided with 1-phase AC supply. Also it consists of centrifugal switch which is used to separate the winding during starting purpose.


Stator is provided with slots in the inner periphery to provide a low resistance stator conductors.

Here the rotor is invariably a squirrel cage type. To start the motor, we convert the single phase into 2 phase motor it requires an auxiliary winding called starting winding is mounted on stator.

Here the auxiliary winding is a high resistance winding placed in upper slots of stator. provided with a centrifugal switch.

The centrifugal switch separates auxiliary winding from main winding during starting if rotor speeds upto 75% of rated speed.

Here the auxiliary winding is connected in parallel with main winding. To change the direction of rotor, the polarities of auxiliary is changed.



Here the stator uses a distributed windings.

working

1- ϕ phase induction motor is inherently not self starting motor.

When the power to stator is on, stator develops an alternating flux because of ac currents. This alternating flux links with stator conductors induces an emf in rotor conductors. Due to the stator flux & rotor induced currents a torque will be produced.



Rotor currents develops the N & S polarities such with respected to stator N & S pole.

Here rotor conductors in the upper $\frac{1}{2}$ comes under stator N pole, rotor conductors in lower $\frac{1}{2}$ comes with stator pole.

Rotor under N pole of stator develop a torque to rotate the rotor one direction

Rotor under S pole of stator develops a torque tends to rotate in another direction.


The 2 torques are equal & opposite then net torques becomes cancel out. Their fore net torque becomes zero so rotor remains stationary.



The analysis of single phase can be made on 2 theories. (1) Double field (2) cross field theory.

Double Revolving field theory


stator has a large no. of slots provided with distributed windings generates an alternating flux. The net amount of flux is splitted into 2 equal halves having opposite directions at synchronous speed.



considered 2 fluxes, each has $\phi_m/2$ maximum value.

Let flux phase OA + OB rotates in opposite directions at synchronous speed

$N_s = \frac{120f}{P}$. If OA has moved by making some angle say θ , OB also moved by making some angle $-\theta$.



Let $\phi = \phi_m \cos \alpha$

if $\alpha=0$, then sum of fluxes


$$\phi = \frac{\phi_m \cos(0)}{2} + \frac{\phi_m \cos(0)}{2}$$

$$\phi = \phi_m$$

if $\alpha=\theta$ then sum of fluxes is

$$\phi = \frac{\phi_m \cos \theta}{2} + \frac{\phi_m \cos \theta}{2} = \phi_m \cos \theta$$

if $\theta=\alpha$, $\phi = \phi_m \cos \alpha$




if $\alpha = 90^\circ$ then projections of OA + OB are in direct opposition

$$\phi = \phi_m \cos 90$$

$$\phi = \frac{\phi_m \cos 90}{2} + \frac{\phi_m \cos 90}{2} = 0$$

Sum of fluxes on X-axis is zero.


if $\alpha = 180^\circ$



phasors OA + OB are in phase and each is equal to $-\frac{\phi_m}{2}$ $\phi = \phi_m \cos(180) = -\phi_m$

$$\text{sum of fluxes } \phi = -\frac{\phi_m}{2} - \frac{\phi_m}{2} = -\phi_m$$

if $\alpha = 270^\circ$



$$\phi = \phi_m \cos \alpha$$

$$\text{if } \alpha = 270$$

$$\phi = \phi_m \cos(270) = 0$$

phasor projections on X-axis is 0 since $\phi = 0$

if $\alpha = 360^\circ$

$$\phi = \phi_m \cos \alpha$$

$$\phi = \phi_m \cos(360) = \phi_m$$

$$\phi = \frac{\phi_m}{2} + \frac{\phi_m}{2} = \phi_m$$




Fig shows instantaneous value of flux, against α the curve is indicated.

At slip ($s=1$), T_f & T_b are equal in magnitude but T_R becomes zero at $s=1$.

$$\text{Power } P_g = \omega \times T_g$$

$$\text{Power developed by rotor } P_g = \left(\frac{1-s}{s}\right) I_2^2 R_2$$

$$T_g = \frac{P_g}{\omega} = \frac{\left(\frac{1-s}{s}\right) I_2^2 R_2}{\frac{2\pi N}{60}} = \frac{60 \times \left(\frac{1-s}{s}\right) I_2^2 R_2}{2\pi N}$$

if 60 is assumed constant

$$T_g = \frac{\left(\frac{1-s}{s}\right) I_2^2 R_2}{2\pi N} = \frac{N}{sN_s} \times \frac{I_2^2 R_2}{2\pi N}$$

$$T_g = \frac{1}{2\pi N_s} \times \frac{I_2^2 R_2}{s} = K \times \frac{I_2^2 R_2}{s}$$

$$K = \frac{1}{2\pi N_s}$$

$$\text{forward torque } T_f = K \times \frac{I_2^2 R_2}{s} \text{ synch coat}$$

$$\text{backward torque } T_b = -\frac{K \times I_2^2 R_2}{(2-s)} \text{ synch coat}$$


$$T_R = T_f + T_b$$

$$T_R = K \times I_2^2 R_2 \left[\frac{1}{s} - \frac{1}{(2-s)} \right]$$

Rough

$$= \frac{(2-s) - s}{s(2-s)} = \frac{2-2s}{s(2-s)} = \frac{2(1-s)}{s(2-s)}$$

cross field theory



According to this theory, stator flux is divided into 2 perpendicular components. One along the axis of stator winding & other perpendicular to it.

Considered the above the fig, coils 1-2 & 3-4, flux ϕ_y is perpendicular to coils 1-2, whereas flux ϕ_x is along the axis of coils 3-4.

The flux ϕ_x linking the coil 3-4 induces an emf will set up a current in the coil 3-4. The current in the coil 3-4 will set up an mmf is in opposition to mmf setting up the flux ϕ_x . Thus phase displacement b/w 2 mmf's is 180° . Hence there is no torque.

If a slight initial push is given to rotor when power is on, flux ϕ_x cuts across coil 1-2 a dynamically induced emf is set up in the coil

Due to interaction b/w ^{flux} ϕ_y & current in coil 3-4 & between flux ϕ_x & current in coil 1-2, a torque is produced. This torque speeds up the rotor. Hence rotor continues to run in initial push direction.

Methods of starting induction motor


Single phase induction motor is inherently not self starting motor. If rotor is pushed in any direction by hand, it would continue to run in that direction.

The most common method of starting single phase motor is by converting temporarily into 2 phase motor.

Depending on suitable mechanism, single phase motors are classified as 2 types


① split phase motors

② shaded pole motor



Split phase motors

① Resistance split phase motor



- 1 → main winding
- 2 → auxiliary winding
- S → Centrifugal switch
- R → Squirrel Cage rotor.

- ① Stator consists 2 windings ① main winding
2 ② Auxiliary or starting winding.

Main winding has low resistance & high inductance path where as auxiliary winding has high resistance & low inductance. 2 windings are connected in parallel.

The phase displacement b/w 2 windings is 90° . There is a centrifugal switch connected in series with auxiliary winding. Here rotor is of squirrel cage type.


If a supply is given to stator from single phase a.c source, current I_m & I_s flows in main & auxiliary windings creates large phase angle b/w them. A rotating field is setup in rotor develops driving torque.

If rotor reaches 75% of synchronous speed the centrifugal switch opens out. It separates the auxiliary winding & the motor continues to run as single phase motor.

The direction of rotation can be changed by reversing the connections of auxiliary winding.

These motors used in Centrifugal Pumps, fans, blowers, etc. Range is 0.5 HP - $\frac{1}{20}$ HP

⑧ Capacitor-start motor



1 → main winding
 2 → auxiliary or starting winding
 3 → S Centrifugal switch

R → squirrel cage motor

C → electrolytic Capacitor. is used only for starting purpose.

Construction is similar to

split phase motor. Here an electrolytic Capacitor 'C' is connected in series with

the auxiliary winding through

switch 'S'. Starting Procedure is similar

to split phase motor. When rotor runs 75% of synchronous speed Centrifugal switch opens by separating the auxiliary winding.

Because of Resistance to reactance of 2 windings is different & a large phase angle, the motor develops high starting torque compared to split phase motor.

Its available range is $\frac{1}{8}$ HP to $\frac{3}{4}$ H.P

Capacitor - start Capacitor - run motor

This is also similar to Capacitor start induction motor. Here stator carries 2 windings (1) main and (2) auxiliary or starting winding. Both Auxiliary & main windings remain in operation.


Here 2 capacitors C_1 & C_2 are used in parallel with auxiliary or starting winding.

Here C_2 is connected in series with the centrifugal switch. and is parallel with capacitor C_1 .

C_1 & C_2 are designed to develop high starting torque. When motor speed reaches 75% of synchronous centrifugal switch (S) opens and disconnects the capacitor C_2 .


C_1 is designed for continuous duty during running it improves power factor & efficiency of motor. As a result starting torque of motor is high.

It is widely used in compressors, blowers, conveyors, centrifugal pumps. Its ranges is from $\frac{1}{8}$ HP to $\frac{3}{4}$ HP



- 1 → main winding
- 2 → auxiliary winding
- C_1 & C_2 are capacitors
- S → centrifugal switch
- R → squirrel cage rotor

② Shaded pole motor



It consists of a squirrel cage rotor and a stator consists of salient poles.


Each pole of stator wound by a excitation coil. It is supplied from a single phase AC source.

Each salient pole in stator is splitted into 2 equal halves. Each half pole of salient is called as shaded pole. Each half pole is wrapped with copper band called as a shading band shown in above figure. These shading band forms as short circuit.

If single phase supply is given to stator, a rotating alternating flux is set up. This flux links with shading band induces an emf which inturns induces a current in the shading band because shading band forms as short circuit.

According to lenz's law direction of induced emf & the direction of current in shaded band must oppose each other. As a result flux in shaded pole reduces. This gives a

a small starting torque.



Limitations

- * The starting torque of motor is low
- * Efficiency is low
- * There is no chance to change the direction of rotor by reversing

Applications

* Domestic toys * small fans, hair driers, also where some applications require low starting torque

Single phase series motor

A series motor which can work on both AC + DC supply. Such motor is also called universal motor.

Construction

It consists of a field winding mounted on salient pole fixed to the yoke.

The outer part of armature is provided with slots where armature windings are accommodated. All the armature windings are connected to the commutator and is connected to the brushes.

Here field & armature windings are connected in series to carry same current.

If motor is provided with dc supply, a flux will set up in field winding and set up a current in armature winding. Due to interaction b/w field flux & current in armature a torque will develop.

If motor is provided with AC supply, ac currents flow in both field & armature windings. But the direction of currents reverse. This results a pulsating torque is converted into unidirectional torque due to ~~commutator~~. Commutator. Thus an AC series motor works ^{on} AC supply also.


Demerits of AC series motor

- * starting torque is low
 - * Power factor is low
 - * Efficiency is low
 - * Severe sparking at brushes results power loss
 - * Hysteresis & eddy current losses is high
- to reduce both stator & rotor are fully laminated

— * — * —

Sparking at brushes is eliminated using a high resistance carbon brushes & interpoles are used.

Low power factor in AC series motor is minimized by using compensating windings. This winding is connected in series with armature winding.




MMF Produced by Compensating winding balances the mmf Produced by the armature. Hence it neutralises. This Compensating winding is a low reactance winding.

universal motor (UM)

It is a series motor which works on both

AC & DC supply. But this motor does not have Compensating winding.




The operating speed is quite high from 7000 - 20,000 rpm - this is small in size & less weight. The no load speed of rotor is limited to a safe value by considerable amount of windage & frictional loss.

Also load torque is quite small. Commutation problems are absent because armature winding carries a small current.

Applications

- * vacuum cleaners, hair driers, drill machines, shavers, food mixers, sewing machines etc.



characteristics of universal motor.

Single phase synchronous motor (unexcited - type)

A revolving magnetic field produced in synchronous motors from a single phase source by use of same method in single phase Induction motors. It is a self starting motor.

Here also consists of 2 windings (1) main field winding (2) auxiliary or starting winding with a capacitor.

Main winding is fed to single phase ac supply. An auxiliary winding of high resistance is employed.

single phase synchronous motors are constant speed machines. These motors are simple in construction but it does not require dc excitation. Thus we called as unexcited motor.

These are classified as 2 types

- (i) Reluctance motor
- (ii) Hysteresis motor

Reluctance motor

single synchronous reluctance motor is same as single squirrel cage type induction motor




fig ①
4 pole
Reluctance motor
1

* It has 2 windings

main & auxiliary or starting stator windings.

* The rotor of reluctance motor is basically a squirrel cage with some rotor teeth is removed at appropriate places. to get desired number of salient poles.


Fig ① shows 4 pole reluctance motor here teeth are removed at four locations to produce 4 pole salient pole machine. The remaining teeth can carry copper bars and form as short circuit. to the end rings.

The motor is starting by providing single phase supply to stator, motor starts as induction motor. As motor reaches 75% of synchronous speed centrifugal switch opens & disconnects the auxiliary winding.

When rotor speed reaches synchronous speed a reluctance torque is produced. This torque pulls the rotor into synchronism. It is depending load inertia.

If rotor reaches synchronous speed then induction torque disappears & motor continues at synchronous speed.

torque - speed characteristics of reluctance motor




Starting torque depends on position of rotor. The reluctance torque depends on torque angle $\alpha = 45^\circ$. The value is in b/w 300-400% of full load. If rotor speeds close to synchronous speed, rotor develops reluctance torque which can keep the motor into synchronism.

The motor operates at constant speed over 200% of its full load torque. If loading increases above 200% of pull load torque, the motor loses synchronism & motor runs as Induction motor. This is due to starting of Reluctance motors are undergoes Cogging. Cogging in reluctance motors are minimized by skewing the rotor.

Advantages of Reluctance motor

- Construction is simple
- low cost
- maintenance is low
- no slip rings
- no brushes
- no d.c field winding

fig
Reluctance motor



Disadvantages

- * Power factor is low
- * O/P of reluctance motor is greatly reduced due to absence of field winding
- * The size of reluctance motor is larger than synchronous motor.

Applications

- * electric clock timers
- * used in signalling devices
- * recording instruments
- * used in phonographs
- * also used for constant speed applications.

Hysteresis motor

Basically synchronous motor with uniform air gap without field winding.

It can operate either on single phase & 3 phase supply.

Torque developed in this is due to hysteresis & eddy currents induced in rotor.

Construction of Hysteresis motor

stator is connected to either single phase or 3 phase supply. If 3 phase supply is given to stator it produces a uniform rotating field. If single phase supply, stator winding is provided with split capacitor type with an auxiliary winding is used to produce uniform field.

Rotor Construction

The rotor of hysteresis motor is made of magnetic non magnetic materials which is a smooth cylinder and it does not carry any field winding.

In small rotor a solid ring is used which is made up of special magnetic material such as chrome or Co-bolt steel having very large hysteresis loop.




fig ① Rotor of hysteresis motor




fig ② various hysteresis loop




Fig ③ Magnetic field in hysteresis motor

If either 3 phase or single phase AC supply is given to stator, a rotating magnetic is set up in stator.

This magnetic field magnetizes the rotor ring which is made of magnetic material and develops a poles in it.

The flux in the rotor ring lags behind the stator flux, it is due to hysteresis loss in rotor.

Consider above fig ③

Let $B_s \rightarrow$ stator magnetic field

$B_R \rightarrow$ Rotor " "

$\delta \rightarrow$ angle b/w stator field axis & rotor field axis

The angle δ is responsible for the production of torque. δ depends on shape of hysteresis loop.

An ideal material would have rectangular loop shown in loop 1 fig ①.

loop 3 is for ordinary steel, which is not suitable for hysteresis motor

loop ② is approximately similar to loop ①
 since the materials here are used for hysteresis
 motor hard cobalt.

Torque in the rotor is due to magnetic
 field in rotor also produce additional
 currents called eddy currents.

eddy current loss is given by

$$P_e = K_e f_2^2 B^2$$

P_e = eddy current loss

K_e = " " Constant

f_2 = frequency of rotor eddy currents

B = flux density

$$f_2 = sf_1$$

where s = slip, f_1 = stator frequency

$$P_e = K_e s^2 f_1^2 B^2$$

Torque is given

$$\gamma = \frac{P_e}{s\omega_s} \Rightarrow K' s$$

where $K' = \frac{K_e s^2 f_1^2 B^2}{s\omega_s} = \frac{K_e s f_1^2 B^2}{\omega_s}$

Torque due to hysteresis loss

Hysteresis loss is given by

$$P_h = K_h f_2^{\alpha} B^{1.6} = K_h s f_1 B^{1.6}$$

Torque is given by

$$\gamma = \frac{P_h}{s\omega_s} = \frac{K_h f_1 B^{1.6}}{\omega_s} = K''$$


$$T_e = K' s = \frac{1}{N} \quad K' = \frac{K_e f_i^2 B^2}{\omega_s}$$

eddy Current Torque is proportional slip

as torque decreases speed increases

because slip decreases: If motor speed N reaches N_s then slip becomes zero & Torque T_e is zero. Here the machines continue to run as permanent magnet motor.

Torque speed characteristics



ideal characteristics is due to presence of harmonics. Torque developed by an induction motor is zero at synchronous speed.

where as for hysteresis motor torque is constant at all speed including N_s .

Applications

- it is also used low noise devices
- Also used sound reproduction equipments like record players, tape recorders
- Also used in electric clocks.

Stepper motors

Also known as stepping motor. The rotor moves through a definite angle for each pulse applied to the stator.

The pulse can be adjusted by selecting suitable number of stator phases & rotor poles.

Speed of motor depends on the number of pulses actuating the rotor.

Stepper motors are used where incremental motion is required. These are used in printers, plotters, tapdrives, numerically controlled devices.

Stepper motor mainly consists of stator & rotor. A set of train pulses are applied to the stator develops a torque on rotor to move certain angle.

These are classified as 2 types

① variable reluctance

② Permanent magnet




Fig ① 4 phase 2 pole variable reluctance motor

The principle is based on flux linkages. Here flux lines occupies the low reluctance path, such that stator & rotor alignment minimizes the magnetic reluctance.

Here both stator & rotor are provided with same number of teeth. Also the alignment of stator teeth & rotor teeth must be perfect so as to reduce the reluctance.

If stator is excited by unidirectional pulse current, it produces a torque and at every instant of incident pulse the rotor exhibits oscillatory behaviour. Hence there must be ~~adequate~~ adequate damping provided in motor.



In Practical a stator has several stacks also called stator phases. These stator phases are energized sequentially by applying pulse voltages. For every voltage pulse each of stator phase energizes, the result is rotor moves forward rapidly with some angle.

Here rotor angle depends on the pulse applied to energize the stator.

if $T =$ number of teeth

$N_s =$ no. of stacks

then angular displacement $\beta = \frac{360^\circ}{N_s * T}$



ABC are stator stacks, each stack has 2 teeth, Each stator phase teeth is facing to rotor also, have 2 teeth

fig (a) variable reluctance stepper motor, fig (b) variable reluctance with stator & rotor teeth arrangement.


If stepper motor is loaded, The pulse voltages are applied to stator stack at a finite rate, the rotor follows command and drives the load to next position.

The maximum stepping rate is around 1200 pulses per second.

(b) Permanent magnet stepper motor

In this type of motor, stator carries several windings. These windings are wound for any number of poles.

The rotor has definite number of permanent magnet poles. The rotor is a salient pole type which is made up of ferrite material & they are project out of the rotor core.



Here all the stator windings S1, S2, S3, S4 are excited from single phase ac source.

Here each winding get excited one after other sequentially.

Due to interaction in stator fluxes & rotor fluxes, a torque is developed in rotor to rotate. This continues until the stator axis & rotor axis come in same alignment.

For each excitation of stator winding, the rotor moves certain angle, for each excitation of stator. Desired angle can getting

Equivalent circuit of single phase I.M

By conducting No load & Blocked rotor test by drawing its equivalent circuit.

Equivalent circuit of I.M depends on double field revolving theory. Let stator impedance $Z_1 = R_1 + jX_1$ & impedance of rotor is $R_2 + jX_2$. Where R_2 & X_2 are equal to half of standstill Resistance = $R_2'/2$ & standstill reactance = $X_2'/2$.




fig (a) shows if rotor is completely blocked looks like transformer with end winding short circuited.

fig (a): equivalent of single IM at standstill.

* From double field theory two fluxes in stator winding induces emf as E_{mf} & E_{mb} . $V = E_{mf} + E_{mb}$. At standstill magnetizing & rotor impedances are divided into 2 equal halves connected in series shown in fig (b)




fig (b) shows Equivalent of single phase IM at standstill based on double field theory.

fig (b)

When motor is running at speed N with respect to forward field the slip is ' s ' & same motor is running with respect to backward field the slip is $(2-s)$. Then the equivalent circuit under normal running conditions is fig (c).




fig (c): Equivalent circuit of single I.M under normal running condition with forward & backward slip.

If core losses is neglected then circuit is fig (d)




fig (d) Equivalent circuit under running condition without core

Stator impedance $Z_1 = R_1 + jX_1$

Total equivalent impedance $Z_{eq} = Z_{01} = Z_T = Z_1 + Z_f + Z_b$

⇒ forward field impedance $Z_f = \left(\frac{R_2'}{2s} + \frac{jX_2'}{2} \right) \parallel \frac{jX_m}{2}$

$$Z_f = \frac{\frac{jX_m}{2} \left[\frac{R_2'}{2s} + \frac{jX_2'}{2} \right]}{\frac{R_2'}{2s} + j \left[\frac{X_m + X_2'}{2} \right]}$$

⇒ Backward field impedance $Z_b = \left(\frac{R_2'}{2(2-s)} + \frac{jX_2'}{2} \right) \parallel \frac{jX_m}{2}$

$$Z_b = \frac{\frac{jX_m}{2} \left[\frac{R_2'}{2(2-s)} + \frac{jX_2'}{2} \right]}{\frac{R_2'}{2(2-s)} + j \left[\frac{X_m + X_2'}{2} \right]}$$

⇒ Motor Current $I_1 = \frac{V}{Z_{eq}} = \frac{V}{Z_1 + Z_f + Z_b}$

⇒ power factor $\cos \phi = \frac{R_{eq}}{Z_{eq}} = \frac{R_1 + R_f + R_b}{Z_1 + Z_f + Z_b}$

$$R_f = \frac{R_2'}{2s}, \quad R_b = \frac{R_2'}{2(2-s)}$$

⇒ forward emf $E_{mf} = I_1 * Z_f$

backward emf $E_{mb} = I_1 * Z_b$

⇒ $I_{2f}' = \frac{E_{mf}}{\sqrt{\left(\frac{R_2'}{2s} \right)^2 + \left(\frac{X_2'}{2} \right)^2}}, \quad I_{2b}' = \frac{E_{mb}}{\sqrt{\left(\frac{R_2'}{2(2-s)} \right)^2 + \left(\frac{X_2'}{2} \right)^2}}$

⇒ Gross power developed in forward field

$$P_{gf} = (I_{2f}')^2 * \left(\frac{R_2'}{2s} \right) \text{ watt}$$

$$P_{gb} = (I_{2b}')^2 * \left(\frac{R_2'}{2(2-s)} \right) \text{ watt}$$

⇒ Torque developed in forward field

$$T_f = K * (I_{2f}')^2 * \frac{R_2'}{2s} = K = \frac{1}{2\pi N_s} \text{ or } \frac{P_{gf}}{\omega_s}$$

$$N_s = \frac{N_p}{60}$$

Torque developed in Reverse field

$$T_b = \frac{P_{gb}}{\omega_s} = K * (I_{2b}') * \frac{R_2'}{2(2-s)}$$

$$K = \frac{1}{2\pi \frac{N_s}{60}} = \frac{9.55}{N_s}$$

$$T_b = \frac{9.55 * (I_{2b}') * R_2'}{N_s * 2(2-s)}$$

$$T_f = \frac{9.55 * (I_{2f}') * R_2'}{N_s * 2s}$$

$$\text{Total Net torque } T = T_f - T_b = \frac{9.55}{N_s} * \frac{R_2'}{2} * \left[\frac{I_{2f}'}{s} - \frac{I_{2b}'}{2-s} \right]$$

Experiment calculations for equivalent I.M

No load test ⇒

V ₀	I ₀	
220	4.2	

Blocked test

V _{sc}	I _{sc}	W _{sc}
58	6.7	351

$$\Rightarrow R_1 = R_{ac}$$

$$R_{ac} = 1.5 R_{dc} \Rightarrow R_1 = R_{ac} = 1.5 R_{dc}$$

⇒ from no load test we know V₀ I₀

Magnetising reactance $X_m = \frac{V_0}{2I_0}$

$$Z_{sc} = \frac{V_{sc}}{I_{sc}}$$

$$Z_{sc} = Z_{01}$$

$$R_{sc} = R_{01} = \frac{W_{sc}}{I_{sc}^2}$$

s.c parameters

$$Z_{sc} = Z_{01}$$

$$R_{sc} = R_{01}$$

$$X_{sc} = X_{01}$$

$$X_{01} = X_{sc} = \sqrt{Z_{01}^2 - R_{01}^2}$$

$$X_{sc} = X_{01} = \sqrt{Z_{sc}^2 - R_{sc}^2}$$

$$R_{01} = R_2' + R_1 \Rightarrow R_2' = R_{01} - R_1$$

$$X_{01} = 2X_1, \quad X_1 = X_2' = \frac{X_{01}}{2} = \frac{X_{sc}}{2}$$

$$Z_F = \frac{jX_m}{2} \left[\frac{R_2'}{2s} + \frac{jX_2'}{2} \right] ; \quad Z_b = \frac{jX_m}{2} \left[\frac{R_2'}{2(2-s)} + \frac{jX_2'}{2} \right]$$

$$\frac{R_2'}{2s} + j \left(\frac{X_m + X_2'}{2} \right) \quad ; \quad \frac{R_2'}{2(2-s)} + j \left(\frac{X_m + X_2'}{2} \right)$$

$$\Rightarrow Z_T = Z_{01} + Z_F + Z_B$$

$$I_1 = \frac{V}{Z_T}$$

⇒ calculating total current I_1 , we need to find I_F & I_B

$$E_{2F} = I_1 * Z_f ; \quad E_{2b} = I_1 * Z_b$$

\hookrightarrow forward emf \hookrightarrow backward emf



$$I_F = \frac{E_{2F}}{\sqrt{\left(\frac{R_2'}{2s}\right)^2 + \left(\frac{X_2'}{2}\right)^2}} ; \quad I_B = \frac{E_{2b}}{\sqrt{\left(\frac{R_2'}{2(2-s)}\right)^2 + \left(\frac{X_2'}{2}\right)^2}}$$

⇒ forward & reverse direction torques

$$T_F = (I_F)^2 * \left(\frac{R_2'}{2s}\right) ; \quad T_b = -(I_B)^2 * \left(\frac{R_2'}{2(2-s)}\right)$$

⇒ Net torque $T = T_F - T_b$.

final equivalent circuit



BLDC motors

* Also known as Brushless DC-motor. It is electronically commutated DC-motor.

* Speed & torque of this motor is controlled by producing current pulses to the motor winding

* In this motor, permanent magnets rotate around a fixed armature to produce a large amount of torque over wide speed ranges.

*

Working of BLDC motor

⇒ In brushed motors, an armature which is rotating one consists of permanent magnets which creates a magnetic field when power is switched on.

⇒ For continuous rotation of armature, this brushes changes the polarity of poles by reversing the current.

⇒ Same principle is employed for BLDC motors also. The only difference is BLDC motors shaft consist of position feedback controller.

Construction of BLDC motor


It also consists of 2 parts stator & rotor.

* The rotor consists of permanent magnets which continuously rotating. These magnets revolve in stator.

* Rotor which is stationary one consists of stator windings.

* A solid state circuit performs controlling & distribution of power to motor.

Types of BLDC motors




2 types of BLDC motors

① outer rotor motor

(2) Inner rotor motor

↳ winding surrounds the rotor



In this design, the rotor is completely surrounded by windings in the core of motor. The magnets in the rotor traps the heat of motor.

- * Such motors operates at lower current
- * Cogging phenomenon is low.

Inner rotor design

surrounds

↳ stator winding, rotor




fig: Inner motor design

- * Rotor is located in the center of stator winding.
- * These rotor magnets do not provide heat insulation.
- * such rotors dissipates heat outside.
- * such motors produces high amount of torque.

BLDC motor

Advantages

- ① velocity & speed depends on current but not voltage
- ② No brushes means, frictional losses is less, no sparking
- ③ produces less noise
- ④ Accelerate & decelerate is easily due to low rotor inertia.
- ⑤ less maintenance

Disadvantages

- ① cost is very high
- ② High power is required
- ③ during low power, heat generated creates the magnetic field.