
DC- Generators -> Unit-@

principle

At is a meetine which Converts mechanical entry i/p

into electrical energy. O/p of DC Genography is DC electrical. Whenever a rotating Conductor is placed in a stationary magnetic field, a dynamically induced rome is induced in a Conductor. If Conductor ands is shoot circuited then Convert flows through a Conductor.



Working !


Jassume coil is rotating in clock cuize direction flux linked with coll changes, an empt is induced $e=\frac{d\phi}{dt}*N=N\frac{d\phi}{dt}$

If call rolles AB 4 co one porallel to magnetic lines, no empt is included.

If $\theta = 90^{\circ}$ 80 270°, Martimum flux is cut by Conductor, an enrol is induced.

If 8=0 01 180° emp is 200.

1



1600 sa) 1 sec.

from 0, to do ' sale of change of flax linkages. irementer hance every also increases. Cheere o in 900 on may Han I to 1-).

from 900 to 1800, fewe livinges Cut by Cordence decreases, describent emp, also decreases soon from position a to position 3.


Direction of induced energ is found by flamming of oight hand ande. From 0 to 900 to position from 1 to 3 indicates 1st half position of coll sociation.

from 6=180° to 270° or position 3 to seething (1) enny increases & enny decreases at \$ \$ 2700 to 0:360" Completely arested 1/2 Cycle.

The 2 helf cycles, called as the 1/2 sycle, Current floors from A-B-M-L-CO & oroster but cycle called - ve 1/2 Cycle, current flows from D-C-L-M-B-A.

D+ve 4 D-ve 1/2 Cycles called as one soubolution. or one cycle. Il.

potate of Generation Construction.



Yoke -> known as magnetic frame. -> stationary part of machine, which produces a regressic April Same feur from main poles. Constraint to > Acts as 2 purposes O to cour the corde mochine 1 Provide the mechanical support

afor small machines it is made up of Iron, to longer mochines It is made up of cast steel. because assight to main fact-o, to reduce a eight steel is preferrable.

at consists of pole core, pole store + pole coils. -> pole core & pole coils forms the magnetic field.

pole shoe To pole core

-> end of pole core It is fried as stee type to seduce the air gap b/w the star & roter.

-> if pole core is wounded with coppe wite then it is known as pole coils.

interpoles ...

also Called as Commutating poles

-> weed to improve the Commutation. -> There are made up of thick Conductor with few turns wounded on that Conductor.

-> It is carries full armative arrest. dy all see bringers of

Armatuse

-> Actaling past of machine is armature -> Consists of accontinue core of armature cuirding. -> Armature Care congists some states to carry armatuse wirdings. This core sociates in magnetic field. -> If ormative votates in magnetic field hydreresis + eddy Current losses taxes place in the form of hest.

Comm whator > It is a current collecting device which an Ac induced emp into unidirectional emp. All the ends of armatuse colls are spriegly Connected to

each other & 168 ends are woulded to

Commutator. and a factor day of Horaco Man Thing

Brushes:

-> collects the Current from Commutator

-> roade up of Carbon or graphite.

-> These are recrangular shape placed is brush holders.

Bearings:

-) used to seduce the foiction & noise bloo the stator 4 votor bearings are provided to the votor

-> For small machines, ball bearings are used -> For large 11 groller bearings are used.

Armatuse aundings

-> classified as 2 types

1 open coll winding: (2) closed coil winding

The ends of the cuindings are in open circuit untill an external source on load is Connected.


- 1 closed winding
- -> preferred for de machines.
- -> The ends of cuindings are Completely short circuited on closed.

-hope are again classified as

@ ring cuinding

Armatuse cora Consists of ming made with cuirdings are arranged by providing lamminations. The ends of stry cuindings are Connected to Community

advantages in the sist wings relation gazed section 2.3 -> no croking of winding each other seems simple some cultding used for 2,4,6 + 8 pelas machines disadvarlages in the first in the -> unever fur linking with the coll. -> Emplis small composed to drum winding Here event is half of the drum winding. -> Insulation of aurding is difficult. -> maintainence cost is high. (B) Drum aurding - anductors are placed in armature slots + are connected one to another by front & book end connecting. these are BIBBLA HAY classified as (i) sirgle layer cuirding An armature Consists of one slot, only one winding is used in the slot. on only one conductor is used in one slot. Here a coiling (ii) double layer wirding there 2 coils are placed in one slot & 2 conductors one used in one state. 2 conductors / slot - Here one coll is on upour past of pole 4 another past is bottom part of pole. -> wed in medium street machines. - ditte -> uper sides of coils, as numbered as 1/3/5/7 4 lower coil Rides are neurosad as 2,416,8, advantages -> for higher salings machines using 2 coils per slot 10 1/6 1/6 1/6 1/6 1/6 1/6 reduces the size -> Commutation is improved (m==2/= // =/ -> EMF O/P is high. so we have the Valley and C.




come cultaing: It is a soies winding.

1 set of Colls corry Current in one direction it another set of cally carry · Current in opposit direction. coich are Connected 17 Paries. of - of of pedieno got

-> Both You YE are odd a of some signi.

> YR = YF+YB = Z+L PHENDON it is read to the first transport overlained of 150

-> no; of let puts eared to 2m 800A = 2



Paris Son

es) ess verses where

disportant definitions

pole pitch Distance b/co the 2 adjacent poles

not of Conductors divided by no : of poles.

Pole pitch = no; of Conductors / slot not of poles

Example: 48 Conductor's per 310t, Consurs of 4 Poles - pole pitch = 48/4 = 12.


coil span (Ys) 81 coil pitch

also colled ag' pole span. At is a districe b/w the 2 sides of a coil.

=> coll spon on pole opan on coll pitch /6 = notof slots collspan = 180° 11 ho- of poles

=> It collapan on pole gran is caud one pole pitch then it is called full pitched.

Pitch of a winding quidalist and to it that it is training Distace b/10 the 2 successive Conductors 87 distance blo the 2 begining conductors. lap aunding Y= YB - YF wave 11 Y = YB + YF populating Mar of Lot of the Back pitch : no! of Conductors spanned by a coil on back end. It is devoted as You are of leaving they tall of the front pitch (YE) not of conductions spanned by a coil on front end. Resultant pitch (YR) Distance b/s the beginning partlet one coil to the beginning past of react coil. enf eaution of Generator with sure $E_{g} = \frac{\phi z N}{60} + \left(\frac{P}{A}\right)$ Ly generated employed and sign did sign Let \p = flux/ pde in wb Z = 102 of Conductors on total not of Conductors no: of slots x no: of conductors / slot P= no; of -poles in to ton. not of parallel parts in : el : el no: of sendusions / minute: dating along are know that awarage emf / conductor of a requisition e= Ndo N= no; queturns =1 the state of a period HOLD MAN . Y CONTRICT IN OUT STORE IN CONTRACTOR => Total four 'cut / pole do = op wb not of revolutions per temperates, Gorps = 1 spm; 11 rem = 608 PS GOTPS = Nopm dt=18PS= N spm 8PS 2 60



EL = NEOL and die 1 \$ 2 = 20 m cdb, di= 20 mb N2 = 11000 TPM N1 = 800 TPM 10 30 101161 $E_2 = E_1 * \begin{bmatrix} N_2 \phi_2 \\ N_1 \phi_1 \end{bmatrix} = 100 * 1000 * 20 * 10^3 = 125 v$ (11) de = 14 m mp , No = 900 x PM 00 = 019 614 01= 80 m cob, N1 = 800 x pm 3 - 1961 $E_{2} = 18 E_{1} \times \left[\frac{N_{2} \phi_{2}}{N_{1} \phi_{1}^{2}} \right] = 100 \times \frac{900 \times 29 \times 10^{-3}}{800 \times 20 \times 10^{-3}} = 135 \text{ V}$ 2) alculate voltage induced in armature of a 4 pole sol lap wound de machine towing 728 Conductors + ourning at 1800 opm. The freez/pole is 30 to cob. Eg & E. = $\frac{\phi z N}{60}$, $\frac{\rho}{A}$ of $\frac{1}{1000}$ columns which sol given poles p=4 1 Connectors is lap coound so parallela paton = not of pales i.e A=P=4 principal Conductors, Z=+728, speed, N= 1800 8 pm, \$= 30 m ws 6 = 30×10-3, 728 × 1800 × 4 = 8 (a) use above problem data first voltage induced in armotive howing come would de machine. sol Poles = P = 4, 9 = 30 m cob, Conductors Z=728, apeed No 1800 rpm, Connecision is waite wound parallel parts is A=2 Eg & E = 72N 4 P = 30410 4723 + 1800 44 = 60 201 (a) A 4 pole lap wound armsture has 144 21068 with 2 coll Bides per 1866, each is tauting 2 turns. If fur per pole is 20 m cob 4 armatus gotales, at 720 cpm.


as from the paint worth appear who en

A I make the

no! of poles P=4, freex/role = 20 m cob , 18 pled N = 780 Connection is lap around, parallel parts in = P = 4 5mm 10; of 810+8 = 144 810+8 1) 100 not of coils por slot = 2 no; of twins per coil = 2 Total not of Conductors = not of slots & not of coils + not Z= 144 + 2 + 2 = 576 For wave cound no; of parallel parts induced empf Eg 87 E = ØZN + P = 20+10 + 576; 4 720 Eg = 138.24 Volt An 8 pole de grander has 500 Conductors, usefull flux 0.05 cob. estat cull be generated emf. If it is lop connected, runs at 1200 pm., what must speed scanised to produce some emp. if it is wome no : of poles P=B, conductors Z=500, fux Ø=0.05 Eg= ? (lop Connected A=P=8, N=1200 FPM) $E_{8} = \frac{0.05 \times 1500 \times 1200}{60} \times \frac{8}{8} = 500 \times 1200 \times \frac{1200}{8} = 500 \times 1200 \times \frac{1200}{8} = 500 \times 1200 \times \frac{1200}{8} = 500 \times 1200 \times 120$ 1 speed sequired to produce same erof if it is come wound. For wome wound no! of parallel paths A=2 Eg = 500V, N= ?, Ø = 0:05, Z = 500 $E_{g} = \frac{\varphi z N}{60} + \frac{P}{A} \Rightarrow \frac{E_{g} + 60 + A}{\varphi + z + P} = N$ N = 500 + 60 + 2 = 300 FPm 0.05 ×500 × 8

10

An 8 pole lap wound armaturie sustated at 350 pm is securized to generate 260V, we full fure/pole is 0.05 wh It armature has 120 8648; calculate no: of state home Conductors of a determine the actual value of fure securized to generate same voltage.



spectucion of reagnosic feur leads to reduction of a distrosions in main field flux leads to increase, tron lesses, poor Communion, sparking at brushes. فع المحدد معروب المناع المعالي عام المحدد عن المعالمة الم Considered a 2 pole machine, shown in figo; Let us assume there is no amentione Currents at. no load. main field flux is an horizontal place ch. shown in tise and and an and one d so at no load GNP -> Geometrical newral d-axis plane 4 MPUP cronageousic reutral plane exactly coincide. shown in tige. MNP => => De machine is loaded, armature ainding seciones comative aurent. GNP = X-aris igen scribono had they all at tordaxis ==) | hand A bouthish and setting = priser co feel q There were configurated. Este: /1 =1-351 noin peter. intrust policy Gereoal totation anisarian fig 6 6 6 the superior that comments This armative Current get up an armative fine da shows in vertical axis stown in tio @ Oli ~ there armatuse sorates in clock cuige direction infor greates, per and land > If armatuse flux da cross the main field flux (of) then it is called cross magnetication. effect. = If armature fux pa opposes the main field flux " OF they it is called de-magnetication reflect. Here total sux / pde geduces from no load to full load.

cross magnerigation Cars bed mentionised using misself significant -> using high orchuciones pole lips By flattering the pole faces, so that air gap. is increased, this leads to increase reluctance. -> reducing the rearmatuse flux -> By providing more selucture 1 41 by providing. a lamination on poles!" we con seduce the armatuse flux. Look or to or c. History soul brigar. دواه دول ما ما مده الم لا DO: field ple laminations. -> strenthing the main field flux By increasing the ortio of main field feur to the full Load armatuse minfile This can be actioned a during the De machine design. -> wring tinter poles Anterpoles are small poles, located b/w the main poles. There poles are converted in soils with armatuse remodises the armatuse monf. this improves the Commutation, -> using Compensating cuindings -> also called as auxillary cuindings. -> intex are arranged with main field winding stots. stored be compensaring of auxillary winding. should be completely apposite to the armstive ewinding Corrects. eniform distribution of the without distribution of fure.

De-magnishing ampère teurs per pole Armature fux de-magnesises the rain field fux predous the room field full. So are seawer an extra approx turns to increase the main field fux. It can be calculated. no! of turns = . Half the no! of Conductors Z= total not of Conductors I= Current 16 each armotuse Conductor Jos James too cause cultding I = In for lop counding total no! of Conductors = 48m y Z Here 2 conductors becomes one two .. total not of twons = 20m + ZI I S + 06 . 1/4 / 2 1/3 60 / 1/2 / 1/ De-magnetixing comp-turns per pair of poles = 20m + ZI nest - 1 = 1 1 1 per pde = 0m y ZI cross magnetising Ampère turns / pole ATC/P ATc/pole = Total no! of Conductors/pole - De-majorer zing Conductors/ Pole ATc/pole = Due know that demagnetizing Conductors/pole = 20m yz Total no! of Cordiners/pde = Z => Cross regnerising Conductors/pole = Z: - Z 128m 360 Conclusions $= \frac{1}{2} \left[\frac{L}{P} - \frac{20m}{360} \right]$ coops reagneristy amper KHHHHI/pole = ZI[+ 20m]

B) A 300 KCO, 500 V, 6 pale lap coound generate toos 70 slots with 12 Conductors / slot. If brushes agree whifted to 3:33 mechanical degrees. Innote shout field correct. Find idemagnetising a cross magnetising amotors.

Contention of council A = p Of at generate is 1300 KW = Pout when the Voltage V2 500 V made at the fill of the Poles P=6, not of slots = 70, no: of conductors/slot Talled a rock sound all places gras 12 and It princip order to interpolated of = 3:33. 1 mords 1100 monds to -> Demagnetiang ampluen/pole = ? => cross magnesialing ampturo/role=? ! store de des cos Ja= IL+ Inh with the species of white = IL+ V/Rah Deglect short revistance

Ta = IL + V = IL + O

Resh

Pout = VIL => Pout = VIL 300 #103 = 900 # IL To - 600 to - 500" = 600 A => Demagnetising amp turns/pole ATa/pole = ZI + Om 360 Ta = 600+0 = 600a Current in each Conductor I = Ia = I = Ia = 600 = 10A A no! of possible Z => no! of slots x no! of Conductors/ slot was more 70 +12 = 340 Conductors. ATa/ pole = 1 840 × 100 × 3:33 2 1 11 men 360 compared for thems =) crops represent any turns/pole ATc/role = ZI [11- Oro = 840×100 \[\frac{1}{2\sqrt{6}} - \frac{3.33}{360°} \] = 0 months of the state of the stat The experience of the property of the second Called & alleged a of the finite of contentions

in the party load is the

Compensating winding Due to armituse season, flux distribution of come budly distorted. In the absence of Compensating windings there fux oscillating blow backwood & forward.

If this emp exceeds the break down voltage a spack will spread all ours the commutator. This leads to short circuit of committee. This happens who colly are breated b/101 main poles it sudden increase In trady increases the emf. All this is due to armetica seacrion. so this windings are weed to reusalize the armatuse realism. These are Placed in the slots of main field cuindings.

So compensating winding is consecred in soince cuits armature winding. other cross magnetizing effect causes spooking at the Communators.

Let Zc = not of Compensating Conductors/ pole = = = Za= no : of amostive Cooductors/ pole Ia = Armatuse Current barrels and

$$Z_{c}I_{a} = Z_{a}\left(\frac{I_{a}}{A}\right)_{a,l,n} \qquad (100)$$

$$Z_{c}' = Z_{a} \qquad (20)$$


ACTION OF CHE ALTON

at is the process of severing the armstuse Communitation brushes

disportance of 1 Communication

- 1 Converting are current in armature into de Current
- (2) also used to reverse the direction of Current.
- 3) It maintains voter most estationary in spore.


Commutation period => Te = audth of brush Pheriperal position of Commo tates.



EWE COMMUNICION Some times It is Inability to take removed of Current due to gracimo voltage. 1 So Commonion. failure trees place. It can be overcomed by using emf Communican. Here an earl amount Empt is generated a is opposite director to reacting voltage becomes multified. This. is done by O Brush shifting In the method, brushes one. partly chifted beyond the Magnetic reutral varieties. Dequet sendance voltage and be reduced. en) using Commutation polegning -> also and as interples. -> located b/co main poles ... +> - s communing pole acirdings are Corrected in series with amortise? airding. exactly opposite to successive voltage. No, Son Genmoning exactly officite to seasonse voltage. -> Emp of intespoles magnitude is opposite to the Equalizer Consection minutes of supplied to the This Consection is araises who there is a lap cuirding. An lop winding induced rent in posable parts are weared due to 10 100 miles le ser 1) differences in our gap (11) Amproper arrangement of field cuindings - above e Couges finally leads to circulating Current. , These circulating Currents at brughes & commun leads to sporking. I had all pall of some inter - finally Communition failure taxes place. sexistance Copper Conductors are Connected across the

-> These are arranged in the form of ting, will by pools Ac etraulating aurordy.

-> due to -the potential difference exist b/10 the domitude aciding + equalitar acidings there circulating Corrers becomes disperted.



founded openations of DC General


Many of power plants found to have several smaller generators searing in posalled instead using single writ. Here all writes our at a time or tens with keeping owning parallel.

parallel operation provides personal and the second

- O Deliability
- 1 Continuity of Service
- 3 High efficiency
- (4) Repaier is quite eary
- (5) Eary maintainerce.

To action the parallel operations following Conditions must satisfied

- (a) Generatory must have eared oating
- (b) polarities of gereators must have some
- @ load characteristics should be some.
- @ voltages should be identical,
- @ Generators that are driven by primerrowers should expeed rough be same.



-> Generates the & - up terminals ope exceptly connected to bus bon torminals. in prince some some

- -> If polarity of incoming generator is not some than a short circuit/ avill exten switch swil is closed.
- -> short circuit leads to block out of plant!
- -> Before paralleling 16 is necessary to check the reverse Polarities any. Solvand of phicalina 19
- -> short generalor () is Corrected across, the bone book s) DB'- For keeping and generator in //eligouity 15fm, it generater - the following procedure is followed.
- Obering the 2nd generator speed to 118 sated Value
- (2) After borging end generator speed then Close saith # Scor - Her circuit is Completed.
- c3) Connect a voltaneter across south scal.

STATE OF STREET

cu) excitation of 2nd generator is adjusted till the Voltmeter across SWI seads toro. poursing 169 gd parist see the services

si wirned bank forth

DC- Motors (1-8) pages

Mechanical one.

Methanical energy.

is Mechanical.

Principle of DC motor


. unit-11
. Dc-motors

placed in a stationary magnetic field, the Conductor experiences a Mechanical force.

The direction of force is given by flammings left onle

F= BIL

so its Construction is similar to dic generator.
Working of DC motor



to die supply, field magnets gets excited develops

Here armature Conductors Carry Currents. @

Conductors under N- pole Carry Current en

Conductors under 5- pole Carry Current on opposite direction to the N- role.

magnetic field, the Conductors experiences a mechanical force.

tends to sotate is the armature is articlock-

brush to another side of brush, arrent in amores seversed. The conductor shifted to another pole by maintain direction of force semains constant.

given as [F = BIL] Neuttong. Unit-II

B= fux density in wb/m2 I= Current in Amps

l = length of Conductor

Back enf 81 Counter enf

magnetic field, an emp is induced in the

this induced empt is motor is called as back empt on counter emp.

The hack emp demoloped by the motor must corress. the supply voltage using lengs law.

Back emp

$$E_b = \frac{\cancel{\emptyset} \cancel{Z} \cancel{N}}{60} * \frac{\cancel{P}}{\cancel{A}} \longrightarrow \mathbb{D}$$

9 = func/ pole 10 webers p= no; of poles


Z = nc: of Conductors

N= speed of motor

A= not of parallel paths

Eb= back eng

Equivalent circuit of motor



Ja = V- Eb

V-JaRa-Eb=C V= Eb+ Ia Ra


Ra = armature voltage V-Eb = net voltage is armature

Back ent of motor depends on (Admature speed (2) Armature current (3) Armature gresistance.

NEba_1

if En is lux theres supply voltage EbLV Speed of motor is high, Eb also high but Itamo

·ELT. hock emf 1 armature speed



mynusc losses or core or Iron lesses

eddy Current losses are due to hysteresis 4

loading Condition. These are 2011 of full load lossess. Brush losses

ator & Carbon brushes. These losses produces a Mechanical losses

these losses are associated with the mechanical parts. Mechanical losses consists of frictional 4 windage losses. These losses occurs due to wearout of beautings.

These losses are overcomed by seducing the friction b/w the states I state by providing air

stray losses

the above all losses are stray losses. They are to determine, these losses are very difficult


Efficiency of DC machine 80 motor

The efficiency of dc motor is the sectio of

It is denoted as '?'

Efficiency $\eta = 0/\rho$, 100 = 0/e

1/P × 100 = 0/P + Total logges * 100



1 ren = 18 cm

Unit -I

Force De-rectoes

Tt is the product of force A radius. Consider a cancel of radius (8) in meter, circumferential force (F) Networks. Let the force (F) causes the torque = F * 8 N-m wheel to rotate (N).

CO = 2MN rad/sec

work done per sievolution = Force * distance distance = circumference of a circle = 211 r

W = F * 217

Power developed P = Work done = F*2Tr

time time for 1

P= F*2117 60 N

(

TPM = 60 N

P= (F*r) *211N 60 P= T* 69 | watts

> T = Torque in Netwoon meter w= angular speed in rad/sec

Electrical power supplied to it A mechanical power produced by it. It is called as armalu.

Gross Muchanical toraine is Eb Ia

Pocor is armature = armature * co

Eb Ja = T * w

Eb Ja = Ta + 21TN 60

Lat Eb = ØZN *P

Ta = 60 (02N) * (P) Ia

Ta = 0-159 0 * Ja * Z * P

T is proposional to Ø Ia.

Epecal Control of de motor

we know that back emf developed by motor

Voltage equation of motor is

V = Eb + IaRa

Eb 2 V- IaRa -> 1

By varying flux on field, especid of motor is

Changing in flux co) can be obtained by changing field current.

$$\phi = \frac{di}{dt}$$


Field current is varied by varying the field spesiestance on Hiddell which is connected in series with short field winding.

e varied if field current varies then flux also varies finally speed of motor varies.

By increase the field sesistance, flux of meter decreases, current through motor decreases as a sresult motor speed increases.

$$N = \frac{R}{\emptyset}$$


Je Ish is less means, field Resistance is maximum, Rheostat carries small amount of current. I'r losses will be small.




Greed - Torava

 $\frac{O \geq N}{60} * \frac{P}{A} = (V - IaRa)$ DC-motes3 N = 60 + A + C V - Ia Ra) Unit - I OYZ # P N = (V- Ia Ra) -> 3 Kb = 2 + P Equation 3 indicates speed of de motor V= supply voltage Ia = armature Current Ra = armature resistance \$ = flux They are 3 methods of speed control → O By vorying armature surestance (Ra) → ② By varying flux (\$) [field Control] → 3 By vorying applied voltage (voltage (control) speed control of de motor using field 81 flux Control method field Rheastat 3 Roh e= ON ove know that induced emf of machine e= ØN By maintaining e is constant

e





that armature voitage changes from the to From the speed will change from the from the from the from the from the speed will change from the speed.

since the speed Control is convied out with stated Courrent A Constant flux of motor, a Constant Lorane upto base speed is obtained. Since power is proportional to speed, it increases with speed. Hence from armature voltage Control method Constant torane and variable power drive is obtained from speed.

Problems

Oc-motors

A 4 role de motor taxes 50A armature current. The armature has lap connected 480 conductors. The flux/pole is 20 m cab. Calculate gross torque developed motor.

Poles P=4, Ia=50A, no; of Conductors Z=480

Armature has lap Connected

no; of parallel paths (A) = no; of poles (p)

A = P

A = P = 8 4

Gross torque developed motor

 $T_q = 0.159 * Ø * Ta * ZP = 0.159 * 20 * 10^3 * 50 * 480$ = 76.394 N==

Ra=0.7552, armature Current Ia=3ca, to certain load. Calculate induced enf 19 motor?

4ct V= 22CV, Ia=30A, Ra=0.75

- Eb+V+ IaRa =0

V= Eb+ Iaka

220V = Eb+ 30 + 0.75

Eb = 220 - 30 * 0.75 = 197.5 V

301

Problem no: of poles in dic motor has 4 poles Connected in lap. The flux/pole is 30 m cob. No: of armature Conductors is 250. when Connected to 230V supply it draws armature Current 40A. Calculate back emp of speed at which motor is surning. Assume armature specialistance 0.62.

sol no f poles p=4.

given armature winding is connected in lap

A=P=4

surry voltage V= 230V, not of Goductors Z= 250

\$= 30 m wb = m = 30 * 103 wb, Ia = 40A,

Back emp Eb = ? , speed of motor N=?

V= Eb+ IaRa

Eb = V- IaRa = 230 - (40 * 0.6) = 206 V

we know that back emp developed by motor

Eb= \$\frac{\phi \neq N}{60} * \frac{P}{A}\$

 $\frac{E_{b} * 60 \times A}{0 \times P} = N \Rightarrow \frac{206 * 60 * 4}{30 * 10^{-3} * 250 * 4} = N$

N= 1648 21W




1 DC shurt generators are used for som Constant loads. These is also used for charging batteries.

(2) sories generators are generally used as boosters for adding a voltage diff in transmission line to reduce vollage doop (3) Compound generators are used whose Constant Voltage is sequired in dc 1/w3. (networks). These generators maintains good Voltage singulation.

DC-motorg unit-(1)


characteristics of DC motors (G5-M6) pages

O short motor characteristics



In this Connection, field winding is Connecte across the armature of the rooter.

Since supply given to the motor is constant so field current is constant, here funcing Constant



T v3 Ia T v3 N Ia v3 N

T dp Ia
T d I

Since & is nearly constant for shurt motor


Tol Ia

Torque, T

- is called as electrical characteristics

 (b) speed (N) 4 armature Current (Ia)
- @ speed (N) & Torque (Ta) also known as Mechanical characteristics

(a) T/ In character; 8403 we know that Tad Ø Ia NX ED assume ø is Constant TadJa electrical characteristics are straight from origin 6) speed vs Armature characteristics If Ø is assumed Constant then Nd Eb. Eb is practically constant so speed is also Constant speed Eb & Ø decreases, if load increases as a sesult speed some what decreases. The drop in speed varies from 5-15% of full load speed. As a sesult slightly have drooping shown in dotted line @ speed vs Armature torque Ia This curve is obtained by the Values N& Ia for various armature Current NT Tal



6 speed vs Armature Current

Eb & NØ

Ød Ia

NdEP

Neglect Eb since speed variations is very bor various Load averents.

with increased Ia, & also increases . speed Nd_

If the load is heavy, Ita is large so speed is very low.

If load current is low, Ia is also low, of is also low

Na 1 p = low means

so series motor never start without some mechanical load.






fig shows N/Ia characteristics


O speed vs armature torque (Mechanical characteristics, cotan speed is low, Torque is the high if speed is high, Torque is low





field windings. It series field aids the short field excitation then it is cummulative then it is cummulative then it is cummulative then it is cummulative then it is called opposes the shout field then it is called differentially.

Characteristics of Cummulative Compound motors



IL = line line current = Is csupply current)

IL= Is

Ise = Ia

IL= Ise+ Ish = Ja+ Ish

a Ta vs Ia characteristics.

As load on motor increases, Series field increases but Shunt field becomes Constant

Load 1, sories field 1, Shart field Constant Ta compound

shurt

shurt

Increases

As a sexuel total flux (B) increases

Ta d Ø Ja Torque of Cummulative motor 7 shunt motor Tor (b) N/ Ja characteristics Nd Load on motor increases, flux also increases since Ja increases, speed (N) decreases Load 1, Ø1, NI Speed in Commulative motor L Short motor Speed. -> Ja so for Cummulative rootor Torque (Ta) is greater than Ta C Torques of sheet motor N/Ta TdØIa

Not Eb De Load 1 | Torque 1 Flux 1 | Torque 1 Ia 1 | NJ short motor is used for consent expect expect expect starting heavy loads, also suitable for high load variations.

@sturt motors

used for Constant speed applications such as lather, Centrifugal pumps, machine tools blowers, fans

(b) series motors using in soilway traction, craves electric sailways, Conveyors, hoist, trolley cors

@ Compound motors

For shears, punches, hoists, stamping process :

Three Point Starter


are know that Voltage of de motor is

V = Eb+ IaRa

 $\frac{V-E_b}{Ra} = Ia \rightarrow Current drawer by motor$

V= supply voltage, Eb=back enf Ra = armature assistance

when motor is sest, Eb is toro. When we apply full voltage, armateure draws very, Currents to avoid high starting Current a series sussistance is connected to the armateure of motor.



These are indicated as Line (L), field (F) 4
Armsture (A).

then moter is in normal operation starting arm (SR), over load coil (Re) & Hold on coil (H) which holds to starting arm. Juring its full surring position.

Starting the motor

showly from left to Right. when own contact with stud, field circuit & armature connected in series with starting resistance Re.

hance Rs is gradually cut off till the motor tains its stated speed.


the arm (SR) to off position. when the arm the electromagnetic H is energisted & acts as as magnetic to the hold starting arm untill the field Current flow through the Hold on coil. In case of failure of power on sudden disconnection of supply, Hold on coil becomes de-energisted & subcases the arm as a result immediately comes to storting passition coff) by the action of topology force.

Over current release on over Load coil, also and Consists of an electromagnet Connected to line supply. If armature current exceeds its preset value then Rod 'm's gets magnetised a lifted up as a results it short circuits the electromagnet. Hence the starking arms (SR) will be released comes to its original back position by spring altion.

DC- motors

OILIC

over load coil.



-> No voit release coil is connected in series with short field

> If starting arm is at stud () line Current divides into 3

- 1 parkers through starting registerie armature & soiles (2) and part passes through short field.
- 3) 3rd poole 11 11 no voit selesse coil.
- pullback to off possition.
- scape starting de notes, feeld circuit is Kept closed.

 Pheostat in socies auth start feeld is kept at zero on minimum position. Similarly starting revisionce in socies and with armature is kept at maximum value.

For stopping the motor, line scotted is opened instead 1 of throwing back the stocking arm. MAKELE - THEY ALMIHALE ALL - MAKELI MAKELANIA . Also for stopping the roots, entire field resistance is

Cut off & allow the motor speed falls below the normal speed other opered the line society.


Testing of de-machines

To determine the efficiency of a dic machine as need to Proferm 3 test

Opinect method:

- -> suitable to a small machines
- -> used to mangue efficiency of losses.
- -> The machine is MHHMANIA AN Completely done by full load.
- 1 Indirect rested
- -> switches to find the efficiency + larges in street +
- -> losses can be determined without leading machine.
- -> it fails to provide the temperature going during light Load Cordi Hong.
- (3) Regensorthue method
- -> Deautres 2 identical machines of same saling.
- -s one machine oching as motor & others assing as generaty. -> tis seawley bound power to text large machines
- -> efficiency, temporature graige, losses can be find out

For stopping the motor, line switch is opened instead of throwing back the stocking arm. ANKER - THAT MANAGEMENT - MANAGEMENT . Also for stopping to rooter, entire field resistance is Cut off A allow the motor speed falls below the normal speed often opered the line society. Testing of de-machines To determine the efficiency of a die machine as reed to bedern 3 test Opinect method -> suitble for a small machines -> used to measure efficiency of losses -> The machine is ALHARMAN AN Completely done by full low applied to machine. 1 Indirect rettod -> switches to find the efficiency of losses in short of -> losses can be determined conthout leading machine. -> It falls to provide the temperature going during light Load and Hong. (3) Regensossive method -> Deautres 2 identical machines of same saling -> one nature acting as motor & others assing as generating -> This seawley small power to test large machines > efficiency, temporature trains, losses can be find on



-> suitable to test small motors.

the shaft of the mater of the pulley is a water cooled

-> Boake band Growists of lends, one end is connected to spring through the easts on ground.

weight (W1).

who gives force applied on the pulley.

bet wi be suspended creight in ekg?

We be sporting reading cohich reads the waight

Hut amount of free acting on pulley is = 9181 CWF-W2) networks.

if co) is the radius pulley is notes

N is note speed in spen

That shaft trave doubleped by notes is

Tish: 9:81(W1-W2) # of N.m.

Motor of power = Teh * ETIN wat +

= 9.81 CW1-W2) * 8 * LTN

note i/b becomes = NI

2%= 0/P = 9.81C (01-(02) *Y Y 2 MN)

Prombacks of the test months of note common be determined accurately of the formation internal lasses a afficient of large reaching.

the state of the state of the state of

tion of the supplier to the process of the section of

the state of the state of

La grande I tol 1: and the sale

ACTOR OF ACTOR OF THE PERSON O

and the second second second second

the second of th


A TEN TO THE REAL PROPERTY AND ADDRESS.

La and Special and the second of the

- -> Also colled as Back-Back test
- -> This test is corried on 2 identical short machines.
- -> It is a full load test.
- -> Both machines are mechanically Coupled 4 are electrically
- -) one act as a motor & other act as a generate.
- -> electrical o/p of generator is used in supplying a greater

to be needed

- 1 2 short machines of identical statings is needed
- 2) 2 shunt machines Connected in parallel
- 3) field on 0 moter is weakened & other is stoengthened.
- (4) field accorded acting as a motor of field strengthen acting as a generator.



- -> Before stocking the experiment, souther (s) across voltagery is kept opened
- -s machine (M) is establed by using estable, adjust the speed of (M) upto its normal 80 gated value.
- -> Machine (M) Coupled to the Machine (G) generates Voltage Is sead by Voltmeter.
- -> Adjust the voltage of Mochine (G) by varying the field Phosetat untill the Voltmeter attains Zero reading,

-> Zoro seading in voltmeter indicates - Ha magnificate A

polarity is some to that of supply realing.

-> If voltmeter attains Toro - Han close - He scultch cg,

Motor i/p = VC JI+JI), Jz is Current from main supply

Generator. O/p = VII. -> 1

so electrical off of generator & small power from raing

-> assume both machines have some efficiency:

=> efficiencies of both machines are different because of their armatuse Currents & excitation Currents is different.

Let Ra = armative of each desistance

I3 = excitation Current of generator

I4 = 11 11 11 motor.

Asmatuse Coppes losses

- > Ia2 Ra = C I1+ I2- I4)2 Ra
- John C II+ I3) Ra

Sheet Copper losses

⇒ VI4

Generato

⇒ VF3

posser drawer foor Rupply is VIE es total gasarable & rooter losses is card to i/p power supplied by rains.

=> stray losses of the machine is obtained by subtracting armative & short Copper losses from i/p power

=> strong losses = 1/p Pocusar from _ total losses of both reachines.

= VI, - (CI+I3) Ra+ (I+I2-I4) Ra+ VI3+ VI4) =W

More is stony Lorses for 2 moetines.

story loves per a mochines

stray losses per one machine = W/2.

Total losses = (I1+I3) Ra + VI3 + W = Wg

O/P = VII => Ng = VIII VII+Wg

Total losses = C II+ I2 - I4) Ra + V I4 + W/2 = Wm

Advantages

-> power seawired is small

-> temperature saine also observed in the form of logies

-> Commutation anolities also observed.

Diradvantages

2 Identical machines.

field test -> for somes motor


-> sequires a machines to perinfrom this test.

-> These emotines are compled to every offer

some machine acts as a motor of atther acts as generates.

> Iton a frictional losses of both machines are made early by O Toining the field cuinding of generate in solly with armation of motor

(11) Both machines makes to run at earl speeds.



full load value indicated by ammater (A).

>> Let V = supply voltage, I = motor Current

V2 = terminal voltage of generate, I2 = load Current

Motor 1/0 90 100-100

Motor 1/p 90 intake of whole set = VII, O/p of generate = V_2I_2

Total losses = motor i/p - Generator O/p = VII - V_I I_ = Wt Armatura & field Cu losses = I12 (Rat 2Rge) + I2 Ra = Wcu

Raz amoutuse stesistance of each machine. Rocz sevies field stesistance of each machine.

(7)

etray laskes = Wt - Weu = Total losses - Cu losses

Stray losses about is for about a machines.

" por machine = Wt - Weu

motor efficiency

Motor 1/pa VIII

Motor losses = armature Car + field cu + Stray losses

losses losses

= Ioi Ra+ Ii Rse + Wos = Wm

= Ii CRa+Rse) + Wos = Wm

= O/P = I/P - motor losses = VIII - Wm

P/P

VIII

Generate efficiency (Ng)

Here generator ofp is consted & it is not, feel back to the motor, so generates efficiency will be small use.

Generator $O/p = V_2 I_2$ there is culose = $I_1^+ R_{Se}$ armstrate culose = $I_2^+ R_0$ Stroy loss = W_0 Total losses = $I_1^+ R_{Se} + I_2^- R_0 + W_0 = W_0$

2g = 0/P = V2 I2 = V2 I2 1/P 0/P+ T.L V2 I2 + Wg

Retordation test

-> Also called as ourning down test

-> used to find stray losses in short machines,

-> By knowing the armateure & field Cu losses we
calculate the efficiency.

Allow the machine to run above the normal speed than supply is cut off from the armature. by maintaining its field constant.

(000)

Now the kinchic energy of armatuse is used to meet the solutional logges.

Kinetic energy => K.E = 1 IW2

where I = moment of inortia of armature


Rotational losses W= gate of charge of K.E

$$W = \frac{d}{dt} (K \cdot E) = \frac{d}{dt} \left(\frac{1}{2} I \omega^2 \right) = I \omega \cdot \frac{d\omega}{dt}$$

case i To find do du du dt

Ovormeter is connected across the armature, acts as a speed indicator because EdN.

a secult voltmeter reading slowly falls down.



let AB > indicate target to rormal speed $\frac{dN}{dt} = \frac{OB \text{ in spm}}{OA \text{ in sec}}$

$$W = I \cdot \frac{d\omega}{dt} = I \cdot \left(\frac{2\pi N}{60}\right) \cdot \frac{d}{dt} \cdot \left(\frac{2\pi N}{60}\right) = I \cdot \left(\frac{2\pi}{60}\right) \cdot \frac{dN^2}{dt}$$

$$W = O \cdot O \cdot I \cdot I \cdot N \cdot \frac{dN}{dt}$$

case !! To find the moment of inertia

(a) To Calculate (I)

shaft a draw the slow down armer of ineotia to the

larger. For any speed dN x dN are determined.

Losses in both machines would be some

country (1) A (2) cases

$$(\mp \mp \mp) \frac{dN}{dt_2} = \pm \frac{dN}{dt_1}$$

$$\frac{dN}{dt_1} \left| \frac{dN}{dt_2} \right| = \frac{I+I_1}{I} \Rightarrow I = I+\frac{dN/dt_2}{dN/dt_1-dN/dt_2}$$

6) and method a whose I is eliminated

In this method an electrical trave is added by means of revistance acts as a setarding trave. This setarding torave making it show down, stown in [fig[]]

Let W' be the additional pooler loss = Ia(Ra+R) & VIa

$$W = \left(\frac{2\pi}{60}\right)^2 \pm N \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$W + W' = \left(\frac{2\pi}{60}\right)^2 \pm N \cdot \frac{dN}{dt}$$

$$\frac{W+W'}{W} = \frac{dt_1}{dt_2} \Rightarrow : W = W' \times \frac{dt_2}{dt_1 - dt_2} = W' \times \frac{t_2}{t_1 - t_2}$$

\frac{dN}{dt_1} = Date charge of speed custout extra # load
\frac{dN}{dt_1} = " " " " " " " \quad \text{custout} extra electrical load.

swinburne's test

A 500V, DC shunt motor trikes 4A on no load, the asimature sustained of 0.2 st., field Current IA, Determine its 0/p 4 efficiency cohen i/p Current is 10A.

Voltage = 500V, line Current 81 no local Current II= 4A, Ra=0:212

=> gives field Current I, & Ish=1A.

No load Condition

field Current = 1A

No load armature Current => Iao = I to - If Iao = 4-1= 3A

IL= If+Ia Ia= IL-Ie

VJf=1AY Jaz?

V- Iao Ra - Eb = 0 => Ebo = V- Jao Ra = 500 - 310. 2 = 499A

=> No load Culasses = Ia Ra = 32 + 012 = 118W

=> Motor i/P = Motor O/P + Total losses

VIL = Motor O/p + (Constart losses + Culosses)

Constart losses Wc = ? Lat motor o/p = 0

Constant losses Wc = Motor P/p - Culosses

= VII - T2 Po - CEO

= VIL - Jao Ra = (500 * 4) - (118)
= 1990w

on-load Condition

load Correct IL=10A

armature Current on load Ia = IL-If = 10-1=9A

=> Back emp Eb = V- Ia Ra = 500-(9*0.2) = 498 V

=) Cu losses on load = Ja2 Ra = 92 x 0.2 = 16.2 W

Total lesses = Wc + Ia2 Ra

We = VIL - Ja2 Ra = (500 * 10) - (16.2) = 1998 w

Moto o/p = Moto i/p - T. L = C500 x 100 - (1998+16.2) = 2986W

1/

III Unit

Ac-machines

single phase transformers

DC generators generated Constant DC Voltage.

To increase on decrease the Constant dc Voltage is not achieved. The Voltages in Case Aic an be charged. To avoid the above Voltage value charging problem we go for using Ac Voltages.

This charge can be done by using Ac machines Best example converting voltages from high to

Best example Converting voltages from high to low . On low to high voltage is done by a devil Called Transferner.

Definition of transformer


It is a static device which transforms voltage on current in one circuit to another circuit without changing frequency.

Supply VI 3 (load side)

Primary winding secondary winding

Load is Connected to secondary side.

e types (1 etep up (22) Step down transformed






fig: Connection type of transformer

-> It consists of magnetic on Iron core & 2 different windings wounded over the core.

-> Here windings forms an electrical circuit A

Core forms the magnetic circuit

principle

on mutal induction b/w the 2 circuits.

If one winding (primary) is connected to the supply of AC, alternating flux of is established in the core due to the current in primary.

Alternating flux in Primary links with the other winding secondary. The alternating flux in endary induces an error in secondary.

If endary winding is closed on short circuited by land, a secondary current will flow.

Finally we conclude that energy in one circuit is transferred to other circuit by maintaining 1/p + 0/p frequency is constant.

Constructional details

they are 3 important parts

- O primary winding @ secondary winding
- 3 Transformer core.

primary winding -> supply part is connected to primary winding secondary winding -> Load past is connected to secondary side is called as secondary winding.

Transformer core

The outer part of transformer is, core.

the core is made up of Iron. It is

secondary windings


Sometimes the core is made up of sillicon steel since to meduce the hysterosis losses.


the Core is made up of some laminated stampings which are insulated each other by varnising metal oxide to seduce eddy eddy current losses.

The thickness of laminating stamping are

Again. Transfermer core are classified as 2 types.

@ core type . (B) shell type





A part of core is sourrounding by the windings.

Sourrounds the core.

It has a limited which is made up of L-shape For each L'shape limb a core sourrounds the cuinding.

colls are usually cylindrical type

type coils are used

> For smaller natings, either savare of sectorgular type coils are used.

Shell type transformer




fig: shell types transformer

An this core sourrounds the winding.

Here 2 windings are carried by a central limb.

The cores are in the stope of E 4 one

stope stampings. Therefore not of limbs is three.

HDEC

It has a parallel magnetic paths.

Transfermer tank

The outer part of machine is tank. It is a metallic Container which com be used for placing a core & windings. The tank is filled transformer oil.

Transformer oil

It is at mineral oil. It provides coolings to transformer core a windings during loading Conditions.

It also acts a insulation b/w tank to

Conservator

It is a drum located at the top of transformer colicity contains transformer coll. It is connected to tank by means of pipe. During loading 4 unloading conditions oil gets contraction t expansion in the space of conservator.

Breather

It is a cylindrical tube consists of a silica get with cobalt. The purpose is to extract fresh air which is used to cool core & winding inside the tonk.

```
Emp eaution of a transformer
    let VI be the Aic voltage applied at
    the primary side having the frequency f.
because of primary voltage current flows
through the primary side induces a flux (1)
in primary side.
   -> struspidal flux 19 primary con
sepresented as
          Ø= Øm sincet
     - where on = maximum sinusoidal flux
  The flux to primary induces an emp in
primary winding
       we know that Induced emp
                       primary
         e= - Nido
                        er= induced enf
                         NI = no + of turns in
       e1 = - Nid ( pm sinut)
           -NI CO Om Coscot
                             CO= 21TF
            - 211 f Ni Om Coscot
         = 211 for NI pm sin (cot - 90) = 211 f NI pm
            el= emi = enfinion
       suns value of Induced emp EI
           e1= emi = 2MFNIOM
             E1 = 4.44 + NI Pm
```

E2 = 4:44 f N2 Pm

E1= induced enf in secondary

E2= induced enf in secondary

N1 & no; of turns in primary 4 secondary

N2 & no; of turns in primary 4 secondary

Transformation ratio | K = V1 = N2 = F1 = E2 |

Losses A efficiency of transformer

Losses in transformer as classified as
Ocore losses of Iron losses (2) Copper losses
The above 2 losses neduces system efficiency
a increases the temperature

core losses.

these losses are due to alternative flux in transformer core. These losses additionally generates hysteres A eddy current losses.

(We) Eddy Current loss = Whit & Bm watt/m3
(We) Eddy Current loss = Whit & Bm frt watt/m3

Wh = Kh + f + Bm

We = Ke * E * Bm f2

Iron losses = Hysteresis + Eddy Current

Hysteresis is minimised by using high stell having more silicon content & Eddy Current losses is minimised by using thin laminations on core

(1) Copper Lorses

These losses occur in both primary & secondary. These are determined from short circuit losses.

Copper losses Peu= I'R

Copper losses vary as savare of load current.
Total losses = 1-ron losses + Copper losses

among 90% of total larges are due to copper lowers only.

Efficiency of transformer

the efficiency of transfermer is defined as it is the ratio of o/p power to i/p power in KW

Efficiency [] = 0/P = 0/P = 0/P + Total losses

2 = full load VA * P.F

(Full load VA) + (P: +Pcu)


(XC)

Transfermer tests

power factors, loads are determined from 2 text (1) open circuit (2) short circuit text.

open circuit on No load text

from this we measure core losses.



(P) > primary side c supply)

(3) -> secondary side (load side) -> open

L.V -> Low voltage winding

cu), ammeter (A), wattmeter are taken at LV side.

Here sated voltage of LV winding is applied to primary a secondary left opened. Applied voltage is measured by voltmeter a no load current is measured by ammeter. No load on Iron losses is measured by wattmeter (Wo). So iron losses is Gonstant during no load on loading.


Iron losses, Pi = Watt meter needing = Wo No load Current To = ammeter reading Applied Voltage = Voltmeter reading = Vo

P/P POWER WO = Vo Io cospo

cospo = No load p.f

cospo = Wo Vo Io


Iw = Io cospo, Im = Io singo
Iw -> working component
In -> magnetising component



In this test measuring enuippments Voltmeter.

Ammeter, wattmeter are Connected at High voltage

winding side & Low voltage winding secondary is short circuited by using thick wire.



Here sated current of High voltage winding is applied to the primary. Due to current in Primary (II) induces a Current in secondary In

Here voltmeter seads short circuit voltage Vsc Ammeter seads primary rated current I, wattmeter seads full load cu losses = Ws

full load Cupper losses = 17 Ro1

$$\frac{P_{c} = P_{1}^{2} Ro1}{Ro1 = \frac{P_{c}}{\tilde{I}_{1}^{2}}}$$

equivalent resistance of the former nafer to primary.

During no load Conditions Cu losses is small during loading Conditions Cu losses is almost doubles: So Cu losses are also called variable losses

eauvalent impedance siefer to Voc primary Zoi = Voc II

Total 81 eavivalent seactorice sefor to primary

XOI= $\sqrt{Zoi^2 - Roi}$

full load Copper 10 eses Pe = Vac II Cos Osc

 $Cos\phi_{sc} = \frac{P_c}{V_{sc} I_i}$

Problem

A 20 KVA transformer has 200 turns on primary & 4 to turns on secondary. Primary is connected to 1000V, 50Hz supply. Determine (1) 2 ndarry Voltage on open Circuit
(11) Current flowing through, 2 windings on full load (111) maximum value of flux.

not of turns in primary NI = 200

Not of turns in secondary Nz = 40

frequency f = 50Hz; primary voltage V = 1000v

II = ?, Iz = ?, secondary voltage Vz = ?

WINHITE

1 secondary voltage , V2

we know that transformation satio

$$K = \frac{V_2}{V_1} = \frac{N_2}{N_1} = \frac{E_2}{E_1} = \frac{I_1}{I_2}$$

$$K = V_2 = \frac{N_2}{V_1}$$

V2 = V1 * N2 = 1000 * 40 = 200 V

(1) Correct flowing through primary II

Current flowing through secondary In

(111) Maximum value of flux pm=?

Pm = E1 = 22.52 mub

Problem

2) single phase transformer has frequency 50 Hz

having no load satio is 6600. V. If maximum value of flux is 0.09 Weber, find the number of turns in each cuindings.

sel frequency of= 50Hz, Primary voltage V=26600V secondary voltage V=300V, flux pn=0.09wb

```
find number of turns NI 1 N2
                 No load salio = 6600 - VI
      we know that Enf equation of transformer
     E1= 4.44 * f * Øm * NI
     300 = 444 + 50 + 0.09 + NI
   K = \begin{bmatrix} V_2 = E_2 = I_1 = N_2 \\ V_1 = E_1 & I_2 \end{bmatrix} = \begin{bmatrix} N_1 = N_2 \\ N_2 = \frac{300}{4444} \end{bmatrix}
                                      444 $ 50 × 0 .09
      N1 = V2 = 300
4.44 * f * Øm 4.44 * 50 * 0.09
Problem 3 A 6600/440 V single phase 600 KVA
transformer has 1200 pointing turns find
1) Transformation statio (11) Secondary turns
(111) Voltage/turn (111) secondary Current codes
supplied a load 400 kw at 0.8 p.f lagging.
     given
     Vi= 6 1 = 6600
            V2= E2= 440 ..
     transformer sating = 600 KVA
     primary turns NI= 1200
 secondary voltage E== 440V
  (1) K= ? (11) Secondary turns (11) secondary
 (IV) Voltage / turn = ?
1) transformation statio
             K= V2 = 440 = 0.066
```

1 secondary turns

$$K = V_2 = N_L$$

$$V_1 . N_1$$

(111) Voltage/twon

(IV) secondary Current (I) when it supplies tood.

400 km at 018 p.f.

$$I_2 = \frac{400 * 1000}{440 * 0.8} = 1136.36A$$

Total primary no load Correct. (2) $I_0 = \sqrt{I_{\infty}^2 + I_{\perp}^2}$

Important points to be semember

(1) No load primary Current To is very small find

Compared to full load primary Current.

(11) As primary no load Current To is very small

Cu (copper) losses in Primary on no load is

neglitible.

Problems on No-load

factor 0.3 on open circuited. Find magnesisting a working Components of no load primary Current.

sol Primary voltage $V_1 = 2200 \text{ V}$ 2 ndary voltage $V_2 = 250 \text{ V}$ No load Current Io = 0.5 A

No load Power factor cospo = 0.3 => cos-1(0.3) find I'm (magnetising component) = ? \$0 = 72.54 Iw (working Component) = ?

- 1 Iu = Iosing = 0.5 * sin (7254) = 0.476A
- 2) Iw= Iocospo = 0.5 * 0.3 = 0-15A
- Do no load current of toformer is 15A howing power factor of 0.2 when connected to 460V, 50Hz supply. If primary winding has 550 turns calculate (1) I've city loss (111) maximum value of flux pm

```
Given date

no load current To = 15A

p.f. cospo = 0.2

V1 = 460V = E1

Potrmory winding NI = 550

Potrmory winding NI = 550

The Tosing = E1 15 * Sin C78'4) = 14'7 A

CII) Iron loss Wo = V1 Iocospo

= 460 *0.5 * 0.2 = 138 ii

CIII) maximum value of flux (pm)

E1 = 4.44 * 0 * f * N1
```

Øm = E1 = 460 = 3.77 m web 4.44 x f x N1 . 4.44 x 50 x 550

Find (1) active Component Iw (11) Reactive Component Ire (111) no board Current Io at a pawer factor 0.25 legging having 230V/115 v If i/p power on no load to high Voltage winding is tow.


primary voltage V1 = 230V 2ndary voltage V2 = 115V No load P/P power Wo & Po = 70 W Power factor = 500 = 0.25

\$0 = CO8-1(0.25) = 75.52

1 Active Component

Iw = Io Cospo

Io=?



Primary Current flows through the primary winding but up a flux is core.




fig stows transformer under load condition


Secondary Current Is established a flux of.

This flux of opposses the flux cop) & decrease
the no load flux . Hence primary induced event

El Deduces 2 more Current flores through primary

Let the additional primary Current be I2. It is known as load Component of primary Current. It opposite on antiphase cuits I2.

I I establishes a flux \$92 cohich is opposite to direction of \$92 - Hence \$92! + \$92 Cancels each other. It is shown in find



Let NI -> no; of turns in primary

Th -> Primary Current on no local

No -> no; of turns in andary

ive

.

I2 > secondary amorest (T4)

I2' > Load Component of Primary Current

$$\frac{N_2}{N_1} = \frac{I_1}{I_2} = K \longrightarrow 0$$

secondary Current In creates an additional current in primary side, this is given as In. Ip = In!


N2I2 = NIII

NLIL = NII

$$I_2' = \frac{N_2}{N_1} * I_2 = K * I_2$$

During loading on unloaded Condition, flux possing through the case is constant.

Extra d



fig@ phasor diagrams for non inductive load (Resistive Load)




fig B) phoson diagram
for inducive
load.

I2 -> secondary aurrent

I'm Load Component of primary Current

$$\frac{N_2}{N_1} = \frac{I_1}{I_2} = K \rightarrow 0$$

puring leading Condition on secondary Secondary Current Iz creates an additional Current in primary side, this is given as Io = I2 I2':

> N2 I2 = NII NLIL = NIIL

 $I_2' = \frac{N_2}{N_1} * I_2 = K * I_2$

During loading on unloaded Condition, flux passing through the core is constant.

Fortra peed

EL

fig@ phasor diagram for non inductive load (Registive boad)




fig () phoson diagram for induvive

from fig@ Is is in phase with Es. It causes

Primary Component of load Current Is which is


arriphase with Is A is equal in magnitude

Total primary current I, is the sum of Is! 4

Io. II logs betind voltage at an argle Ø1.

from figb

Here Is lag Es by \$2. Current Is is in antiphase cutty Is.




To is required

fig@ shows that \$1>\$\psi_1\$, neglect Io
then \$1=\$\P2\$

NII' = N2II = HIT2

$$\frac{N_2}{N_1} = \frac{T_1}{T_L} = \frac{T_2}{T_2} = K$$



y winding or v

Equivalent circuit of transformer An equivalent circuit is used to evaluate or describe som behaviour using equations. figo shows eavivalent circuit of transformer XI I, 3 51 E.2 Ro & Xog -> puring no load Condition, transformer draws no load in primary side. No load current Io Produce flux 4 Core losses in Core -> From loss Component is sepresented by (Ro) non

inductive registance à magnitude magnitising Current by Xo.

Both Ro 4 to are Connected in parallel airy Primary winding. Bo 4 to branch is called as No load branch or exciting branch.

BI, XI > Primary Resistance 4 meactance in se Ro, Xo, -> No load Resistance + gréactance in se Full load primary Current in NO load -> Load Component of primary current in Amp working Component In -> magnesisting Component -> induced emp in primary

Rr, X2 -> 2nday winding sesistance & seachance in I


Z1 = load impedance

In= full load endang Current in Amp

1 = transformation ratio

Fauivalent circuit safer to primary (exact of)

If all the endary parameters are transferred to primary side is shown in given fig




While transferring the endary parameters to Primary side, Resistances, measterness are divided by K2

Currents are multiplied by K

the circuit is Called as exact equivalent circuit of transformer.

$$R_{2}^{1} = \frac{A_{2}}{K_{L}}$$
, $X_{2}^{1} = \frac{X_{2}}{K^{2}}$, $V_{2}^{1} = \frac{V_{2}}{K}$, $I_{2}^{1} = KI_{2}$
 $R_{0} = \frac{V_{1}}{I_{W}}$, $X_{0} = \frac{V_{2}}{I_{W}}$ $Z_{L}^{1} = \frac{ZL}{K^{2}}$

Approximate eauvalent circuit is drawn as



fig@ approximate equivalent circuit

current. So $I_2' = I_1$. So exciting branch on to load Granch is transferred to left side of circuit stown in above fig@.

Combined all sexistances in figure \mathbb{Q} $R_{01} = R_1 + R_2^1 = R_1 + \frac{R_2}{R^2}$ Similarly add all secucionces in fig. $X_{01} = X_1 + X_2^1$

Theor above stig@ is sedrous as

Roi Xoi

VI

VI

Roi Zoi= Roi+iXoi

VI

Roi Zoi = Roi+iXoi

VI

Roi Zoi = Roi+iXoi

VI

Roi Zoi

VI

Roi Xoi


Roi Xoi


VI

Roi Xoi

Ro

fig 3 shows all parameters seperred to Primary





fig@ all parameters separred to secondary

 $Z_{02} = R_{02} + j \times_{02}$ $|Z_{02}| = \sqrt{R_{02}^2 + x_{02}^2}$


phosor diagrams


fig () shows phasor diagrams of pratical transformer for inductive load (lagging power factor)

Both E1 LE2 lags the mutal flux by 900.

The 1110 load Component of primary Current Is'
rentralises the dermagnetising current Is

Transferrers





```
losses in Transformer
                                                  جلی
Efficiency of a transformer
  Transformer efficiency 7 = 0/p power
                                                   ong
                         O/p+ fron losses + copper losse
         0/p+ Total losses
  O/p power = V2I2coso
    cotere V2 = secondary terminal voltage on load
            In = " Current at load
          cosp = Power factor at load
 Iron losses is derived from occ text it is
given as Pr = Wo.
 Copper losses is derived from soc test it is
given tos Pau = Wsc. at full load
    let x be load of the transfermer
                                                  1 ×01 5
is transformer efficiency of = x + V2 + I2 + cosp
at x= 100% full load
   x= 50% at 1/2 load
                 XX KVA * COSØ
                X + KVA + COS Ø + P; + xº Pau
```

Regulation of transformer

(T9)

Proper operation of electrical opporatus depends on the stated voltage. During transformer on loading, the o/p voltage varies we have to maintain the o/p voltage with variations

Definition

Voltage from fill Load to the Load terminal Voltage

 V_1 Regulation = $\frac{V_2 - V_{2CF \cdot L}}{V_2}$ + 100

= V2 N-L - V2 F-L * 100

N·L → No load F·L → ful load

Regulation for ideal transformer is 0%.

1. Regulation = Voltage drop +100 = IIROI cosq + I, xol

1. Reg = II Rol Cosp + II X 01 Soln # 100

+ -> lagging - -> leading

for unity Power factor Y. Reg = IIROI > 100

Problem

Conducting an 15KVA 450/20V, 50H3 transfer-

Shoot circuit test

V_= V_{SC} = 9.65 V

I_1 = I_{SC} = 22.2A

See all on High voltage sid

W_{Cu} = W_{SC} = 120 W

calculate: (1) draw its equivalent circuit reprisonming

(11) Efficiency, (11) (7) efficiency at 1/2 load

for 0.8 lag p.p.

and 0.8 lag p.p.

30
$$V_1 = 450$$
, $V_2 = 120$
 $V_1 = \frac{V_2}{V_1} = 0.266$

$$\frac{V_2}{V_1} = \frac{I_1}{I_2} = \frac{I_0}{I_1} = 0.266$$

$$I_0 = I_1 + 0.266$$

No load Primary Current.

Io = Io * K = 4. Q * 0.266 = 1.12A

Primary volleage VI= 450V

W:= W0 = 80 W

W:= VIJo COSO

80 = 450 * 1-12 * cos \$00

Cospo = 0.159

\$0 = Cos-1(0-159) = 80-9

Sindo = 810680.9) = 0.987

32

Leonaforman

Charking Component (Iw): Iw = Io Cospo 2 1-12 x 0-159 = 0.178 A Magnetising Component (Iw) In= Josing = 1-12 * 0-987 = 1-1A $R_0 = \frac{V_1}{I_{\omega}} = \frac{450}{0-178} = 2530 \Omega$ $\times 0 = \frac{V_1}{I_{u}} = \frac{450}{1-1} = 409$ V1=450, V1=120 V instruments seeds on primary ride, so are con 5.c test consider a wattingles beads Pointage side Vsc = 9.65, Isc = 22.A, Wsc = Pcu = 120 W Copper $\frac{Z_{\text{ci}}}{I_{\text{sc}}} = \frac{V_{\text{sc}}}{I_{\text{sc}}} = \frac{9.65}{22.2} = 0.435 \Omega$ Isc Ro1 = Wsc => (22'2) * Ro1 = 120W Ror = 0.24352/ Zoi= V Roi + xoi X01 = Z01 - R01 => X01 = \ Z012 - R01 = 0.36) O approximate eautvalent circuit エ VI TIN Y ILL

```
Efficiency 1 = oft borcer
                                  P.F = C08 $ = 0.8
   O/P Power = KVA * P.F
              = 15 * 1000 * 0:8
              = 12000 W
   1/P Power = O/P Power + Total losses
   Total losses = iron losses + Copper losses
                = (80+120) = 200 W
  1/p Power = 12000 + 200 = 12,200 W
       = 12000 + 100 = 98.36%
 6) Voltage segulation
     1. Reg = Voltage drop * 100
                   1/p voltage
Voltage drop = II ( Boi cospo + Xoisingo)
    full load Current I1 = KVA = 15 + 103 = 33.3 A
Voltage drop = 33:33 (0.243 * 0.8 + 0.361 * 0.6)
                       = 13.69V
CO30 = 0.2
                     7. Regulation > 13.69 + 100
 Ø = cos-1(0.8) =
Sin( ) = 0.6
                             = 3.04 %
```

The losses = 80 W

Cu losses = $\chi^2 + W_{80}$ Cu losses = $\chi^2 + W_{80}$ $= (\gamma_2) * 120 = 300$ Total losses = $\chi^2 + W_{80}$ $= (\gamma_2) * 120 = 300$ $= (\gamma_2$

Problem (2) Raving of transformer is 40kvA having

Primary 4 endany Desistences are 102 4 0.022

at 6600/250 V. Eausvalent leakage Dealtone Deferred

to primary ounding is 352. Find full lead Degulations at various power factors (1) cost by (11)0.8 log

(111) 018 leading

frimary sesistance R1= 1052 2ndary sesistance R2= 0.0252

= 98-197.

leakage sneactance seferred to primary X01=35 she primary voltage V1=6600, 2nd army Voltage V2=250V

... Transformation gratio $K = \frac{V_2}{V_1} = \frac{250}{6600} = 0.0378$

```
Equivalent assistance orefor to primary
      R_{01} = R_{1} + R_{2} = R_{1} + R_{2} = 10 + 0.02 = 24.52
       we know that %- Voltage Regulation sufar
to primary
    1. Regulation = II (Roicosø±) xoisinø) + 100
 Here + for lagging
  - for leading
 1 V. Regulation for unity Power factor
          CO3Ø=1
             Ø = cos-1(1)=0
          Sing = Sinco) = 0
    Primary Consent II = KVA rating
                           Primary vollage
        40 71000 = 6.06 A
1. Reg = I. ( ROICOSØ + XOISIND) + 100
        = 6.06 (24 +1 + 35 +0) = 6.06 +24 +100
                   6600
1. Reg = 2.203
(11) V. Regulation for 0.8 lagging P.f
    C030 = 0.8
       Ø = co8-100.8) = 36.86
     Sin(36.86) = 0.6
  Primary Current IL = 6.06 A
```

T 13

need an order to determine. Efficiency A Regulation over the data of open circuit A short circuit test. From these data we can predetermine the efficiency A segulation at various power factors A various load are obtained.

Example Find the Degulation, efficiently of transformer at various loads A power factors from the given data of o'C A S.C test Conducted on I KVA sahing having primary voltage 2004 A secondary voltage 110V.

5.c test: Vo= 110v, Io=1.2A, Wo=55.2w S.c test: Vsc= WAV, Ioc=5A, Wsc=50W

sol from o.c test

 $W_0 = V_0 I_0 \cos \phi$ $W_0 = V_0 I_0 \cos \phi$ $W_0 = V_0 I_0 = \frac{55.2}{110 \times 1.2} = 0.418$ $W_0 = C_0 \times V_0 I_0 = \frac{55.2}{110 \times 1.2} = 0.418$

Sing = Sin (65:29) = 0-908

-> working Component & IW = [To cosq) = 1.2 x 0.418 = 0.50

-> Magnetising Current Iu= [Iosina]= 1.2 * 0.408=1.08 A

 \rightarrow No load DiesiAtance $|R_0 = \frac{V_0}{J_{\infty}} = \frac{110}{0.50} = 2202$

Transfermers

Short circuit test

$$V_{SC} = 9.8$$
, $J_{SC} = 50$, $W_{SC} = 50$ W

 $V_{I} = 200V$, $V_{2} = 110V$
 $\Rightarrow W_{SC} = \frac{10}{V_{1}} = \frac{abb}{V_{10}} = \frac{10}{200} = 0.55$
 $\Rightarrow W_{SC} = \frac{10}{V_{10}} = \frac{10}{100} = 0.55$
 $\Rightarrow W_{SC} = \frac{10}{V_{10}} = \frac{50}{(5)^{1}} = 2.2$
 $\Rightarrow V_{SC} = \sqrt{\frac{1}{2}} = \frac{50}{(5)^{1}} = 2.2$
 $\Rightarrow V_{O2} = \sqrt{\frac{1}{2}} = \frac{10.8}{(5)^{1}} = 2.0$
 $\Rightarrow V_{O2} = \sqrt{\frac{1}{2}} = \frac{10.8}{(5)^{1}} = 2.0$
 $\Rightarrow V_{O2} = \sqrt{\frac{1}{2}} = \frac{10.8}{(5)^{1}} = \frac{10.8}{(5)^{1}} = \frac{10.85}{(5)^{1}} = \frac{10.85}{(5)$

```
efficiency 7 = DC + KVA + COSØ
                 XX KVA * COS & * Wo+ x2 Wsc
  where x = load i.e 0.25, 0.50, 0.75, 100%.
  We = ivon losses, Wac = copper losses
             cosp = 0.2, 0.4, 0.6, 0.8, 1
Similarly
          1. Regulation is
  7. Reg = xx Isc (Rozcosø + Xozsinø)
                        V2
                          V10=55.2
   + -> lagging
                         Wac: 50
        s leading
> At load x= 25% on x=0:25, efficiency 4
Diegulation is
* x=0.25, cosp=0.2 => p= cos-1(0.2)= 78.46
          Sing= Sinc78'46) =0.979
* efficiency 7 = 0.25 * 1 * 1000 + 0.2
                 0.25 + 1 + 1000 + 0.2 + 55.2+ (0.25)2 + 50
           = 0.05+1000
                                            = 0.46
                                50
              0.05+55.2+3.125
                               50+55:2+3:125
            = 46 % at cosp=0.2
                   0.25 * 5 (2*0.2 + 0.4 *0.979)
 1/- Regulation =
                   1-25 (0.4+0.36) = 0.899
   [lead 0.042,)
```

```
at cos $ 20.4 sind = Sin (66.42) = 0.916
       Ø=cos-100.4)=66.42
               2 = 1025 (2*002 +-4*0.916) *100
1. Regulation
  at cosp=0.4
                   = 0:870, lead (0.038)
  at using power factor 1. Reg is
      C030=1
         $ = cos-((1) =0, sind= sinco)=0
                  1.25 (2+0.2+0) *100
                 = 0-45.
Efficiency at load 50%
    x= 50% = 0.5, cos $ =0.2
efficiency 1 =
               CX* KVA* COSØ)+ Wo+X2 WSC
    = 0-5 * 1 * 1000 4 06400
                            ¥ 100 = 59'630
      (·100+55.2+(0.5)2+50)
1. Regulation at cosp=0.4, 5:170=0.9165
           X * Isc (Roz Cosp + Xozsing) *100
      0.5 + 5 ( 20 +0.4 + (0.4 + 0.9165)
      2.5 (0.8 + 0.3666) = 2.69, Lead CHOILE
                                      130·985
                110
```

```
ali cosp=1, sinp=0
 y. segularion
              0.5 * 5 (0.8) = 0-909
at ces$ = 0.2, sing = 0.9797
 1. regulation = 2.5 (0.4) = 0.18
efficiency at load x=100 % & x=1
                                     at cosp 20.2
         X* KVA* COS $ * 100
         XXXXXX COSØ + WO + x2 WSC
          1 * 1 * 1000 * 0.2 * 100 = 65.5 y.
            200+55.2+50
  Y. Regulation at load x=1, Cosp=0.2
Ø = cos-1 co.2) = 78.46 , sing= sinc78.46) = 0.9797
 1. Reg = x Isc ( Rozcosø + Xoz sino) , 100
                        Vy
        = 5(2+0.2+0.4+0.9797) +100=, 門井1
                                        = 3.59
               lag = 3.59, lead 0.0369
   cosq = 0.4 , sing = 0-91651
 1. Rey = 5 (2*0.4+0.4*0.91657) 2100 - 5.30
```

cos\$2018 sin\$20.6 cos = 0.6, sin = 20.8 4. Reg = 8.3 long J. Reg = 5(2*0.6+0.4*0.8) lead 6.18 1. Reg = 6-909 lead 4 Cos \$= 1 Sin\$=0 5(2) 9.09 As load increases efficiency increases As Power factor increases, oregulation increase load P.f efficiency oregulation

```
transformere > problems
      Performance of single phose T/f having 200/400 V, 5048
 has following data.
 Ooc test: 200V, O. 7A, 70W OD L. V side
 (1) sic test: 150, 10A, 85W on HIV side > Reads on HIV
 -> colculate endany voltage V2 while delivering [5 kw of power
 at 0.8 P.f lag, pairmany Nottage V1=200V.
 Given pointing Voltage V1=200 = E1

2 hidaay Voltage V2 = 400 = E2

O.C test: V0=200V, I0=0.7, W1=70W.

E2 = V2 = 400 = 2

E1 . V1 = 200 = 2
                                                for astimon a de
                                             Ez = V2 = 400 = 2 = X
 Sictost: Vac=150, Isc=10A, Wau=85w
                                (V) Rol = Roz = 0.85 = 0.71 x
 from oc test
 Ico= To cosp.
                                (1) X01= \Z012 - R012 = \((0.375)^2-(0.21)^2
  Wi = VI To cosp
   cosp = 40 => To = 70 | Xo1 = 0.31

cosp = 200 * To = 200 * cosp > given of of theremed is 5 KW at 0.8

cosp = 0.31
> cosp = 70 = 0.5
                                 Pif lagg
                                                              cosp, =0.8
=> sing = 0.866 | V2 I2 COSØ2 = 5 * 1000 | V2 = N-L
Iw= Iocosp = 0.7 + 0.5 = 0.35 = 12 = 5 + 1000 = 15 6 A, = 400
                                              400 +018
In= Tosing = 0.7 + 0.866 =
                In= 0.606A => endary voltage at full load ( V2(FL))
=> Po = Vi = 200 = 571.4 \ . 81 Total voltage drop in 2 rday
\Rightarrow x_0 = v_1/x_0 = \frac{200}{0.606} = 3302 = x_2(Ro_2 \cos \phi_2 + x_{02} \sin \phi_2) = x_0
    from 3.c. test = 15.6 (0.85 *0.8 + 1.24 *0.6) = 22.21
                                => 2rdoory voltage doop
 Vsc = 15 V, Isc = 10A, War = 85W
 given all parameters selve to
                                      V2 = V2CN-L) - V2CF.L) = 400-22-QV
 be wasning.
                                   V2 = 377'84
   Ro1 = 8 XO1 = 8 , ZO1 = 8
                                => 1/2 voltage Degulation pough
1 Zoz = Vsc = 15 = 1.5
      Jec
                                        = V2 CNIL) - V2 CFIL) * (00
(11) Weu = Isc * Roz = 85
   Roz = 85/(10)2 = 0.85 D
                                           400 - 22.2V x 100 = 94'46
(111) X02 = \ Z02 - Ro, -
                                              400
x02 = √(1.5)2 - (0.85)2 = 1.24 SL
                                          endary total vollege drap ( 1/2 1/2) = 100
                                1/ Reg =
(IV) ZOI = ZOL = 1.5 = 0.375
                                                  V2 CN. L)
             Kz
                   C2 12
                                       = 5.5 %
```

```
A E30/460V theorer has Polinary Segistence B1=0.22, X1=0.55
    corresponding values for endany one R2=0-75D, X2=1852.
    Find 1) endany terminal voitage V2, supplying a load of 10A at
    0.8 Pif lag, first 168 Voltage Degulation.
308
           V1=230, 2rday voltage on no load V2 = 460 V
    => K= V2 (N.L) = 460 = 2 , T2 = 10A , COSO1 = 0.8
     BI=0.50, XI=0.50, RI=0.750, X2=1.80
     1. Regulation sufer to endary = | 72 ( Be cosp + 7281002) $100
     Iz ( & cosp + sind ) = Total voitinge drop in endary or endary
    Voltage at full load.
    => Convert all the parameters of Asimany to endowy side
    Equivalent seristance refer endary (Roz = Rz + KZRI
        el greditance 11 10x 11 Xoz =
   Roz = 0.75 + C2) + 0.2 = 0.75 + 0.8 = 1.55 &
  X01 = 1.8 + (2)2 + 0.5 = 1.8 + 2 = 3.82
   => 2 rdasy voltage drop at full load = [Iz(Rozcosq + Xozsino)]
   given
             cosp = 0.8, SIND = 0.6, T2 = 10A
     V2 CF. L) = 10 (1.55 + 0.8 + 3.8 +0.6) = 35.2V
   => 1. voltage diffithation = endang voltage drop
                                             at full load $ 100
   \frac{V_2(F\cdot L)}{V_2(N\cdot L)} $100 = \frac{35\cdot 2}{460} $100 = 7.65%.
                                           endary voltage at
                                           Ho lood MON
    Theirfore endany voltage drop Ve = V2 (N. L) - V2 (FIL)
   the season - removed - st
                                   V2 = 460 - 3512 = 42418 V
```

1 19 15 2

```
Condition for maximum efficiency ( naz)
  efficiency is maximum if Culoses Pou = Iron losses P.
 Let Culosses | Pau = In Roi
  let Iron losses P: = Hysteresis + Eddy ament losses
= Wh + We

> Noce Coreidered at pormary 1/p side
   Arput = V_1 I_1 \cos \phi_1

Etticiency Q = \frac{0/p}{i/p} = \frac{1/p - T \cdot L}{i/p} \frac{i/p = 0/p + T \cdot L}{i/p} \frac{i/p}{i/p} = \frac{i/p - T \cdot L}{i/p}
 Total larges = Iron losses + Cu losses = P: + I; Roi

\begin{cases}
= 1 - \frac{P_1}{V_1 I_1 \cos \phi_1} - \frac{R_{01} * I_1}{V_1 \cos \phi_1} & \longrightarrow 0
\end{cases}

     differentiating cauchion ( W. r. to II we get
\frac{d\eta}{d\pi_{1}} = 0 + \frac{P_{1}}{V_{1}\cos\phi_{1}} + \frac{Ro_{1}}{V_{1}\cos\phi_{1}}
0 = 0 + \frac{P_{1}}{V_{1}\cos\phi_{1}} + \frac{Ro_{1}}{V_{1}\cos\phi_{1}}
\frac{d}{dx}
\frac{d}{dx}
   \frac{P_{i}}{V_{i}I_{i}^{2}\cos\beta_{i}} = \frac{R_{01}}{V_{i}\cos\beta_{i}} = \frac{P_{i}}{I_{i}^{2}} = R_{01}
\frac{d}{dI_{i}}\left(\frac{1}{I_{i}}\right) = \frac{1}{V_{i}\cos\beta_{i}}
                                                P_{i} = I_{i} R_{0i}
\frac{d}{d \pm i} (I_{i}) =
=> Load KVA at 1 max = I+KVA + Iron losses = -1 I,

=> Load KVA at 1 max = I+KVA + Iron losses = -1 I,
  X= Full Load KVA 80

V2 load KVA = 2 XX KVA * P:

Ti
=> load in Kw at Pinax = x+KVA*Pf + Pi
```

(a) A 25 KVA, 2500/150 V 1- phase transferrace has Iron losses = 960 W

full load Cu losses = 1500 watts. calculate at cotat. load maximum efficiency accurages & find the value of maximum efficiency at unity power factor.

KVA Brading = 25

V1 = 2500, V2 = 250V, Iron losses Pi = 950 W, Pau = 1500 watter

Load KVA at maximum efficiency = x2 * KVA * Pi x2 Pau

X = full load = 100× = 1

= 25 * 960 = 20 KVA

VIN 1500

Cm = 0/P > 0/P = X*KVA * Pi = 1 * 25 * 1 = 25 KVA

TY KVA*Pi + Till


at maximum efficiency Pi = Pau = 960 w

Total losses = Pi+Pau = 960+960 = 1920 kco

Cmax = 25 * 1000 = 92:86 %

(| A 250/ 500V, 50Hg T/f Primary resistance & seactinge are 0.1752, 0.3752 + endary Desistance 4 Deacharces are Re= 7802 X= 2652. Determine voltage segulation, losses, efficiency delivering GKVA at 0.8 P.f leading at orated voltage. VI= 250V, 2 ndooy voltage at 10 load V2 cNIL) = 500V, \$=50Hz امد R1=0.1751, R2=7801, X1=0.3751 4 X2=2651, COSO2=0.8 => transfermation source K= V2 (N.L) = 500 = 2 1 % Regulation = V2CN.L) - V2CF-L) + 100 VYHAMMANAMANA) > Izc Rozcosp + xozson () = 2rdory voltagedrop at full load VecF.L) => Convert all primary presincters into endary side Roz = R2+ K2R1 = 780+ (2) + 0-175 = 780+0.7 = 780-752 X02 = X2+ K2 X1 = 265+ C2) + 0.375 = 265+ 1.5 = 266-5 T => 2rdooy voltage doop V2CF.L) = 12(780.7+0.8+0.6 + 266.5) = 9406.8 gives 6 × 1000 = V2 I2 cosø V2 = 5575.9 6+1000 = I2 > 12A 500 ¥ losses = ohnic losses = I2 Roz = (12)2 x 780.7 = 112.42 KW 1. efficiency 7 = 0/p = V2I2 + COSØ2 = 500+12+0.8 0/P + T.L (500+12+018)+112.42 4800 × 100 = 97.71

Sumpner's Test 0 -> Also called as back-back test & Regenerative test. 8 heat loss test -> This test in Authobia for Conducting full load on large transferences. -> This test , Dearlines 2 transformers of some KVA -> Here primaries of 2 +1/fs are connected in parallel 4 are Connected to supply. > 2 titis endances and connected in series out polarities in place opposition. auth polimories. -> Their phase opposition are identiced using a Nothmeter Connected in endaries side. -> If voitness indicates Zero means, their andorses are in phase opposition. Otherwise voltage greads -> If voltometer sends any value, there are not in phase apposition, Just by interchange ardary terminals procedure to conduct test -> ey opening the secondary side SPST southers open a difficulty apply saled voltage across side. reds only iron losses in Princey → By closing SPST switch on inday side apply gated arrest to the endacy side. -> wathroster we greate full load a losses on -> from Iron + Cu losses we determine efficiency, 1/2 Regulation at any lead + Pif are preditarnised. -> power loss in this test are twice or doubles the single



Advantages of sumpners test

3


> nigher Capacity of t/former Con be tested without using actual load.

- -> power seaword is very small
- Also used to fird a losses, iron losses, efficiency of degulation at any desired load & desired Pif
- → It is also used to reasure temperature give at any load.

Dixadvavlages of sumprer test.

-> Requires 1 identical thormous of some salings.

Separation of losses in 1-phase transformer 0 -> are know that induced early of transformer e=4.44*f* Øm* N N -> no; of turns 2 is fixed, only frequency + two in that is going to be charges edfom => on = e => During no load, induced emple 2 V. Øm x V To maintain fuex in are constant, are maintain Ve outro Constant. Here separation of iron lasses is proformed at various for aversics to reasontin V/F gasio Constant. Reasoneres to case out test -> securres on alternator, which is driven by DC motor -> A 2 coinding transformer which is of single phase -> Liv awarding of theorner is connected to any a phases of 3 place statos of alternator -> H.V wirding of theorem is kept open W 1300 Vorsicoble LPP spead Wattmeter relote



-> A LAF wattometer Connected across the LV side of

Procedure for Conducting test

1) close oper switch, allow notes to run at Constant speed say N. having freavorcy (f).

 $N_1 = \frac{120f}{p} \Rightarrow f = \frac{N_1 * p}{120}$

2) Adust the field of alternator wortill a voltmeter reads

```
Vi = f, * Pated L.V Nice voltage of T/f

Rated supply frequency.

> measure the speed of motor as N2, corresponding voltage V2 = f2 * V

f

> procedure is seperated for variable speed of rote days voltage, continues sading a calculate frequency
```

For core losses of sinusoidal i/p
total core losses = Hysteresis + Eddy Current losses
Pc or W: & Wc = Wh + We

Wh = P + B max + f & We = BB max + f2

P, Q are Constants & are Calculate hystoresis & eddy Current losses.

Wi = Wn + We = P*B^{1.6}

$$\frac{W_{i}}{f}$$
 = PB^{1.6}
 $\frac{W_{i}}{f}$ = $\frac{W_{i$

We = K2 x p2 } Hence from loves are
Seposated

Who Kh*f We= Ke*f2

```
Iron losses of transformer Core at rosmal flore donsity was 3
reparted at frequency 30Hz & 50Hz, seemlls are being
30W & 5400 - Calculate 1 Hyeroscesis loss & (11) eddy current
loss-
total core loss in a transferner
> W:= Wh+ We = PB max * f + QB max * f2
   if flux density is Constant
                                      Kh= KI ->
> W: = Kb*f + Ke*f2 -> 1
                                      Ke = K2 ->
 At f=30H3, W:=30W
                                At f=50H3, W= 54W
=> 30 = Kh + 30 + Ke * (30)2 → @
                                54 = Kh (50) + Ke (50)2
 30 = 30 * Kb + 900 * Ke -
                                54= 50 Kg + 2500 Ke →3
 solve equations (2) & (3) we get
  Kh=0.88 , Ke= 4 * 10-3 = 0.004
=) Hysterain losses & eddy Correct losses at f=50H8 &
     Wb = 0.88 * 50 = 44W
                            since Wh = Kh x f
     We = Ke * f2 = (0.004) * (50)2 = 10W
  Wia Wh+ We = 44+10= 54W
=> Hysteresis losses 4 eddy aurent losses at f=30Hz is
 Wh= Kh*f= 0.88 + 30= 26.4W
 We = Kexf2 = 0.004 * (30) = 3.6
 W:= Wh+We = 26.4 + 3.6 = 30W
A 440V, 50Hz transfermer has total from losses are 2500W at
normal voltage & frequency. when applied voltage & frequency
wore 2004, 25Hz, fron loxes are found to be 850W.
Calculate Hystosegie & eddy Current losses at normal voltage
 for case 1 details
                       for case (ti) details
  V=440V
                        V= 220V
  f=50Hz
                        f= 25Hz
Iron losses W = 2500W
                        W: = 850W
```

```
Hysteresis losses Win = Khit at f=50Hz W:= 2500W (4)
      Wh= Kh $50 = 50 * Kh ; We= Ke * f2 = Ke * 2500
      W:= Wh+ We => 2500 = 50 + Kh + 2500 * Ke -> 0
    =) At f=25Hz, Pron losses is 850W
      Wi = Wh + We => 850W = Kh * f + Ke * f2
                         850 = Kh * 25 + Ke * 625 → 1
       50 Kg + 2500 + Ke = 2500
       25Kh+625 * Ke = 850
           Kn=18, Ke=0.64
    > At normal frequency, tysteresis & eddy Corrent losses are
      Wh= Kh*f = 18 * 50 = 900 W
      We = Ke*f2 = 0.64 * (50)2 = 1600 W
     Wi= Wh+ We = 900+1600 = 2500W
(6)
    Transformer is Connected to 1000 V, 50 HZ supply, Core losses is 1000 W,
    typeparesis loss is 650W & eddy Current loss is 350W. If
    applied voltage is vaised to 2000, f is 100Hz, find new core
    losses -
      At 1000V, f=50HZ W:=1000W Wh=650W, We=850W
301
      Hysteresis losses Wh= Kh*f= 650 = Kh* 50=> Kh=13
    => Now applied voltage is saised to 2000V, new frequency
    f=100Hz then core losses = ?
      W:= Wh+ We
                                            We = Ke * f2
                                            350 = Ke # 2500
          = Kh+f + Ke+f2
                                              Ke = 0-14
          = (13)*(100) + (0.14)(100)2
      W: = 2700 W.
```

7.
$$z^2 = \sqrt{(7.8)^2 + (7.8)^2}$$

7. $x = \sqrt{(7.8)^2 + (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{8} = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{8} = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{8} = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{8} = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{4^2 - 1.82^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{(7.8)^2} = \sqrt{(7.8)^2}}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{(7.8)^2} = \sqrt{(7.8)^2} = \sqrt{(7.8)^2}$

7. $x = \sqrt{(7.8)^2 - (7.8)^2} = \sqrt{(7.8)^2} = \sqrt{($

Fig a

Vi age F2

AB - Primary winding having N1 turns

Step down II & II

Step up

-> these cuirdings are not electrically separated, operation is similar to 2 winding transformer.

-> It is used colore the transformation ratio differs from unity (K+1)

So Copper losses are very less Compare to 2 winding transformer.

Neglecting OHH iron losses & no load current

$$\frac{V_2}{V_1} = \frac{N_2}{N_1} = \frac{I_1}{I_2} = K$$


-> Current in section BC is due to the difference b/w Current I2 A II

In I2 is greater than II. (II-II)


-> O/p is similar to 2 winding transformer.

Efficiency & Voitage acquibition is more

superior than 2 winding transformer.



Ic= II-I2 Step dollars up



sawing of corper



I weight of copper is proposional to the Product of Current & number of turns

Total weight of Copper in Auto transformer

d (NI-N2) II + N2CI2- II)

⇒ In 2 winding transformer at of an is at of Cu in primary of NIII ? Wo wt of Cu in endary of N2 I2 ? Wo

Total weight of Copper of NIII+NLIZ

wt of Cu in Auto thermer $= \frac{(N_1 - N_2) I_1 + N_2 (I_2 - I_1)}{N_1 I_1 + N_2 I_2}$ transformer $= \frac{I_1(N_1 - 2N_2) + N_2 I_2}{N_1 I_1 + N_2 I_2} = \frac{I_1 V_1 (I_1 - 2N_2) + N_2 I_2}{N_1 I_1 + N_2 I_2}$

$$= \frac{1}{N_1} \left(\frac{1 - 2N_2}{N_1} + \frac{N_2 I_2}{N_1 I_1} \right) = \frac{2N_2 + 1}{N_1 I_1} = \frac{2N_2$$

$$\begin{bmatrix} N_L = K, & \frac{T_1}{T_L} = K \\ N_1 & \frac{T_1}{T_L} = K \end{bmatrix} = 2k - \frac{2K}{2} = 1 - K$$

Now

cot of Copper in Auto transformer

= (1-K) + coeight of Copper in 2

winding transformer

Wa = Wo (1-K) Wa = coeight of cu in autotransform
Wo = coeight of cu in ordinary on 2
counding transformer

sowing = We-Wa = We-CI-K)Wo = KWo

sawing of cu in auto transformer

= K * (wt of cu in 2 winding t/former)

so power transfermed is inductively when i/p is CI-K) + i/p

from source to load. (K# 1/p power)

Problem

Auto transformed supplies load is 3KW at 115 voits at unity power factor. If applied Primary voitage is 230 V. Calculate power transferred to load. @ inductively cb) Conductively also Calculate sawing of Cer in auto-transformer (Wa). THE PHIHHHAM VANHAGET I'B FAMIN A 2ndary VANHAGET IN 1/4000 1, A 2ndary Current Ir is 100A.

301 Vg = 4000V, V = \$1600, 1/p put power = 3 x00

Power Transferred inductively

= 1/p (1-K) = 3000 (1-0-5) = 1.5 KW


K= \frac{115}{930} = 0.5 \rightarrow power transferred Conductively


= K * i/p power = 0.5 + 3000

= 1.5 KW

(b) II = K => II = 0.5 * 100 = 50 A Sawing of Cu = K + Wo = 0-5 Wo

12





2300 43.5 HV side rating is 13800 LV side rating is 11500 11500 11500 possible voltage dating 13800/11500 13800/11500 figo V1 = 2300 V2 = 13800 from figo i/p current at winding (A1-AL) = 8.7 > KVA rating = Primary Voltage * Primary Current = 13800 + 8.87 = 120 KVA O/P Current = $\frac{KVA \text{ moving}}{V_2} = \frac{120 \times 1000}{2300} = 52 \cdot 2 \text{ Amp}$ => current 19 winding (B1-B2) = 13800 =VI Difference b/10 0/p current CI2) 4 = 52.2-8.7= 43.5 A The Rated Current at winding BI-BI is 43.5A from fig 2 Va = 13800 , V1 =11500 Transfermation ratio = 18800 = 1.2 KVA rating = Polmary Voltage * Primary Current = 13800 × 43.5 = GOO KVA 0/p wrent (Iz) = KVA rating = 600 + 1000 = 52.2 Am Current in winding A1-A2 = I2-I1 = 522-43.5

Parallel operation of single phase transformers

A single t/former is enough to need the required load demand.

- The same amount of load can be meat by Connecting on another transfermen to ... present one Caro also meet the same land.

Another transfermer can be arranged in parallel with previous one then load can be shared by 2 transformers.

-> Adding one transformer in parallel with

existing involves a cost

But having some advantages transformy s operating in parallel.

Advantages, of using one on more tran-Stormens are

* 2 transfermers operating in parallel Increases the Rystem sigliability.


* If one fails to operate, other one supply power to load ine Continounity of supply is possible

+ Depending on power demand, transformers Can be southered on & switched off

Conditions satisfied for parallel operation of transformers

T/formers rosust have earl vostage mario's 1.e primaries of 2 T/formers are Connected to same source. Or voltage

endaries of 2 T/formers are must have eanal Voltage magnitudes * leakage impedance stould be inversely Proposiona



No load endories voltages of A 4 B 7/former is gluen our

Ea A Eb

-> if Ea-Eb=0 &1 Ea=Eb

There is no circulating Current exist.

-> if Ea + Eb &1 unequal -then Circulating Currents exists in Secondary

ic = Ea-Eb

ZA+ZB

Also if Ea & Eb are out of phase, magnitudes of endories also charges results large circulating Currents, increases of mic losses will reduces efficiency of Thermer It is recommended that

Ic circulating Currents must be less than

Ic 2 10% of rated Current Ic 4 Ea are some Ic 4 Eb are opposite

Ea + IaZA = Eb-IbZB

E + IAZA = E - IBZB

Use know that t/former secondary voltage

V= E-IAZA = E-IBZB

JAZA - JBZB

 $I_A = I_B \frac{Z_B}{Z_A}$, $I_B = I_A \frac{Z_A}{Z_B}$ This for on no local operation

transformers

V2 = EA - IAZA = EB - IBZB = IZL

EA = V2+ IAZA , EB = V2+ IBZB , V2 = IZL

EA = IAZA + (IA+IB) ZL -> @

) "_____

EB= IBZB+ (IA+IB) ZL -> 6

V2= (JA+JB)ZL

EA-EB = IAZA-IBZB -> C

 $I_A = (E_A - E_B) + I_B Z_B \rightarrow \emptyset$

substitue equation (1) in equation (6)

 $E_B = I_B Z_B + \left[\left(E_A - E_B \right) + I_B Z_B \right] + I_B Z_B$

EBZA TOTAL

$$E_{B}: I_{B} \neq_{G} \neq_{A} + \left\{ (E_{A} - E_{B}) + I_{G} \neq_{B} + I_{G} \neq_{A} \right\} \neq_{L}$$

$$E_{B} \neq_{A} = I_{G} \neq_{A} =$$

$$E_{BZA} := I_{GZ_{GY}Z_{A}} + (E_{A}-E_{B})Z_{L} + I_{GZ_{B}Z_{L}} + I_{BZ_{A}Z_{L}}$$

$$= I_{GZ_{GY}Z_{A}} + (E_{A}-E_{B})Z_{L} + I_{GZ_{L}}(Z_{A}+Z_{B})$$

$$= I_{GZ_{A}} + I_{GZ_{A}Z_{B}} + I_{GZ_{A}Z_{B}}(Z_{A}+Z_{B}) + (E_{A}-E_{B})Z_{L}$$

$$= E_{BZ_{A}} - (E_{A}-E_{A})Z_{A}$$


$$E_{B}Z_{A} - (E_{A} - E_{B})Z_{L} = I_{B}(Z_{A} + Z_{B} + Z_{L}(Z_{A} + Z_{B}))$$

$$I_{B} = E_{B}Z_{A}$$

$$J_{B} = \frac{E_{B}Z_{A} - (E_{A} - E_{B})Z_{L}}{Z_{A}Z_{B} + Z_{L}(Z_{A} + Z_{B})}$$
in P

$$I_{A} = \frac{E_A Z_B + CE_A - E_B}{Z_A Z_B + Z_L (Z_A + Z_B)}$$

IP ZA & ZB are small



Compared to ZL

I = divide

$$I_B = \frac{E_B Z_A}{Z_L(Z_A + Z_B)} - \frac{(E_A - E_B)}{(Z_A + Z_B)}$$

I = IA + IB

is given as

under load Conditions, circulating Currents

$$\frac{I_{c} = \frac{E_{A} - E_{B}}{Z_{A} + Z_{B} + \frac{Z_{A} Z_{B}}{Z_{L}}} = \frac{Z_{L} \left(E_{A} - E_{B} \right)}{Z_{L} \left(Z_{A} + Z_{B} \right) + Z_{A} Z_{B}}$$

from gives eausion

Total Current

Substitute IB in eauto

$$E_A - E_B = I_A Z_A - (I - I_A) Z_B$$

$$E_A - E_B = I_A Z_A + I_A Z_B - I Z_B$$

$$= I_A (Z_A + Z_B) - I Z_B$$

$$E_A - E_B = (I - I_B) Z_A - I_B Z_B$$

 $E_A - E_B = I * Z_A + I_B Z_A - I_B Z_B$
 $E_A - E_B = I * Z_A + I_B (Z_A + Z_B)$

$$I_B(Z_A+Z_B) = I*Z_A - (E_A-E_B)$$

$$I_B = I*Z_A - (E_A-E_B)$$

$$Z_A+Z_B$$

The value of
$$V_2$$
 may also found as
$$V_2 = E_A - I_A Z_A$$

$$I_A \mathcal{Z}_A = E_A - V_2$$

$$I_{B} = \frac{(E_{B} - V_{2})}{Z_{B}} = CE_{B} - V_{2}Y_{B}$$

$$| I = \frac{V_L}{Z_L} = V_2 Y_L |$$

if load is given in KVA then V2 is

$$S = V_2 I \Rightarrow \boxed{I = \frac{S}{V_2}}$$

V2= EAZB + EBZA - IZAZB

ZA+ZB


V2= EAZB+ EBZA - SZAZB V2 ZA+ZB

 $V_2 = V_2 \left(\frac{Z_B E_A + E_B Z_A}{V_2 \left(Z_A + Z_B \right)} - S Z_A Z_B \right)$

V2 (ZA+ZB)= V2 (ZBEA+EBZA) -SZAZB

If IA & Io Krower from V2

VL = EA - IAZA & VE = EB - IBZA



KVA & A = 500, KVA & B = 250 KVA Problem

Two transformers (B) 4 (B) operating in parally Supply a common land 750 KVA at 0.8 P.4 log. Their open circuit voltages are 405 4 415 v. T/former (A) has sexistance 1%. A reactance 5%. T/former B has resistance 1-5% A seactince 4% Find @ cross current in secondaries on no load (b) load shared by each T/former

Sol T/former (A) EA = 405 T/former (B) EB = 415

RA = 1%, XA = 5% KVA = 500 RB = 1.5%, XB = 4%. load Current in KVA = 750

KUA = 250 KVA

let V2 be assured T/FA

IARA = 1% & V2 $R_A = \frac{1}{100} * \frac{V_2}{I_A}$ $I_A = \frac{1000}{V_0} * \frac{V_2}{V_0}$

 $I_A = \frac{7/4}{V_2} \times V_A = \frac{500 *1000}{400} = 1250A$

 $R_A = \frac{1}{100} * \frac{40.0}{1250} = 0.0032 R_A = \frac{1}{100} * \frac{V_2}{1000}$

 $7A = \frac{5}{100} * \frac{V_L}{I_A}$

IAXA = 5% & V2

 $X_A = \frac{5}{100} + \frac{V_L}{I_A} = 0.016 \Sigma$

$$I_B = \frac{\text{Raving of T/fB}}{V_2} = \frac{250 \times 1000}{400} : 625 \text{ A}$$

$$\begin{bmatrix} R_B = \frac{1.5}{100} * \frac{V_2}{F_B} \end{bmatrix} = \frac{1.5}{100} * \frac{400}{625} = 0.0096$$

$$\frac{1}{100} = \frac{4}{100} \times \frac{V_2}{I_8} = 0.0256$$

$$Z_{A} = 0.0032 + 0.0016$$
, $Z_{B} = 0.0096 + 0.00256$
= $0.063 / 78.5^{\circ}$ = $0.0275 / 69.4$
 $Z_{A} + Z_{B} = 0.0436 / 72.9^{\circ}$

Let ZL be the land impedance, with terminal V_2

$$\frac{\sqrt{2}^2}{ZL} = \frac{1000}{100} = \frac{10^3}{750} = \frac{10^3}{36.86}$$

$$V_2^2 = Z_L \Rightarrow Z_L = (400^2)$$
 $1000 L = 750 + 10^3 [-36.86]$

$$I = \frac{E_{A} - E_{B}}{Z_{A} + Z_{B}} = \frac{(405 - 415)}{-0.0436} = -229.3 [-72.9]$$

```
(b) lond current shared by each biformer
           ENZB+ CEN-EB) ZL
    In =
           ZNZB+ZL(ZN+ZB)
         9701-350
   IB = EBZB - CEA-EB)ZL = 875 | 42.6
           ZAZB+ ZLCZA+ZB)
    , load stored by each therener
       SA = V2 * IA = 400 * 970 [-35" = 388 [-35" KVA
        Cosph = cos(-35) = 0.81
       SB = V27 IB = 400 + 875 426 = 350 426 KVA
           Cosp = Cos (426) = 0.736
            2 THormers have following
Rated Current.
                               (B)
               200 A
Per unit Resistance 0.02
                               600 A
" " Reactance 0.05
                              0.025
No load emp 245v
                              0.06
                              2400
  Calculate terminal voltage & supply load
impedance (0.025+20.1)
900
      given impedance in per unit is convered
into se
   ZA = Zru + emf(A)
                          => ZA = c0'02+0.025i) * 245
               Rated current
                           Zn = 0.066/68/2
                               = 0.025.+0.061281
```

```
Zocpu) * EmfcB)
                Rated current of T/F(B)
     = (0.025+00.06) + 248 = 0.026 67.3
  Also ZL= (0.25+00.1) = 0.269 [21.8]=
    ZA+ZB = 0.066 68.2 + 0.026 67.3
         2 0.0919 [67.94
 endary terminal voltage
        V2= IZL
     I = EAZB+EBZA = 855 |-24.8
          ZAZB + ZL LZA+ZB.)
   V2= 855 |-24.8 x 0.269 [21.8
      = 229.99 | -3
  load of (2+31.5) = 2.5 36.86
     ZA = 0.15+ 30.5
     Zo = 0.1+00.6
     EA = 207 L00
      EB = 205 10°
  find power o/p A p.f of each T/former
801
      IA = EAZB + (EA - 68) ZL
            ZAZB + ZL (ZA+ ZB)
      TA = 42.26 |-38.9 = 32.89 - 326.55
```



Noco

$$V_2 = I ZL$$

= $(IA+ I_B) ZL$ $\begin{cases} V_2 = IZL \\ V_2 = IZL \end{cases}$
= $(42.26+33.56)$

$$\phi_{n} = -3.9 - (-38.9) = 35$$

CHAPTER

- Three-phase Transformers
- Star/Star or Y/Y Connection
- Delta-Delta or Connection
- ➤ Wye/Delta or Y/ Connection
- Delta/Wye or /Y Connection
- Open-Delta or V-V Connection
- Power Supplied by V-V Bank
- > Scott Connection or T-T Connection
- Three-phase to Two-Phase Conversion and vice-versa
- > Parallel Operation of 3phase Transformers
- Instrument Transformers
- Current Transformers
- Potential Transformers


Learning Objectives TRANSFORMER: Three-phase Transformer THREE PHASE



Three phase transformers are used throughout industry to change values of three phase voltage and current. Three phase power is the most common way in which power is produced.

33.1. Three-Phase Transformer

Large scale generation of electric power is usually 3-phase at generated voltages of 13.2 kV or somewhat higher. Transmission is generally accomplished at higher voltages of 110, 132, 275, 400 and 750 kV for which purpose 3-phase transformers are necessary to step up the generated voltage to that of the transmission line. Next, at load centres, the transmission voltages are reduced to distribution voltages of 6,600, 4,600 and 2,300 volts. Further, at most of the consumers, the distribution voltages are still reduced to utilization voltages of 440, 220 or 110 volts. Years ago, it was a common






Fig. 33.1

contact with each other. The centre leg, formed by these three, carries the flux produced by the three-phase currents I_R , I_Y and I_B . As at any instant $I_R + I_Y + I_B = 0$, hence the sum of three fluxes is also zero. Therefore, it will make no difference if the common leg is removed. In that case any two legs will act as the return for the third just as in a 3-phase system any two conductors act as the return for the current



Like single-phase transformers, the three-phase transformers are also of the core type or shell type. The basic principle of a 3-phase transformer is illustrated in Fig. 33.1 in which only primary windings have been shown interconnected in star and put across 3-phase supply. The three cores are 120° apart and their empty legs are shown in






Fig. 33.2 (a)

in the third conductor. This improved design is shown in Fig. 33.2 (a) where dotted rectangles indicate the three windings and numbers in the cores and yokes represent the directions and magnitudes of fluxes at a particular instant. It will be seen that at any instant, the amount of 'up' flux in any leg is equal to the sum of 'down' fluxes in the other two legs. The core type transformers are usually wound with circular cylindrical coils.

In a similar way, three single-phase shell type transformers can be combined together to form a 3-phase shell type unit as shown in Fig. 33.2(b). But some saving in iron can be achieved in





constructing a single 3-phase transformer as shown in Fig. 33.3. It does not differ from three single-phase transformers put side by side. Saving in iron is due to the joint use of the magnetic paths between the coils. The three phases, in this case, are more independent than they are in the core type transformers, because each phase has a magnetic circuit independent of the other.

One main drawback in a 3-phase transformer is that if any one phase becomes disabled, then the whole transformer has to be ordinarily removed from service for repairs (the shell type may be operated open

1214 Electrical Technology

 Δ or Vee but this is not always feasible). However, in the case of a 3-phase bank of single-phase transformers, if one transformer goes out of order, the system can still be run open- Δ at reduced capacity or the faulty transformer can be readily replaced by a single spare.

33.2. Three-phase Transformer Connections

There are various methods available for transforming 3-phase voltages to higher or lower 3-phase voltages *i.e.* for handling a considerable amount of power. The most common connections are (i) Y - Y (ii) $\Delta - \Delta$ (iii) $Y - \Delta$ (iv) $\Delta - Y$ (v) open-delta or V - V (vi) Scott connection or T - T connection.

33.3. Star/Star or Y/Y Connection

This connection is most economical for small, high-voltage transformers because the number of turns/phase and the amount of insulation required is minimum (as phase voltage is only $1/\sqrt{3}$ of line voltage). In Fig. 33.4 a bank of 3 transformers connected in Y on both the primary and the secondary sides is shown. The ratio of line voltages on the primary and secondary sides is the same as the transformation ratio of each transformer. However, there is a phase shift of 30° between the phase voltages and line voltages both on the primary and secondary

sides. Of course, line voltages on both

With these phase angles, the center points of the Y must tie either all "-" or all "+" winding ends together.

With these phase angles, the winding ends together.

With these phase angles, the winding polarities must stack together in a complementary manner (+ to -).

sides as well as primary voltages are respectively in phase with each other. This connection works




Fig. 33.4

satisfactorily only if the load is balanced. With the unbalanced load to the neutral, the neutral point shifts thereby making the three line-to-neutral (i.e. phase) voltages unequal. The effect of unbalanced loads can be illustrated by placing a single load between phase (or coil) a and the neutral on the secondary side. The power to the load has to be supplied by primary phase (or coil) A. This primary coil A cannot supply the required power because it is in series with primaries B and C whose secondaries are open. Under these conditions, the primary coils B and C act as very high impedances so that primary coil A can obtain but very little current through them from the line. Hence, secondary coil a cannot supply any appreciable power. In fact, a very low resistance approaching a short-circuit may be connected between point a and the neutral and only a very small amount of current will flow. This, as said above, is due to the reduction of voltage E_{an} because of neutral shift. In other words, under short-circuit conditions, the neutral is pulled too much towards coil a. This reduces E_{an} but increases E_{bn} and E_{cn} (however line voltage E_{AB} , E_{BC} and E_{CA} are unaffected). On the primary side, E_{AN} will be practically reduced to zero whereas E_{BN} and E_{CN} will rise to nearly full primary line voltage. This difficulty of shifting (or floating) neutral can be obviated by connecting the primary neutral (shown dotted in the figure) back to the generator so that primary coil A can take its required power from between its line and the neutral. It should be noted that if a single phase load is connected between the lines a and b, there will be a similar but less pronounced neutral shift which results in an overvoltage on one or more transformers.

Another advantage of stabilizing the primary neutral by connecting it to neutral of the generator is that it eliminates distortion in the secondary phase voltages. This is explained as follows. For delivering a sine wave of voltage, it is necessary to have a sine wave of flux in the core, but on account of the characteristics of iron, a sine wave of flux requires a third harmonic component in the exciting current. As the frequency of this component is thrice the frequency of the circuit, at any given instant, it tends to flow either towards or away from the neutral point in all the three transformers. If the primary neutral is isolated, the triple frequency current cannot flow. Hence, the flux in the core cannot be a sine wave and so the voltages are distorted. But if the primary neutral is earthed *i.e.* joined to the generator neutral, then this provides a path for the triple-frequency currents and e.m.fs. and the difficulty is overcome. Another way of avoiding this trouble of oscillating neutral is to provide each of the transformers with a third or tertiary winding of relatively low kVA rating. This tertiary winding is connected in Δ and provides a circuit in which the triple-frequency component of the magnetising current can flow (with an isolated neutral, it could not). In that case, a sine wave of voltage applied to the primary will result in a sine wave of phase voltage in the secondary. As said above, the advantage of this connection is that insulation is stressed only to the extent of line to neutral voltage *i.e.* 58% of the line voltage.

33.4. Delta-Delta or $\Delta - \Delta$ Connection

This connection is economical for large, low-voltage transformers in which insulation problem is not so urgent, because it increases the number of turns/phase. The transformer connections and voltage triangles are shown in Fig. 33.5. The ratio of transformation between primary and secondary line voltage is exactly the same as that of each transformer. Further, the secondary voltage triangle abc occupies the same relative position as the primary voltage triangle ABC i.e. there is no angular displacement between the two. Moreover, there is no internal phase shift between phase and line voltages on either side as was the case in Y-Y connection. This connection has the following advantages:

- 1. As explained above, in order that the output voltage be sinusoidal, it is necessary that the magnetising current of the transformer must contain a third harmonic component. In this case, the third harmonic component of the magnetising current can flow in the Δ -connected transformer primaries without flowing in the line wires. The three phases are 120° apart which is $3 \times 120 = 360^\circ$ with respect to the third harmonic, hence it merely circulates in the Δ . Therefore, the flux is sinusoidal which results in sinusoidal voltages.
- 2. No difficulty is experienced from unbalanced loading as was the case in Y Y connection. The three-phase voltages remain practically constant regardless of load imbalance.
- 3. An added advantage of this connection is that if one transformer becomes disabled, the system can continue to operate in open-delta or in V V although with reduced available capacity. The reduced capacity is 58% and not 66.7% of the normal value, as explained in Art. 33.7.

1216 Electrical Technology




Fig. 33.5 Fig. 33.6 Fig. 33.7

33.5. Wye/Delta or Y/Δ Connection

The main use of this connection is at the substation end of the transmission line where the voltage is to be stepped down. The primary winding is Y-connected with grounded neutral as shown in Fig. 33.6. The ratio between the secondary and primary line voltage is $1/\sqrt{3}$ times the transformation ratio of each transformer. There is a 30° shift between the primary and secondary line voltages which means that a $Y - \Delta$ transformer bank cannot be paralleled with either a Y - Y or a $\Delta - \Delta$ bank. Also, third harmonic currents flows in the Δ to provide a sinusoidal flux.

33.6. Delta/Wye or Δ/Y Connection

This connection is generally employed where it is necessary to step up the voltage as for example, at the beginning of high tension transmission system. The connection is shown in Fig. 33.7. The neutral of the secondary is grounded for providing 3-phase 4-wire service. In recent years, this connection has gained considerable popularity because it can be used to serve both the 3-phase power equipment and single-phase lighting circuits.

This connection is not open to the objection of a floating neutral and voltage distortion because the existence of a Δ -connection allows a path for the third-harmonic currents. It would be observed that the primary and secondary line voltages and line currents are out of phase with each other by 30°. Because of this 30° shift, it is impossible to parallel such a bank with a $\Delta - \Delta$ or Y - Y bank of transformers even though the voltage ratios are correctly adjusted. The ratio of secondary to primary voltage is $\sqrt{3}$ times the transformation ratio of each transformer.

Example 33.1. A 3-phase, 50-Hz transformer has a delta-connected primary and star-connected secondary, the line voltages being 22,000 V and 400 V respectively. The secondary has a star-connected balanced load at 0.8 power factor lagging. The line current on the primary side is 5 A. Determine the current in each coil of the primary and in each secondary line. What is the output of the transformer in kW?

Solution. It should be noted that in three-phase transformers, the *phase* transformation ratio is equal to the turn ratio but the terminal or line voltages depend upon the method of connection employed. The Δ / Y connection is shown in Fig. 33.8.




Fig. 33.8

= 22,000 VPhase voltage on primary side $= 400/\sqrt{3}$ Phase voltage on secondary side

 $K = 400/22,000 \times \sqrt{3} = 1/55\sqrt{3}$ ٠.

 $= 5/\sqrt{3} A$ Primary phase current

 $=\frac{5}{\sqrt{3}} \div \frac{1}{55\sqrt{3}} = 275 \text{ A}$ Secondary phase current

Secondary line current

:. Output =
$$\sqrt{3}V_{I}I_{I}\cos\phi = \sqrt{3} \times 400 \times 275 \times 0.8 = 15.24 \text{ kW}.$$

Example 33.2. A 500-kVA, 3-phase, 50-Hz transformer has a voltage ratio (line voltages) of 33/11-kV and is delta/star connected. The resistances per phase are: high voltage 35 Ω , low voltage $0.876~\Omega$ and the iron loss is 3050~W. Calculate the value of efficiency at full-load and one-half of full-(Electrical Machinery, Madras Univ. 1985) load respectively (a) at unity p.f. and (b) 0.8 p.f.

Solution. Transformation ratio
$$K = \frac{11,000}{\sqrt{3} \times 33,000} = \frac{1}{3\sqrt{3}}$$

Per phase

 $R_{02} = 0.876 + (1/3\sqrt{3})^2 \times 35 = 2.172 \Omega$ = $\frac{500,000}{\sqrt{3} \times 11,000} = \frac{500}{11\sqrt{3}} A$ Secondary phase current

Full-load condition

Full load total Cu loss = $3 \times (500/11\sqrt{3})^2 \times 2.172 = 4,490 \text{ W}$; Iron loss = 3,050 W

Total full-load losses

= 4,490 + 3,050 = 7,540 W; Output at unity p.f. = 500 kW

 \therefore F.L. efficiency = 500,000/507,540

= 0.9854 or 98.54%; Output at 0.8 p.f. = 400 kW

 \therefore Efficiency = 400,000/407.540

= 0.982 or 98.2%

Half-load condition

Output at unity p.f.= 250 kW

Cu losses = $(1/2)^2 \times 4,490$

= 1.222 W

Total losses

$$= 3,050 + 1,122 = 4,172 \text{ W}$$



Three-phase transformer

Example 33.3. A 3-phase, 6,600/415-V, 2,000-kVA transformer has a per unit resistance of 0.02 and a per unit leakage reactance of 0.1. Calculate the Cu loss and regulation at full-load 0.8 p.f. lag. (Electrical Machines-I, Bombay Univ. 1987)

Solution. As seen from Art. 27 – 16, %
$$R = \%$$
 Cu loss = $\frac{\text{Cu loss}}{VA} \times 100$

Now, %
$$R = 0.02 \times 100 = 2 \%$$
 \therefore $2 = \frac{\text{Cu loss}}{2,000} \times 100$ \therefore Cu loss = 40 kW

Now, percentage leakage reactance = $0.1 \times 100 = 10\%$

Regn. =
$$v_r \cos \phi + v_r \sin \phi = 2 \times 0.8 + 10 \times 0.6 = 7.6\%$$

Example 33.4. A 120-kVA, 6,000/400-V, Y/Y 3-ph, 50-Hz transformer has an iron loss of 1,600 W. The maximum efficiency occurs at 3/4 full load.

Find the efficiencies of the transformer at

(i) full-load and 0.8 power factor

(ii) half-load and unity power factor

(iii) the maximum efficiency.

(Elect. Technology Utkal Univ. 1987)

Solution. Since maximum efficiency occurs at 3/4 full-load, Cu loss at 3/4 full-load equals iron loss of 1,600 W.

Cu loss at 3/4 F.L. = 1,600 W; Cu loss at F.L. = $1,600 \times (4/3)^2 = 2,845$ W

(i) F.L. output at 0.8 p.f. $= 120 \times 0.8 = 96 \text{ kW} = 96,000 \text{ W}$

Total loss = 1,600 + 2,845 = 4,445 W

$$\eta = \frac{96,000}{100,445} \times 100 = 95.57 \%$$

(ii) Cu loss at 1/2 full-load = $(1/2)^2 \times 2.845 = 710 \text{ W}$

Total loss =
$$710 + 1,600 = 2310 \text{ W}$$

Output at 1/2 F.L. and u.p.f. is= $60 \text{ kW} = 60,000 \text{ W}; \eta = \frac{60,000}{62,310} \times 100 = 96.57\%$

(iii) Maximum efficiency occurs at 3/4 full-load when iron loss equals Cu loss.

Total loss = $2 \times 1,600 = 3,200 \text{ W}$

Output at u.p.f. $= (3/4) \times 120 = 90 \text{ kW} = 90,000 \text{ W}$

Input =
$$90,000 + 3,200 = 93,200 \text{ W}$$
 : $\eta = \frac{90,000}{93,200} \times 100 = 96.57\%$

Example 33.5. A 3-phase transformer, ratio 33/6.6-kV, Δ /Y, 2-MVA has a primary resistance of 8 Ω per phase and a secondary resistance of 0.08 ohm per phase. The percentage impedance is 7%. Calculate the secondary voltage with rated primary voltage and hence the regulation for full-load 0.75 p.f. lagging conditions. (Elect. Machine-I, Nagpur, Univ. 1993)

Solution. F.L. secondary current =
$$\frac{2 \times 10^6}{\sqrt{3} \times 6.6 \times 10^3} = 175 \text{ A}$$

$$K = 6.6 / \sqrt{3} \times 33 = 1/8.65$$
; $R_{02} = 0.08 + 8/8.65^2 = 0.1867 \Omega$ per phase

Now, secondary impedance drop per phase =
$$\frac{7}{100} \times \frac{6,600}{\sqrt{3}} = 266.7 \text{ V}$$

$$Z_{02} = 266.7/175 = 1.523 \Omega$$
 per phase

$$X_{02} = \sqrt{Z_{02}^2 - R_{02}^2} = \sqrt{1.523^2 - 0.1867^2} = 1.51 \,\Omega/\,\text{phase}$$

Drop per phase = $I_2 (R_{02} \cos \phi + X_{02} \sin \phi) = 175 (0.1867 \times 0.75 + 1.51 \times 0.66) = 200 \text{ V}$

Secondary voltage/phase =
$$6,600/\sqrt{3} = 3,810 \text{ V}$$
 : $V_2 = 3,810 - 200 = 3,610 \text{ V}$

 \therefore Secondary line voltage = 3,610 $\times \sqrt{3}$ = 6,250 V

% regn. $= 200 \times 100/3,810 = 5.23 \%$

Example 33.6. A 100-kVA, 3-phase, 50-Hz 3,300/400 V transformer is Δ -connected on the h.v. side and Y-connected on the l.v. side. The resistance of the h.v. winding is 3.5 Ω per phase and that of the l.v. winding 0.02 Ω per phase. Calculate the iron losses of the transformer at normal voltage and frequency if its full-load efficiency be 95.8% at 0.8 p.f. (lag).

(A.C. Machines-I, Jadavpur Univ. 1989)

Solution. F.L. output = $100 \times 0.8 = 80 \text{ kW}$; Input = 80/0.958 = 83.5 kW

Total loss = Input – Output = 83.5 - 80 = 3.5 kW

Let us find full-load Cu losses for which purpose, we would first calculate R_{02} .

$$K = \frac{\text{secondary voltage/phase}}{\text{primary voltage/phase}} = \frac{400/\sqrt{3}}{3,300} = \frac{4}{33\sqrt{3}}$$

$$R_{02} = R_2 + K^2 R_1 = 0.02 + (4/\sqrt{3} \times 33)^2 \times 3.5 = 0.037 \Omega$$

Full-load secondary phase current is $I_2 = 100,000/\sqrt{3} \times 400 = 144.1 \text{ A}$

Total Cu loss = $3I_2^2 R_{02} = 3 \times 144.1^2 \times 0.037 = 2,305 \text{ W}$

Iron loss = Total loss – F.L. Cu loss = 3,500 - 2,305 = 1,195 W

Example 33.7. A 5,000-kVA, 3-phase transformer, 6.6/33-kV, Δ/Y , has a no-load loss of 15 kW and a full-load loss of 50 kW. The impedance drop at full-load is 7%. Calculate the primary voltage when a load of 3,200 kW at 0.8 p.f. is delivered at 33 kV.

Solution. Full-load $I_2 = 5 \times 10^6 / \sqrt{3} \times 33,000 = 87.5 \text{ A}$

Impedance drop/phase = $7\% \text{ of } (33/\sqrt{3}) = 7\% \text{ of } 19 \text{ kV} = 1,330 \text{ V}$

:.
$$Z_{02} = 1,330/87.5 = 15.3 \Omega/\text{phase}$$
; F.L. Cu loss = $50 - 15 = 35 \text{ kW}$

:.
$$3 I_2 R_{02} = 35,000; R_{02} = 35,000/3 \times 8.75^2 = 1.53 \Omega/\text{phase}$$

$$X_{02} = \sqrt{15.3^2 - 1.53^2} = 15.23 \Omega$$

When load is 3,200 kW at 0.8 p.f.

 $I_2 = 3,200 / \sqrt{3} \times 33 \times 0.8 = 70 \text{ A}; \text{drop} = 70 (1.53 \times 0.8 + 15.23 \times 0.6) = 725 \text{ V/phase}$

$$\therefore$$
 % regn. = $\frac{725 \times 100}{19,000} = 3.8 \%$

Primary voltage will have to be increased by 3.8%.

:. Primary voltage = 6.6 + 3.8% of 6.6 = 6.85 kV = 6.85 V

Example 33.8. A 3-phase transformer has its primary connected in Δ and its secondary in Y. It has an equivalent resistance of 1% and an equivalent reactance of 6%. The primary applied voltage is 6,600 V. What must be the ratio of transformation in order that it will deliver 4,800 V at full-load current and 0.8 power factor (lag)? (Elect. Technology-II, Magadh Univ. 1991)

Solution. Percentage regulation

$$= v_r \cos \phi + v_x \sin \phi$$

$$= 1 \times 0.8 + 6 \times 0.6 = 4.4\%$$

Induced secondary e.m.f. (line value)

=4.800 + 4.4% of 4.800 = 5.010 V, as in Fig. 33.9.

Secondary phase voltage

$$= 5.010 / \sqrt{3} = 2.890 \text{ V}$$

Transformation ratio

K = 2,890/6,600 = 0.437.




Fig. 33.9

Example 33.9. A 2000-kVA, 6,600/400-V, 3-phase transformer is delta-connected on the high voltage side and star-connected on the low-voltage side. Determine its % resistance and % reactance drops, % efficiency and % regulation on full load 0.8 p.f. leading given the following data:

O.C. test; L.V. data: 400 V, 150 A and 15 kW

(Basic Elect., Machines Nagpur Univ. 1993)

Solution. From S.C. test data, we have

Primary voltage/phase = 400 V; Primary current/phase = $175/\sqrt{3} = 100 \text{ A}$

$$Z_{01} = \frac{400}{101} = 3.96 \Omega$$

$$I_1^2 R_{01} = \frac{17000}{3} \text{ or } R_{01} = 0.555 \Omega; X_{01} = \sqrt{3.96^2 - 0.555^2} = 3.92 \Omega$$

$$\% R = \frac{I_1 R_{01}}{V_1} \times 100 = \frac{101 \times 0.555}{6,600} \times 100 = 0.849$$

$$\% X = \frac{I_1 X_{01}}{V_1} \times 100 = \frac{101 \times 3.92}{6,600} \times 100 = 6$$

% regn = $v_r \cos \phi - v_r \sin \phi = 0.49 \times 0.8 - 6 \times 0.6 = -2.92\%$

Full-load primary line current can be found from

$$\sqrt{3} \times 6,600 \times I_1 = 2000 \times 1,000; I_1 = 175 \text{ A}$$

It shows that S.C. test has been carried out under full-load conditions.

Total losses = 17 + 15 = 32 kW; F.L. output = $2,000 \times 0.8 = 1600 \text{ kW}$

$$\eta = 1,600/1,632 = 0.98 \text{ or } 98\%$$

Example 33.10. A 3-ph, delta/star connected 11,000/440 V, 50 Hz transformer takes a line current of 5 amp, when secondary Load of 0.8 Lagging p.f. is connected. Determine each coilcurrent and output of transformer. (Amravati Univ. 1999)

Solution. Due to delta/star connections the voltage ratings of the two sides on per phase basis are:

Primary coil rating = 11,000 V, Secondary coil rating =
$$\frac{440}{\sqrt{3}}$$
 = 254 volts

Primary coil-current =
$$5/\sqrt{3} = 2.887$$
 amp

Each coil is delivering equal volt. amps.

Since three phase volt – amps = $3 \times 11,000 \times 5/\sqrt{3}$

= 95266

Volts amps/phase = 31755

This corresponds to the secondary coil-current of I_2 , given by

$$I_2 = \frac{31755}{254} = 125$$
 amp. This is shown in Fig. 33.10.

Total Output of transformer, in kVA = 31,755

Since, the p.f. given is 0.8 lagging.

The total output power in kW = $31,755 \times 0.80 = 25.4$ kW




Fig. 33.10. Transformer coil currents

Example 33.11. A load of $1000 \, kVA$ at $0.866 \, p.f.$ lagging is supplied by two 3 phase transformers of $800 \, kVA$ capacity operating in parallel. Ratio of transformation is same: $6600/400 \, V$, delta/star. If the equivalent impedances referred to secondary are (0.005 + j.015) ohm and (0.012 + j.0030) ohm per phase respectively. Calculate load and power factor of each transformer.

(Amravati Univ. 1999)

Solution. Total load = 1000 kVA

 $\cos \phi = 0.866 \, \text{Lag}, \phi = 30^{\circ} \, \text{lag}$

Total power output = 866 kW

Secondary current with star connection,

$$I_2 = \frac{1000}{\sqrt{3} \times 440} \times 1000 = 1312.2 \text{ amp}$$

If the two transformers are identified as A and B, with their parameters with subscripts of a and b, we have:

$$\dot{\mathbf{Z}}_{a} = 0.005 + j \, 0.015 = 0.0158 \, \angle \, 71.56^{\circ} \, \text{ohm}$$

$$\dot{\mathbf{Z}}_{b} = 0.012 + j \, 0.030 = 0.0323 \, \angle \, 68.2^{\circ} \, \text{ohm}$$

$$\dot{\mathbf{Z}}_{a} + \dot{\mathbf{Z}}_{b} = 0.017 + j \, 0.045 = 0.0481 \, \angle \, 69.3^{\circ} \, \text{ohm}$$

$$\dot{\mathbf{I}}_{2a} = \text{secondary current of transformer } A$$

$$\dot{\mathbf{I}}_{2b} = \text{secondary current of transformer } B$$

$$\dot{\mathbf{I}}_{2a} = \frac{\dot{\mathbf{Z}}_{b}}{\dot{\mathbf{Z}}_{b} + \dot{\mathbf{Z}}_{a}} \times \dot{\mathbf{I}}_{2} = \frac{0.0323 \, \angle \, 68.2^{\circ}}{0.0481 \, \angle \, 69.3^{\circ}} \times 1312 \, \angle \, -30^{\circ}$$

$$= 88.1 \, \angle \, -31.1^{\circ}$$

$$\dot{\mathbf{I}}_{2b} = \frac{\dot{\mathbf{Z}}_{a}}{\dot{\mathbf{Z}}_{a} + \dot{\mathbf{Z}}_{b}} \times \dot{\mathbf{I}}_{2} = \frac{0.0158 \, \angle \, 71.56^{\circ}}{0.0481 \, \angle \, 69.3^{\circ}} \times 1312 \, \angle \, -30^{\circ}$$

$$= 43.1 \, \angle \, -27.74^{\circ}$$

For Transformer A

Load =
$$3 \times 254 \times 881 \times 10^{-3} = 671.3 \text{ kVA}$$

Power factor = $\cos 31.1^{\circ} \log = 0.856 \log$

For Transformer B

Load = $3 \times 254 \times 431 \times 10^{-3} = 328.4 \text{ kVA}$

Power factor = $\cos 23.74^{\circ} \log = 0.885 \log$

Check: Total kW gives a check. 1000 kVA at 0.866 lag means 866 kW.

Output, in kW, of transformer $A = 671.3 \times 0.856 =$ **574.6 kW**Output in kW of transformer $B = 328.4 \times 0.885 =$ **290.6 kW**Sum of these two outputs = 574.6 + 290.6 =**865.2 kW**

Note. Total kVAR also gives a check.

Depending on leading or lagging p.f., appropriate sign (+ ve or - ve) must be assigned to the kVAR-term.

Tutorial Problem No. 33.1

1. A 3-phase, star-connected alternator generates 6,360 V per phase and supplies 500 kW at a p.f. 0.9 lagging to a load through a step-down transformer of turns 40:1. The transformer is delta connected on the primary side and star-connected on the secondary side. Calculate the value of the line volts at the load. Calculate also the currents in (a) alternator windings (b) transformer primary windings (c) transformen secondary windings.

[476 V (a) 29.1 A (b) 16.8 A (c) 672 A]

2. A 11,000/6,600 V, 3-φ, transformer has a star-connected primary and a delta-connected secondary. It supplies a 6.6 kV motor having a star-connected stator, developing 969.8 kW at a power factor of 0.9 lagging and an efficiency of 92 per cent. Calculate (i) motor line and phase currents (ii) transformer secondary current and (iii) transformer primary current.

[(a) Motor; $I_L = I_{ph} = 126.3 \text{ A}$ (b) phase current 73 A (c) 75.8 A]

33.7. Open-Delta or V - V connection

If one of the transformers of a $\Delta - \Delta$ is removed and 3-phase supply is connected to the primaries as shown in Fig. 33.11, then three equal 3-phase voltages will be available at the secondary terminals on no-

load. This method of transforming 3-phase power by means of only two transformers is called the open $-\Delta$ or V-V connection.

It is employed:

- when the three-phase load is too small to warrant the installation of full three-phase transformer bank.
- when one of the transformers in a Δ Δ bank is disabled, so that service is continued although at reduced capacity, till the faulty transformer is repaired or a new one is substituted.
- when it is anticipated that in future the load will increase necessitating the closing of open delta.

One important point to note is that the total load that can be carried by a V - V bank is *not* two-third of the capacity of a $\Delta - \Delta$ bank but it is only 57.7% of it. That is a reduction of 15% (strictly, 15.5%) from its normal rating.




Fig. 33.11

Suppose there is $\Delta - \Delta$ bank of three 10-kVA transformers. When one transformer is removed, then it runs in V-V. The total rating of the two transformers is 20 kVA. But the capacity of the V-V bank is not the sum of the transformer kVA ratings but only 0.866 of it *i.e.* $20 \times 0.866 = 17.32$ (or $30 \times 0.57 = 17.3$ kVA). The fact that the ratio of V-capacity to Δ -capacity is $1/\sqrt{3} = 57.7\%$ (or nearly 58%) instead of $66\frac{2}{3}$ per cent can be proved as follows:

As seen from Fig. 33.12(a)

$$\Delta - \Delta$$
 capacity = $\sqrt{3} \cdot V_L \cdot I_L = \sqrt{3} \cdot V_L (\sqrt{3} \cdot I_S) = 3V_L I_S$

In Fig. 33.12 (b), it is obvious that when $\Delta - \Delta$ bank becomes V - V bank, the secondary line current I_L becomes equal to the secondary phase current I_S .

$$V-V \text{ capacity} = \sqrt{3} \cdot V_L I_L = \sqrt{3} V_L \cdot I_S$$

$$\frac{V-V \text{ capacity}}{\Delta-\Delta \text{ capacity}} = \frac{\sqrt{3} \cdot V_L I_S}{3 V_L I_S} = \frac{1}{\sqrt{3}} = 0.577 \text{ or } 58 \text{ per cent}$$

It means that the 3-phase load which can be carried without exceeding the ratings of the transformers is 57.7 per cent of the original load rather than the expected 66.7%.




Fig. 33.12

It is obvious from above that when one transformer is removed from a $\Delta - \Delta$ bank.

- 1. the bank capacity is reduced from 30 kVA to $30 \times 0.577 = 17.3 \text{ kVA}$ and not to 20 kVA as might be thought off-hand.
- 2. only 86.6% of the rated capacity of the two remaining transformers is available (i.e. 20×0.866 = 17.3 kVA). In other words, ratio of *operating* capacity to *available* capacity of an open-Δ is 0.866. This factor of 0.866 is sometimes called the *utility factor*.
- 3. each transformer will supply 57.7% of load and not 50% when operating in V V (Ex. 33.13).

However, it is worth noting that if three transformers in a $\Delta - \Delta$ bank are delivering their *rated load** and one transformer is removed, the overload on *each* of the two remaining transformers is 73.2% because

$$\frac{\text{total load in } V - V}{VA/\text{transformer}} = \frac{\sqrt{3} \cdot V_L I_S}{V_L I_S} = \sqrt{3} = 1.732$$

This over-load may be carried temporarily but some provision must be made to reduce the load if overheating and consequent breakdown of the remaining two transformers is to be avoided.

The disadvantages of this connection are:

- 1. The average power factor at which the V-bank operates is less than that of the load. This power factor is actually 86.6% of the balanced load power factor. Another significant point to note is that, except for a balanced unity power factor load, the two transformers in the V-V bank operate at different power factors (Art. 33.8).
- Secondary terminal voltages tend to become unbalanced to a great extent when the load is increased, this happens even when the load is perfectly balanced.

It may, however, be noted that if two transformers are operating in V-V and loaded to rated capacity (in the above example, to 17.3 kVA), the addition of a third transformer increases the total capacity by $\sqrt{3}$ or 173.2% (i.e. to 30 kVA). It means that for an increase in cost of 50% for the third transformer, the increase in capacity is 73.2% when converting from a V-V system to a $\Delta-\Delta$ system.

In Ex. 33.13, the three transformers are not supplying their rated load of $20 \times 3 = 60$ kVA but only 40 kVA.

33.8. Power Supplied by V - V Bank

When a V-V bank of two transformers supplies a balanced 3-phase load of power factor $\cos \phi$, then one transformer operates at a p.f. of $\cos (30^{\circ} - \phi)$ and the other at $\cos (30^{\circ} + \phi)$. Consequently, the two transformers will not have the same voltage regulation.

$$P_1 = kVA \cos (30^\circ - \phi) \text{ and } P_2 = kVA \cos (30^\circ + \phi)$$

(i) When $\phi = 0$ i.e. load p.f. = 1

Each transformer will have a p.f. = $\cos 30^{\circ} = 0.866$

(ii) When $\phi = 30^{\circ}$ i.e. load p.f. = 0.866.

In this case, one transformer has a p.f. of $\cos (30^{\circ} - 30^{\circ}) = 1$ and the other of $\cos (30^{\circ} + 30^{\circ}) = 0.866$.

(iii) When $\phi = 60^{\circ}$ i.e. load p.f. = 0.5

In this case, one transformer will have a p.f. = $\cos (30 - 60^\circ) = \cos (-30^\circ) = 0.866$ and the other of $\cos (30^\circ + 60^\circ) = 0$. It means that one of the transformers will not supply any load whereas the other having a p.f. = 0.866 will supply the entire load.

Example 33.12. What should be the kVA rating of each transformer in a V - V bank when the 3-phase balanced load is 40 kVA? If a third similar transformer is connected for operation, what is the rated capacity? What percentage increase in rating is affected in this way?

Solution. As pointed out earlier, the kVA rating of each transformer has to be 15% greater.

:. kVA/trasformer =
$$(40/2) \times 1.15 = 23$$

 $\Delta - \Delta$ bank rating = $23 \times 3 = 69$; Increase = $[(69 - 40)/40] \times 100 = 72.5\%$

Example 33.13. A $\Delta - \Delta$ bank consisting of three 20-kVA, 2300/230-V transformers supplies a load of 40 kVA. If one transformer is removed, find for the resulting V - V connection

- (i) kVA load carried by each transformer
- (ii) per cent of rated load carried by each transformer
- (iii) total kVA rating of the V-V bank
- (iv) ratio of the V-V bank to $\Delta \Delta$ bank transformer ratings.
- (v) per cent increase in load on each transformer when bank is converted into V-V bank.

Solution. (i) As explained earlier in Art. 33.7,
$$\frac{\text{total kVA load in } V - V \text{ bank}}{VA/\text{transformer}} = \sqrt{3}$$

:. kVA load supplied by each of the two transformers = $40/\sqrt{3}$ = 23.1 kVA

Obviously, each transformer in V - V bank does not carry 50% of the original load but 57.7%.

(ii) per cent of rated load =
$$\frac{\text{kVA load/transformer}}{\text{kVA rating/transformer}} = \frac{23.1}{20} = 115.5 \%$$

carried by each transformer.

Obviously, in this case, each transformer is overloaded to the extent of 15.5 per cent.*

(iii) kVA rating of the V - V bank = $(2 \times 20) \times 0.866 = 34.64$ kVA

(iv)
$$\frac{V - V \text{ rating}}{\Delta - \Delta \text{ rating}} = \frac{34.64}{60} = 0.577 \text{ or } 57.7\%$$

^{*} Overloading becomes 73.2% only when full rated load is supplied by the $\Delta - \Delta$ bank (i.e. $3 \times 20 = 60$ kVA in this case) before it becomes V - V bank.

As seen, the rating is reduced to 57.7% of the original rating.

- (v) Load supplied by each transformer in $\Delta \Delta bank = 40/3 = 13.33 \text{ kVA}$
- :. Percentage increase in load supplied by each transformer

$$= \frac{\text{kVA load/transformer in } V - V \text{ bank}}{\text{kVA load/transformer in } \Delta - \Delta \text{ bank}} = \frac{23.1}{13.3} = 1.732 = 173.2 \%$$

It is obvious that each transformer in the $\Delta - \Delta$ bank supplying 40 kVA was running underloaded (13.33 vs 20 kVA) but runs overloaded (23.1 vs 20 kVA) in V - V connection.

Example 33.14. A balanced 3-phase load of 150 kW at 1000 V, 0.866 lagging power factor is supplied from 2000 V, 3-phase mains through single-phase transformers (assumed to be ideal) connected in (i) delta-delta (ii) Vee-Vee. Find the current in the windings of each transformer and the power factor at which they operate in each case. Explain your calculations with circuit and vector diagrams.

Solution. (i) Delta-Delta Connection

$$\sqrt{3} V_L I_L \cos \phi = 150,000$$

$$\sqrt{3} \times 1000 \times I_L \times 0.866 = 150,000 :: I_L = 100 \text{ A}$$

 \therefore Secondary line current = 100 A; secondary phase current = $100/\sqrt{3}$ = 57.7 A

Transformation ratio = 1000/2000 = 1/2 \therefore Primary phase current = 57.7/2 = 28.85 A

(ii) Vee-Vee Connection

Let I be the secondary line current which is also the phase current in V-V connection. Then

$$\sqrt{3} \times 1000 \times I \times 0.866 = 150,000$$
 : $I = 100 \text{ A}$

:. Secondary phase current = 100 A; primary phase current = $100 \times 1/2 = 50 \text{ A}$

Transformer power factor = 86.6 per cent of 0.866 = 0.75 (lag).

Example 33.15. (a) Two identical 1-phase transformers are connected in open-delta across 3-phase mains and deliver a balanced load of 3000 kW at 11 kV and 0.8 p.f. lagging. Calculate the line and phase currents and the power factors at which the two transformers are working.

(b) If one more identical unit is added and the open delta is converted to closed delta, calculate the additional load of the same power factor that can now be supplied for the same temperature rise. Also calculate the phase and line currents. (Elect. Machinery-I, Madras Univ. 1987)

Solution. (a) If I is the line current, then

$$\sqrt{3} \times 11,000 \times I \times 0.8 = 3,000,000$$
 I = 197 A

Since, this also represents the phase current,

 \therefore Secondary phase current = 197 A; Transformer p.f. = 86.6 per cent of 0.8 = 0.693

(b) Additional load = 72.5 per cent of 3000 = 2175 kW

Total load = 3000 + 2175 = 5175 kW

Now,
$$\sqrt{3} \times V_L I_L \cos \phi = 5,175,000 \text{ or } \sqrt{3} \times 11,000 \times I_L \times 0.8 = 5,175,000$$

:.
$$I_L = 340 \text{ A}$$
; phase current = $340/\sqrt{3} = 196 \text{ A}$

Example 33.16. Two transformers connected in open delta supply a 400-kVA balanced load operating at 0.866 p.f. (lag). The load voltage is 440 V. What is the (a) kVA supplied by each transformer? (Elect. Machines-I, Gwalior Univ. 1991)

Solution. As stated in Art 33.7, the ratio of operating capacity to available capacity in an open- Δ is 0.866. Hence, kVA of each transformer is one-half of the total kVA load divided by 0.866.

(a) kVA of each transformer =
$$\frac{(400/2)}{0.866}$$
 = 231 kVA

(b) As stated in Art 33.8, the two transformers have power factors of $\cos (30^{\circ} - \phi)$ and $\cos (30^{\circ} + \phi)$.

∴
$$P_1 = \text{kVA} \cos(30^\circ - \phi) \text{ and } P_2 = \text{kVA} \cos(30 + \phi)$$

Now, load p.f. $= \cos \phi = 0.866$; $\phi = \cos^{-1}(0.866) = 30^\circ$
∴ $P_1 = 231 \times \cos 0^\circ = 231 \text{ kW}$; $P_2 = 231 \times \cos 60^\circ = 115.5 \text{ kW}$
Obviously, $P_1 + P_2$ must equal $400 \times 0.86 = 346.5 \text{ kW}$

Tutorial Problem No. 33.2

- Three 1100/110-V transformers connected delta-delta supply a lighting load of 100 kW. One of the transformers is damaged and removed for repairs. Find
 - (a) What currents were flowing in each transformer when the three transformers were in service?
 - (b) What current flows in each transformer when the third is removed? and
 - (c) The output kVA of each transformer if the transformers connected in open Δ supply the full-load with normal heating?

[(a) primary = 30.3 A; secondary 303 A (b) primary = 30.3
$$\sqrt{3}$$
A; secondary = $303\sqrt{3}$ A (c) 33.33 kVA] (Elect. Machines-I, Gwalior Univ. Apr. 1977)

33.9. Scott Connection or T - T Connection

This is a connection by which 3-phase to 3-phase transformation is accomplished with the help of two transformers as shown in Fig. 33.13. Since it was first proposed by Charles F. Scott, it is frequently

referred to as Scott connection. This connection can also be used for 3-phase to 2-phase transformation as explained in Art. 33.10.

One of the transformers has centre taps both on the primary and secondary windings (Fig. 33.13) and is known as the *main* transformer. It forms the horizontal member of the connection (Fig. 33.14).

The other transformer has a 0.866 tap and is known as *teaser* transformer. One end of both the primary and secondary of the teaser transformer is joined to the centre taps on both primary and secondary of the main transformer respectively as shown in Fig. 33.14 (a). The other end A of the teaser primary and the two ends B and C of the main transformer primary are connected to the 3-phase supply.




Fig. 33.13

The voltage diagram is shown in Fig. 33.14 (a) where the 3-phase supply line voltage is assumed to be 100 V and a transformation ratio of unity. For understanding as to how 3-phase transformation results from this arrangement, it is desirable to think of the primary and secondary vector voltages as forming geometrical T_S' (from which this connection gets its name).




Fig. 33.14

In the primary voltage T of Fig. 33.14 (a), E_{DC} and E_{DB} are each 50 V and differ in phase by 180°, because both coils DB and DC are on the same magnetic circuit and are connected in opposition. Each side of the equilateral triangle represents 100 V. The voltage E_{DA} being the altitude of the equilateral triangle is equal to $(\sqrt{3}/2) \times 100 = 86.6 \, V$ and lags behind the voltage across the main by 90°. The same relation holds good in the secondary winding so that abc is a symmetrical 3-phase system.

With reference to the secondary voltage triangle of Fig. 33.14 (b), it should be noted that for a load of unity power factor, current I_{db} lags behind voltage E_{db} by 30° and I_{dc} leads E_{dc} by 30°. In other words, the teaser transformer and each half of the main transformer, all operate at different power factors.

Obviously, the full rating of the transformers is not being utilized. The teaser transformer operates at only 0.866 of its rated voltage and the main transformer coils operate at $\cos 30^{\circ} = 0.866$ power

factor, which is equivalent to the main transformer's coils working at 86.6 per cent of their kVA rating. Hence the capacity to rating ratio in a T–T. connection is 86.6% — the same as in V–V connection if two identical units are used, although heating in the two cases is not the same.

If, however, both the teaser primary and secondary windings are designed for 86.6 volts only, then they will be operating at full rating, hence the combined rating of the arrangement would become (86.6+86.6)/(100+86.6) = 0.928 of its total rating.* In other words, ratio of kVA utilized to that available would be 0.928 which makes this connection more economical than open- Δ with its ratio of 0.866.




Fig. 33.15

^{*} Alternatively, VA capacity available is = $V_L I_L + (0.866 \ V_L) I_L = 1.866 \ V_L I_L$ where I_L is the primary line current. Since 3-phase power is supplied, volt-amperes actually utilized = 1.732 $V_L I_L$. Hence, ratio of kVA actually utilized to those available is = 1.732 $V_L I_L / 1.866 \ V_L I_L = 0.928$.

Fig. 33.15 shows the secondary of the T-T connection with its different voltages based on a nominal voltage of 100 V. As seen, the neutral point n is one third way up from point d. If secondary voltage and current vector diagram is drawn for load power factor of unity, it will be found that

- 1. current in teaser transformer is in phase with the voltage.
- 2. in the main transformer, current leads the voltage by 30° across one half but lags the voltage by 30° across the other half as shown in Fig. 33.14 (b).

Hence, when a balanced load of p.f. = $\cos \phi$, is applied, the teaser current will lag or lead the voltage by Φ while in the two halves of the main transformer, the angle between current and voltage will be $(30^{\circ} - \Phi)$ and $(30^{\circ} + \Phi)$. The situation is similar to that existing in a V - V connection.

Example 33.17. Two T-connected transformers are used to supply a 440-V, 33-kVA balanced load from a balanced 3-phase supply of 3300 V. Calculate (a) voltage and current rating of each coil (b) kVA rating of the main and teaser transformer.

Solution. (a) Voltage across main primary is 3300 V whereas that across teaser primary is $= 0.866 \times 3300 = 2858 \text{ V}$.

The current is the same in the teaser and the main and equals the line current.

$$I_{IP} = 33,000/\sqrt{3} \times 3300 = 5.77 \,\text{A}$$
 —Fig. 33.16

The secondary main voltage equals the line voltage of 440 V whereas teaser secondary voltage $= 0.866 \times 440 = 381$ V.

The secondary line current, $I_{LS} = I_{LP}/k = 5.77/(440/3300) = 43.3$ A as shown in Fig. 33.16.





Fig. 33.16

(b) Main kVA =
$$3300 \times 5.77 \times 10^{-3} = 19 \text{ kVA}$$

Teaser kVA = $0.866 \times \text{main kVA} = 0.866 \times 19 = 16.4 \text{ kVA}$

33.10. Three-phase to Two-phase Conversion and *vice-versa*

This conversion is required to supply two-phase furnaces, to link two-phase circuit with 3-phase system and also to supply a 3-phase apparatus from a 2-phase supply source. For this purpose, Scott connection as shown in Fig. 33.17 is employed. This connection requires two transformers of different ratings although for interchangeability and provision of spares, both transformers may be identical but having suitable tappings.



If, in the secondaries of Fig. 33.14 (b), points c and d are connected as shown in Fig. 33.18 (b), then a 2-phase, 3-wire system is obtained. The voltage E_{dc} is 86.6 V but $E_{Cb} = 100$ V, hence the




Fig. 33.19

resulting 2-phase voltages will be unequal. However, as shown in Fig. 33.19 (a) if the 3-phase line is connected to point A_1 , such that DA_1 represents 86.6% of the teaser primary turns (which are the same as that of main primary), then this will increase the volts/turn in the ratio of 100: 86.6, because now 86.6 volts are applied across 86.6 per cent of turns and not 100% turns. In other words, this will make volts/turn the same both in primary of the teaser and that of the main transformer. If the secondaries of both the transformers have the same number of turns, then secondary voltage will be equal in magnitude as shown, thus resulting in a symmetrical 2-phase, 3-wire system.

Consider the same connection drawn slightly differently as in Fig. 33.20. The primary of the main transformer having N_1 turns is connected between terminals CB of a 3-phase supply. If supply line voltage is V, then obviously $V_{AB} = V_{BC} = V_{CA} = V$ but voltage between A and D is $V \times \sqrt{3}/2$. As said




Fig. 33.20 Fig. 33.21

above, the number of turns between A and D should be also $(\sqrt{3}/2)$ N_1 for making volt/turn the same in both primaries. If so, then for secondaries having equal turns, the secondary terminal voltages will be equal in magnitude although in phase quadrature.

It is to be noted that point D is not the neutral point of the primary supply because its voltage with respect to any line is not $V/\sqrt{3}$. Let N be the neutral point. Its position can be determined as follows. Voltage of N with respect to A must be $V/\sqrt{3}$ and since D to A voltage is $V \times \sqrt{3}/2$, hence N will be $(\sqrt{3}V/2 - V/\sqrt{3}) = 0.288$ V or 0.29 V from D. Hence, N is above D by a number of turns equal to 29% of N_1 . Since 0.288 is one-third of 0.866, hence N divides the teaser winding AD in the ratio 2:1.

Let the teaser secondary supply a current I_{2T} at unity power factor. If we neglect the magnetizing current I_0 , then teaser primary current is $I_{1T} = I_{2T} \times$ transformation ratio.

 \therefore $I_{1T} = I_{2T} \times N_2/(\sqrt{3}N_1/2) = (2/\sqrt{3}) \times (N_2/N_1) \times I_{2T} = 1.15 (N_2/N_1) I_{2T} = 1.15 KI_{2T}$ where $K = N_2/N_1 =$ transformation ratio of *main* transformer. The current is in phase with star voltage of the primary supply (Fig. 33.21).

The total current I_{1M} in each half of the primary of the *main* transformer consists of two parts:

(i) One part is that which is necessary to balance the main secondary current I_{2M} . Its value is

$$= I_{2M} \times \frac{N_2}{N_1} = KI_{2M}$$

(ii) The second part is equal to one-half of




Fig. 33.22

the teaser primary current *i.e.* $\frac{1}{2}I_{1T}$. This is so because the main transformer primary forms a return path for the teaser primary current which divides itself into two halves at mid-point D in either direction. The value of each half is $=I_{1T}/2=1.15$ $KI_{2T}/2=0.58$ KI_{2T} .

Hence, the currents in the lines B and C are obtained vectorially as shown in Fig. 33.22. It should be noted that as the two halves of the teaser primary current flow in opposite directions from point D, they have no magnetic effect on the core and play no part at all in balancing the secondary ampere-turns of the main transformer.

The line currents thus have rectangular components of KI_{2M} and 0.58, KI_{2T} and, as shown in Fig. 33.22, are in phase with the primary star voltages V_{NB} and V_{NC} and are equal to the teaser primary current. Hence, the three-phase side is balanced when the two-phase load of unity power factor is balanced.




Fig. 33.23 (a) illustrates the condition corresponding to a balanced two-phase load at a lagging power factor of 0.866. The construction is the same as in Fig. 33.22. It will be seen that the 3-phase side is again balanced. But under these conditions, the main transformer rating is 15% greater than that of the teaser, because its voltage is 15% greater although its current is the same.

Hence, we conclude that if the load is balanced on one side, it would always be balanced on the other side.

The conditions corresponding to an unbalanced two-phase load having different currents and power factors are shown in Fig. 33.23 (*b*). The geometrical construction is similar to those explained in Fig. 33.22 and 33.23 (*a*).

Summarizing the above we have:

- 1. Teaser transformer primary has $\sqrt{3}/2$ times the turns of main primary. But volt/turn is the same. Their secondaries have the same turns which results in equal secondary terminal voltages.
- 2. If main primary has N_1 turns and main secondary has N_2 turns, then main transformation ratio is N_2/N_1 . However, the transformation ratio of teaser is

$$N_2/(\sqrt{3}N_1/2) = 1.15 N_2/N_1 = 1.15 K$$

- 3. If the load is balanced on one side, it is balanced on the other side as well.
- 4. Under balanced load conditions, main transformer rating is 15% greater than that of the teaser.
- 5. The currents in either of the two halves of main primary are the vector sum of KI_{2M} and 0.58 KI_{2T} (or $\frac{1}{2}I_{1T}$).

Example 33.18. Two transformers are required for a Scott connection operating from a 440-V, 3-phase supply for supplying two single-phase furnaces at 200 V on the two-phase side. If the total output is 150 kVA, calculate the secondary to primary turn ratio and the winding currents of each transformer.

Solution. Main Transformer

Primary volts = 440 V; secondary volts = 200 V : $\frac{N_2}{N_1} = \frac{200}{440} = \frac{1}{2.2}$

Secondary current = $150,000/2 \times 200 = 375 \text{ A}$ \therefore Primary current = $375 \times 1/_{2,2} = 197 \text{ A}$

Teaser Transformer

Primary volts = $(\sqrt{3}/2 \times 440) = 381 \text{ V}$: Secondary volts = 200 V

 $\frac{\text{secondary turns}}{\text{primary turns}} = \frac{200}{381} = \frac{1}{1.905} \text{ (also teaser ratio} = 1.15 \times 1/2.2 = 1/1.905)$

Example 33.19. Two single-phase furnaces working at 100 V are connected to 3300-V, 3-phase mains through Scott-connected transformers. Calculate the current in each line of the 3-phase mains when the power taken by each furnace is 400-kW at a power factor of 0.8 lagging. Neglect losses in the transformers. (Elect. Machines-III, South Gujarat Univ. 1988)

Solution. Here K = 100/3,300 = 1/33 (main transformer)

$$I_2 = \frac{400,000}{0.8 \times 100} = 5,000 \text{A} \text{ (Fig. 33.24); Here } I_{2T} = I_{2M} = I_2 = 5,000 \text{ A}$$

As the two-phase load is balanced, the 3-phase side is also balanced.

Primary phase currents are = $1.15 \text{ KI}_2 = 1.15 \times (1/33) \times 5,000 = 174.3 \text{ A}$

Since for a star-connection, phase current is equal to line current,

:. Line current = 174.3 A

Note. We have made use of the fact that since secondary load is balanced, primary load is also balanced. If necessary, I_{1M} can also be found.

 I_{1M} is the vector sum of (i) KI_{2M} and (ii) $\frac{1}{2}I_{1T}$ or 0.58 KI_{2T} .




Fig. 33.24

Now,
$$KI_{2M} = (1/33) \times 5,000 = 151 \text{ A} \text{ and } 0.58 \ KI_2 = \frac{1}{2} I_{1T} = 174.3/2 = 87.1 \text{ A}$$

$$\therefore I_{1M} = \sqrt{151^2 + 87.1^2} = 174.3 \text{ A}$$

Example 33.20. In a Scott-connection, calculate the values of line currents on the 3-phase side if the loads on the 2-phase side are 300 kW and 450 kW both at 100 V and 0.707 p.f. (lag) and the 3-phase line voltage is 3,300 V. The 300-kW load is on the leading phase on the 2-phase side. Neglect transformer losses. (Elect. Technology, Allahabad Univ. 1991)

Solution. Connections are shown in Fig. 33.25 (a) and phasor diagram in Fig. 33.25 (b).




Fig. 33.25

Here,
$$K = 100/3,300 = 1/33$$

Teaser secondary current is $I_{2T} = 450,000/100 \times 0.707 = 6360$ A
Teaser primary current is $I_{1T} = 1.15$ $KI_{2T} = 1.5 \times (1/33) \times 6360 = 221.8$ A

As shown in Fig. 33.25 (b), main primary current I_{1M} has two rectangular components.

(i) KI_{2M} where I_{2M} is the secondary current of the main transformer and

(ii) Half of the teaser primary current
$$\frac{1}{2}I_{1T} = \frac{1}{2} \times 1.15 \ KI_{2T} = 0.577 \ KI_{2T}$$

Now
$$KI_{2M} = \frac{1}{33} \times \frac{300,000}{100 \times 0.707} = 128.58 \text{ A}$$
; Also $\frac{1}{2}I_{1T} = \frac{1}{2} \times 221.8 = 110.9 \text{A}$

Main Primary current =
$$\sqrt{128.58^2 + 110.9^2} = 169.79$$
A

Hence, the 3-phase line currents are 221.8 A in one line and 169.79 A in each of the other two.

Example 33.21. Two electric furnaces are supplied with 1-phase current at 80 V from a 3-phase, 11,000 V system by means of two single-phase Scott-connected transformers with similar secondary windings. When the load on one furnace is 500 kW (teaser secondary) and on the other 800 kW (secondary of main transformer) what current will flow in each of the 3-phase lines (a) at unity power factor and (b) at 0.5 power factor? Neglect phase displacement in and efficiency of, the transformers. (Electrical Engineering, Madras Univ. 1987)

Solution. The connections are shown in Fig. 33.26 and the phasor diagrams for unity and 0.5 p.f. are shown in Fig. 33.27 (a) and (b) respectively.




Fig. 33.26

Fig. 33.27

Here,

$$K = 80/11,000 = 2/275$$

(a) Unity p.f.

With reference to Fig. 33.27 (a), we have $I_{2T} = 500,000/80 \times 1 = 6,250 \text{ A}$

Teaser primary current

$$I_{1T} = 1.15 \, KI_{2T} = 1.15 \times (2/275) \times 6,250 = 52.5 \, A$$

For the main transformer primary

(i)
$$KI_{2M} = \frac{2}{275} \times \frac{800,000}{80 \times 1} = 72.7 \text{ A} \text{ (ii) } \frac{1}{2} \times I_{1T} = 52.5/2 = 26.25 \text{ A}$$

Current in the primary of the main transformer is = $\sqrt{72.7^2 + 26.25^2}$ = 77.1 A

Hence, one 3-phase line carries 52.5 A whereas the other 2 carry 77.1 A each [Fig. 33.27 (a)].

(b) 0.5 p.f.

With reference to Fig. 33.27 (b) we have $I_{2T} = 500,000/80 \times 0.5 = 12,500 \text{ A}$

Teaser primary current $I_{1T} = 1.15 \times (2/275) \times 12,500 = 105 \text{ A}$

For the main transformer primary

(i)
$$KI_{2M} = \frac{2}{275} \times \frac{800,000}{80 \times 0.5} = 145.4 \text{ A} \text{ (ii) } \frac{1}{2}I_{1T} = 105/2 = 52.5 \text{ A}.$$

Current in the primary of the main transformer is = $\sqrt{145.4^2 + 52.5^2}$ = 154.2 A.

Hence, one 3-phase line carries 105 A and the other two carry 154.2 A each.

Note: Part (b) need not be worked out in full because at 0.5 p.f., each component current and hence the resultant are doubled. Hence, in the second case, answers can be found by multiplying by a factor of 2 the line currents found in (a).

Example 33.22. Two furnaces are supplied with 1-phase current at 50 V from a 3-phase, 4.6 kV system by means of two 1-phase, Scott-connected transformers with similar secondary windings. When the load on the main transformer is 350 kW and that on the other transformer is 200 kW at 0.8 p.f. lagging, what will be the current in each 3-phase line? Neglect phase displacement and losses in transformers. (Electrical Machinery-II, Bangalore Univ. 1991)

Solution. Connections and vector diagrams are shown in Fig. 33.28.

$$K = 50/4,600 = 1/92; I_{2T} = 200,000/50 \times 0.8 = 5,000 \text{ A}$$

 $I_{1T} = 1.15 KI_{2T} = 1.1 \times (1/92) \times 5,000 = 62.5 \text{ A}$




Fig. 33.28

As shown in Fig. 33.28 (b), main primary current I_{1M} has two rectangular components.

(i) KI_{2M} where $I_{2M} = 350,000/50 \times 0.8 = 8,750 \text{ A}$: $KI_{2M} = 8,750/92 = 95.1 \text{ A}$

(ii)
$$(1/2) I_{1T} = 62.5/2 = 31.3 \text{ A}$$
 :: $I_{1M} = \sqrt{95.1^2 + 31.3^2} = 100 \text{ A}$

:. Current in line $A = 62.5 \, \text{A}$; Current in line $B = 100 \, \text{A}$; Current in line $C = 100 \, \text{A}$.

Example 33.23. Two single-phase Scott-connected transformers supply a 3-phase four-wire distribution system with 231 volts between lines and the neutral. The h.v. windings are connected to a two-phase system with a phase voltage of 6,600 V. Determine the number of turns in each section of the h.v. and l.v. winding and the position of the neutral point if the induced voltage per turn is 8 volts.

Solution. As the volt/turn is 8 and the h.v. side voltage is 6,600 V, the h.v. side turns are =6,600/8 = 825 on both transformers.

Now, voltage across points B and C of main winding = line voltage = $231 \times \sqrt{3} = 400 \text{ V}$

No. of turns on the l.v. side of the main transformer = 400/8 = 50

No. of turns on the 1.v. side of teaser transformer = $\sqrt{(3/2)} \times \text{mains turns}$

$$=\sqrt{3}\times50/2=43$$
 (whole number)

The neutral point on the 3-phase side divides teaser turns in the ratio 1: 2.

 \therefore Number of turns between A and $N = (2/3) \times AD$ $=(2/3)\times43=29$




Fig. 33.29

Hence, neutral point is located on the 29th turn from A downwards (Fig. 33.29).

Example 33.24. A Scott-connected (2 to 3-phase) transformer links a 6,000 V, 2-phase system with a 440 V; 3-phase system. The frequency is 50 Hz, the gross core area is 300 cm², while the maximum flux density is to be about 1.2 Wb/m². Find the number of turns on each winding and the point to be tapped for the neutral wire on the 3-phase side. If the load is balanced on the one side of such a transformer, find whether it will also be balanced on the other side. (London Univ.)

Solution. Use the transformer voltage equation 1,

$$E = 4.44 fN \Phi_{y}$$
 volt

Gross core area = $300 \, \text{cm}^2$

Assuming net iron = 0.9 of gross area, and considering the h.v. side, we have

$$6000 = 4.44 \times 50 \times N_1 \times 1.2 (300 \times 0.9 \times 10^{-4})$$

$$N_1 = 834$$

Hence, h.v. sides of both transformers have 834 turns each.

Now K = 440/6000 = 11/150

:. Turns on the l.v. side of main transformer

$$N_2 = 834 \times 11/150 = 61$$

Turns on the *l.v.* side of teaser = $(\sqrt{3}/2) \times 61 = 53$

With reference to Fig. 33.30, number of turns in $AN = 53 \times 2/3 = 35$




Fig. 33.30

Example 33.25. A 2-phase, 4-wire, 250 V system is supplied to a plant which has a 3-phase motor load of 30 kVA. Two Scott-connected transformers supply the 250 V motors. Calculate (a) voltage (b) kVA rating of each transformer. Draw the wiring connection diagram.

Solution. (a) Both the main and the teaser have the same voltage rating as the supply voltage i.e. 250 V. The current in the main and the teaser coils is the same as the supply current and is

$$= \frac{Total \ kVA}{2 \times Line \ voltage} = \frac{30,000}{2 \times 250} = 60 \ A \arcsin \theta$$

On the three-phase side, current is the same in all coils and is equal to the load line current $= 30,000/\sqrt{3} \times 250 = 69.3 \text{ A}$

Load voltage on main secondary = line voltage = 250 V

Load voltage on teaser secondary = $0.866 \times 250 = 216.5 \text{ V}$

Hence, voltage rating of main transformer is 250/250 whereas that of teaser transformer is 250/216.5.

The current rating of main transformer is 60/69.3 and it is the same for the teaser transformer.

(b) The volt-amp rating of the teaser primary as well as secondary is the same i.e. $60 \times 250 \times 10^{-3}$ = $69.3 \times 216.5 \times 10^{-3} = 15 \text{ kVA}$

The main volt-ampere rating of secondary is = $250 \times 69.3 \times 10^{-3} = 17.3 \text{ kVA}$

Incidentally, if two identical transformers are used for providing inter-changeability, then both must be rated at 17.3 kVA. In that case, a total capacity of 34.6 kVA would be required to provide a 30 kVA load.

The wiring connections are shown in Fig. 33.31.




Fig. 33.31

Tutorial Problem No. 33.3

1. A Scott-connected transformer is fed from a 6,600-V, 3-phase network and supplies two single-phase furnaces at 100 V. Calculate the line currents on the 3-phase side when the furnaces take 400 kW and 700 kW respectively at 0.8 power factor lagging. (Elect. Machines II, Indore Univ. 1977)

[With 400 kW on teaser, line currents are 87. 2 A; 139 A; 139 A]

2. Two 220-V, 1-phase electrical furnaces take loads of 350 kW and 500 kW respectively at a power factor of 0.8 lagging. The main supply is at 11-kV, 3-phase, 50 Hz. Calculate current in the 3-phase lines which energise a Scott-connected transformer combination. (Elect. Machines, Madras Univ. 1978)

[With 350 kW on teaser line currents are: 45.7 A; 61.2 A; 61.2 A]

3. Two electric furnaces are supplied with 1-phase current at 80 V from 3-phase, 11,000-V supply mains by means of two Scott-connected transformers with similar secondary windings. Calculate the current flowing kW respectively in each of the 3-phase lines at U.P.P. when the loads on the two transformers are 550 kW of 800 kW.

[With 550 kW on teaser, line currents are : 57.5 A; 78.2; 78.2 A] (Electrical Machines-I, Madras University, 1977)

33.11. Parallel Operation of 3-phase Transformers

All the conditions which apply to the parallel operation of single-phase transformers also apply to the parallel running of 3-phase transformers but with the following additions:

- 1. The voltage ratio must refer to the terminal *voltage of primary and secondary*. It is obvious that this ratio may not be equal to the ratio of the number of turns per phase. For example, if V_1 , V_2 are the primary and secondary terminal voltages, then for Y/Δ connection, the turn ratio is $V_2/(V_1/\sqrt{3}) = \sqrt{3}V_2/V_1$.
- 2. The phase displacement between primary and secondary voltages must be the same for all transformers which are to be connected for parallel operation.
 - 3. The phase sequence must be the same.

All three transformers in the 3-phase transformer bank will be of the same construction either core
or shell.

Note. (i) In dealing with 3-phase transformers, calculations are made for one phase only. The value of equivalent impedance used is the equivalent impedance per phase referred to secondary.

- (ii) In case the impedances of primary and secondary windings are given separately, then primary impedance must be referred to secondary by multiplying it with (transformation ratio)².
- (iii) For Y/Δ or Δ/Y transformers, it should be remembered that the voltage ratios as given in the questions, refer to terminal voltages and are quite different from turn ratio.

Example 33.26. A load of 500 kVA at 0.8 power factor lagging is to be shared by two three-phase transformers A and B of equal ratings. If the equivalent delta impedances as referred to secondary are $(2 + j6) \Omega$ for A and $(2 + j5) \Omega$ for B, calculate the load supplied by each transformer.

Solution.
$$\mathbf{S_A} = \mathbf{S} \frac{\mathbf{Z_B}}{\mathbf{Z_A} + \mathbf{Z_B}} = \mathbf{S} \frac{1}{1 + (\mathbf{Z_A}/\mathbf{Z_B})}$$
Now
$$S = 500 (0.8 - j0.6) = (400 - j300)$$

$$\mathbf{Z_A}/\mathbf{Z_B} = (2 + j6)/(2 + j5) = 1.17 + j \cdot 0.07; \mathbf{Z_B}/\mathbf{Z_A} = (2 + j5)/(2 + j6) = 0.85 - j \cdot 0.05$$

$$\mathbf{S_A} = (400 - j300)/(2.17 + j0.07) = 180 - j \cdot 144.2 = 230.7 \angle -38.7^{\circ}$$

$$\cos \phi_A = 0.78 \text{ lagging}$$

$$\mathbf{S_B} = (400 - j \cdot 300)/(1.85 - j0.05) = 220.1 - j \cdot 156 = 270 \angle -40^{\circ}28' \therefore \cos \phi_B = \mathbf{0.76} \text{ lagging.}$$

Example 33.27. State (i) the essential and (ii) the desirable conditions to be satisfied so that two 3-phase transformers may operate successfully in parallel.

A 2,000-kVA transformer (A) is connected in parallel with a 4,000 kVA transformer (B) to supply a 3-phase load of 5,000 kVA at 0.8 p.f. lagging. Determine the kVA supplied by each transformer assuming equal no-load voltages. The percentage voltage drops in the windings at their rated loads are as follows:

Transformer A resistance 2%; reactance 8 %
Transformer B resistance 1.6 %; reactance 3 %

(Elect, Engineering-II, Bombay Univ. 1987)

Solution. On the basis of 4,000 kVA

%
$$\mathbf{Z}_{A} = (4,000/2,000) (2+j8) = (4+j16) = 16.5 \angle 76^{\circ}$$

% $\mathbf{Z}_{B} = (1.6+j3); \% \ Z_{A} + \% \ Z_{B} = (5.6+j16) = 19.8 \angle 73.6^{\circ}$
\$\mathbb{S} = 5,000 \angle -36.9^{\circ} = (4,000-j3,000)\$
Now
$$\mathbf{S}_{B} = \mathbf{S} \cdot \frac{\mathbf{Z}_{A}}{\mathbf{Z}_{A} + \mathbf{Z}_{B}} = 5,000 \ \angle -36.9^{\circ} \times \frac{16.5 \ \angle 76^{\circ}}{19.8 \ \angle 73.6^{\circ}} = 5,000 \ \angle -36.9^{\circ} \times 0.832 \ \angle 2.4^{\circ} = 4,160 \ \angle -34.5^{\circ} = (3,425-j2,355)$
$\mathbb{S}_{A} = \mathbb{S} - \mathbb{S}_{B} = (4,000-j3,000) - (3,425-j2355)$
$= (575-j645) = 864 \angle -48.3^{\circ}$
$\mathrm{cos}{\phi}_{B} = \mathrm{cos}{\partial} 34.5^{\circ} = 0.824 (\lag{lag}); \mathrm{cos}{\phi}_{A} = \mathrm{cos}{\partial} 48.3^{\circ}$$$

Example 33.28. A load of 1,400 kVA at 0.866 p.f. lagging is supplied by two 3-phase transformers of 1,000 kVA and 500 kVA capacity operating in parallel. The ratio of transformation is the same in both: 6,600/400 delta-star. If the equivalent secondary impedances are (0.001 + j 0.003) ohm and (0.0028 + j0.005) ohm per phase respectively, calculate the load and power factor of each transformer. (Elect. Engg-I, Nagpur Univ. 1993)